

A person wearing a red work jacket with a grey reflective stripe and the brand name 'Tungaloy' on the chest is seated at a desk. They are looking at technical drawings spread out on the desk. A metal part is visible on the desk. The text 'User's Guide' is overlaid in white on the image.

User's Guide

USER'S GUIDE

Parts for Tools

L002

Technical Reference

L028







User's Guide - Parts for Tools

Screws

Shape	Designation	Dimension (mm)					T / f	Torque (N·m)			
		a	øb	c	d	e					
	CSTA-NO2	#2-56UNC	4	6	4	82°	T8	1.3			
	CSTA-NO2S			5	3						
	CSTA-NO2L			8	6						
	CSTA-NO3	#3-48UNC	4.3	7	4	80°	T9	2.3			
	CSTA-NO5	#5-40UNC	5	8	5						
	CSTA-1.6	M1.6x0.35	2.5	3.1	0.9						
	CSTA-4	M4x0.7	7	10	7.7	82°	T15	3.5			
	CSTA-5	M5x0.8	7.2	15	11						
	CSTA-5S			12	8						
	CSTA-5SS			9.5	5.5						
	CSTA-5ST25			12	8						
	CSPA-5IP15			15	11						
	CSPA-5SIP15			12	8						
	CSPA-5IP20	15	11	20IP	5						
	CSPA-5SIP20	12	8								
(Steel)											
<p>CSP-2L033 type shown</p> <p>CSTB-4SD type shown</p> <p>CSTC-4L type shown</p>	CSP-2L033	M2x0.4	2.6	3.3	1.9		88°	6IP	0.7		
	CSTB-2			3.3	1.4						
	CSTB-2L			2.7	5.2	3.3					
	CSTB-2L040	4	2.1	M2.2x0.45	3.5	6.1	3.5	60°	T7	1	
	CSTB-2.2	3.8	2.2								
	CSTB-2.2L038	4.6	2								
	CSTB-2.2S	3.1	6.1	3.7	M2.5x0.45	3.5	6	3.4	T8	1.3	
	CSTB-2.2R	3.25	4.6	2.6							
	CSTB-2.5	8	5.4	T8			1.3				
	CSTB-2.5L046	3.5	5.5		2.6						
	CSTB-2.5L080	4.8	2.2	M3x0.5	4.1	8	4.5	60°	T9	2.3	
	CSTB-2.5B	4.2	0.7								
	CSTB-2.5S	5	2								
	CSTB-3	4.1	6	2.5	M3.5x0.6	5.3	12.5	4	T15	3.5	
	CSTB-3L042	5.2	6.5	3.1							
	CSTB-3L050	5.5	8.4	4.3							
	CSTB-3L081	4.2	8.1	4.7	M4x0.7	5.5	11	7.5	T15	3.5	
	CSTB-3S	4.1	6	2.5							
	CSTB-3.5ST	5.3	12.5	4							
	CSTB-3.5H	5.2	6.5	3.1	M4x0.5	6.4	14.7	4	T8	1.3	
	CSTB-3.5	5.5	8.4	4.3							
	CSTB-3.5T	6.5	10	5.5							
	CSTB-3.5TS	4.7	8.4	4.9	M4x0.7	5.5	9.5	5.5	T15	3.5	
	CSTB-3.5D	5.5	11	7.5							
	CSTB-3.5L110	4.8	11.5	7							
	CSTB-3.5L115	4.8	11.5	6.5	M5x0.8	7	12	7.5	T20	5	
	CSTB-3.5L115-S	5.3	12.5	8.4							
	CSTB-3.5L	11.4	7.4								
	CSTB-4	5.5	6	2	M4x0.5	5.42	5.5	2	44°	T8/T10	1.3/2.5
	CSTB-4L060	8.48	3.48								
	CSTB-4L085	5.7	9	5.5							
	CSTB-4L090	5.5	11.5	6.5	M4x0.7	5.42	10	5.95	T8/T10	1.3/2.5	
	CSTB-4L115-S	5.5	8								
	CSTB-4S	6.4	14.7	4							
	CSTB-4ST	M4x0.5	5.5	8	M4x0.7	7	14.7	8.7	T15	3.5	
	CSTB-4SD	M4x0.7	6.5	9			4.5				
	CSTB-4M	M4x0.5	7	14.7			8.7				
	CSTB-4F	M4x0.5	7	14.7	8.7	M4x0.7	7	12	7.5	T20	5
	CSTB-4TS	M4x0.7	6.5	9	4.5						
	CSTB-5	M5x0.8	7	12	7.5						
	CSTB-5S	M5x0.8	7.2	9.5	5	60°	7IP	1.1			
	CSTB-5L105			10.5	6.1						
	CSTB-5L120			12	6.5						
	CSTB-5L159	7.2	15.9	11.2	M4x0.5	5.42	5.5	2	T8/T10	1.3/2.5	
	CSTB-5L163-S	6.9	16.3	11.3							
CSTC-4L055DR	M4x0.5	5.42	5.5	2							
CSTC-4L055DL	M4x0.5	5.42	5.5	2	M4x0.7	5.42	10	5.95	T8/T10	1.3/2.5	
CSTC-4L100DR	M4x0.7	5.42	10	5.95							
CSTC-4L100DL	M4x0.7	5.42	10	5.95							
CSPB-2L043	M2x0.4	2.7	4.3	2.5	M2x0.4	2.6	3.4	1.6	60°	6IP	0.7
CSPB-2H	6	3.9									
CSPB-2.2	M2.2x0.45	3	4	2							
CSPB-2.2SH	M2.5x0.45	3.5	6	3.5	60°	8IP	1.3				
CSPB-2.5			4.2	1.7							
CSPB-2.5S			3.3	5.2				3.3			
CSPB-2.5SH	M3.5x0.6	5.2	9	5.6	60°	15IP	3.5				
CSPB-3.5			9	5.6							
(Steel)											











User's Guide - Parts for Tools

Screws

Shape	Designation	Dimension (mm)					T / f	Torque (N·m)	
		a	øb	c	d	e			
	CSPB-3.5S	M3.5x0.6	5.2	6.5	3.1	60°	15IP	3.5	
	CSPB-4	M4x0.7	5.5	11.6	7.4				
	CSPB-4S			8.2	4				
	CSPB-5	M5x0.8	7	12	7.5	44°	20IP	5	
	VX040024A	M4	5.45	9	6				
	VX040028A	M4	5.2	9.7	4.7	60°	T15	4.5	
	SR14-500/L5.1	M4	5.5	5.1	2.3		T15	3.5	
	SR14-500-L7.0	M4	5.5	7	4.2		T15	3.5	
	SR14-562	M3.5	4.8	8.75	5.55		T10	3.2	
	SR14-562/S	M3.5	4.8	6.5	3.3		T10	3.2	
	SR14-591	M5x0.8	6.6	13.5	7.6		T20	5	
	SR34-508	M2.2x0.45	3.15	4.6	2.67		T7	0.9	
	SR34-514	M2.5x0.45	3.3	5.2	3.2		T7	0.9	
	SR76-943	M6	9.6	20	10		90°	T20	5
	SR76-961	M5	6.6	13.5	7.35		61°	T15	3.5
	SR76-963	M5	8.6	20	9.6	91°	T15	3.5	
	SR-10503833-S	M2.5X0.45	3.25	3.8	1.75	60°	T7	-	
	SR 114-018-L3.40	M2.5	3.6	3.35	2	56°	T6	0.7	
	SM40-143-H0	M4X0.7	5.6	14.3	8.4	61°	T15	3.5	
	TS25F080A	M2.25X0.35	3.7	6.9	2.1	60°	T8	1.3	
	TS25064I	M2.5X0.45	3.5	6.4	3.8	50°	T8	1.3	
	TS30F100A	M3X0.35	4.6	8.3	2.2	60°	T10	2.5	
	TS30085I/HG	M3X0.5	4.3	8.5	5.6		T9	2.3	
	TS30C72I	M3X0.5	4.2	7.2	4.5		T9	2.3	
	TS40085I/HG	M4	5.7	8.5	4.5		T15	3.5	
	TS35085I/HG	M3X0.6	5.3	8.5	4.3		T15	3.5	
	TS40093I/HG	M4	5.7	9.3	4.3		T15	3.5	
	TS40B100I	M4	6	10	6		R3.0	T15	3.5
	TS40F120A	M4X0.5	6	10.6	3		60°	T15	3.5
	TS45120I	M4.5	6.9	12	7.5		R3.5	T20	5
	TS50115I	M5	7	11.35	6.4		T20	5	
	TS50230D3	M5X0.8	7	23	13.5	T20	-		
	TS50250D35	M5X0.8	7.5	25	14.5	T25	-		
TS50F160A	M5X0.5	7	13.9	3.5	T20	5			
TS60265D4	M6X1.0	8	26.5	15.5	T25	-			
TS60285D42	M6X1.0	8.5	28.5	16.7	T25	-			
TS60320D5	M6X1.0	9.5	31	18	T25	-			
TS60F200A	M6X0.75	8.2	16.7	4.5	T20	7			
TS70F250A	M7X0.75	10	21	5.6	T25	7			
TS80340D6	M8X1.25	10	34	20	T25	-			
TS80F300A	M8X1.0	12	25	7.3	T30	10			
(Steel)	CSPD-1.8S	M1.8x0.35	2.4	3.3	1.4	60°	6IP	0.7	
	CSTD-3T	M3x0.5	4.3	7	4.5		T10	2.5	
CSPD-3	4.2			10IP	2.5				
(Steel)	CSTB-4.5L110P	M4.5X0.75	6.6	11.7	7	T15	3.5		
	SRM5X0.8IP20X+ACROLYTE	M5X0.8	9.2	15	9.8	20IP	7.5		
(Steel)	CSTC-2	M2x0.4	3.1	5.1	-	T6	0.7		
	CSTR-4L100	M4x0.7	5.7	10	5.5	T15	3.5		
(Steel)	SR16-212-01397	M5x0.8	6.4	12.5	6.8	T20/T10	2.5		
	SR16-212-01397L								
(Steel)	CST-3.5	M3.5X0.6	6	4.8	-	T9	2.3		
	CST-3.5S			3.5	-				
	CST-5	M5x0.8	10	18	13	T25	5		
	CST-5S			12	7				
	CSTF-2L055-S			M2x0.4	2.7			5.5	3.8






User's Guide - Parts for Tools

Screws

Shape	Designation	Dimension (mm)						Torque (N·m)			
		a	øb	c	d	T / f	e				
 <p>Cross recessed head screw</p> <p>(Steel)</p>	SM2.5×0.45×8	M2.5x0.45	5	8	-	-	90°	-			
	SM2.5×0.5×8	M2.5x0.5	5	8	-	-	90°	-			
	SM3×0.5×6	M3x0.5	6	6	-	-	90°	-			
	SM3×0.5×8			8	-	-	90°	-			
	SM3×0.5×10			10	-	-	90°	-			
 <p>(Steel)</p>	MSP-5	M5x0.8	6.1	7.9	4.9	2		1.5			
	MSP-6.3	M6.3x1	7.7	12.7	9.9	2.5		3			
 <p>(Steel)</p>	BHM3-8	M3x0.5	5.5	10	8	2		1.5			
	BHM4-8	M4x0.7	7	10.6		10	2.5		2.2		
	BHM4-10			12.6							
	BHM5-14	M5x0.8	9	17.6	14	3		3			
	BHM6-20-A	M6x1.0	10.5	24	20	4		5			
	BHM8-25U	M8	14	29.3	25	5		8.5			
	BHM8-30U			34.3	30						
 <p>(Steel)</p>	CSHM-3-8	M3	6	8	-	2	90°	1.5			
 <p>(Steel)</p>	CSHB-4-A	M4	5.5	11	-	T15	60°	2			
	CSHB-6	M6	8.5	19	-	4	60°	5			
	CSHB-6-A	M6	8.5	19	5						
 <p>(Steel)</p>	RT-1	M6	10	22.5	14	4		5			
	RT-2	M8	13	31	20	5		8.5			
 <p>(Steel)</p>	ASM6	M6	10	18	12	3		-			
	AJM5F	M5x0.5	9	13	8	2		-			
	AJM5	M5x0.8	9	13	8	2		-			
 <p>(Steel)</p>	ASM34S	M3	4.8	8	5	2		-			
	ASM34L			11	8		-				
	ASM54	M5x0.8	9	14	9	3		-			
 <p>(Steel)</p>	CHHM3.5-10	M3.5x0.6	6	13.5	10	3		3			
	CHHM4-10	M4x0.7	7	14							
	CHHM5-14	M5x0.8	8.5	19	14	4		5			
	CHHM5-18			23	18						
	CHHM6-15	M6	10	21	15	5		8.5			
	CHHM6-20			-	20						
	CHHM6-25			31	25						
 <p>Hex. socket head screw (JISB1176)</p> <p>(Steel)</p>	CM3X0.5X6	M3x0.5	5.5	9	6	2.5		2.2			
	CM3X0.5X10			13	10						
	CM4X0.7X10			M4x0.7	7		14		12	3	
	CM4X0.7X12	16									
	CM4X0.7X14	18	14								
	CM4X0.7X15	19	15								
	CM4X0.7X20	24	20								
	CM4X0.7X20-M0-A	6	24	20							
	CM5X0.8X8	M5x0.8	8.5	13	8	4		5			
	CM5X0.8X10-A			15	10						
	CM5X0.8X12			17	12						
	CM5X0.8X12-A			17	12						
	CM5X0.8X14			18	14						
	CM5X0.8X16			21	16						
	CM5X0.8X16-A			21	16						
	CM5X0.8X18			23	18						
	CM5X0.8X20-A			25	20						
	CM5X0.8X25-A			30	25						
	CM5X15			M5			20		15		

User's Guide - Parts for Tools

Screws









Shape	Designation	Dimension (mm)							Torque (N·m)			
		a	øb	c	d	e	f	g				
 <p>Hex. socket head screw (JISB1176)</p>	CM6X1X16-A	M6x1.0	10	22	16		5		8.5			
	CM6X1X20-A			26	20							
	CM6X1X25-A			31	25							
	CM6X1.0X40-A			46	40							
	CM6X10				16	10						
	CM6X15				21	15						
	CM6X16				22	16						
	CM6X20				26	20						
	CM6X25				31	25						
	CM6X30-S	M6x1.0			35.7	28						
	CM8X1.25X20-A	M8x1.25	13	28	20		6		25			
	CM8X1.25X25-A			33	25							
	CM8X30H			36	30					5		
	CM10X30	M10x1.5	16	30	20		8		40			
	CM10X30H		16	38	30		6		40			
	CM12X30H	M12x1.75	18	40			8		70			
	CM16X40H	M16x2	24	54	40		10		100			
	CM16x75	M16	24	75	51		14		100			
	CM16x120	M16	24	120	96		14		100			
	CM16x140	M16	24	140	116		14		100			
	CM20x80	M20	30	80	50		17		150			
	CM20x120	M20	30	120	90		17		150			
	CM20x150	M20	30	150	120		17		150			
	CAP-CM12x1.75x50	M12	18	50	38		10		70			
	CAP-CM16X2.0X55	M16	24	55	39		14		40			
CAP-CM20X2.5X50	M20	30	50	30		17		100				
C0.375X1.125H	3/8-24UNF	14.27	38.11	28.58		5.55		35				
C0.500X1.375H	1/2-20UNF	19.05	47.63	34.93		7.94		70				
SD06-A3	M10x1.5	16	70	60		8		40				
SRM6X16DIN912-12.9	M6x1	10	22	14.1		5						
VC00TEDI12040F	M12	26	51	40		8		60				
VC00TEDI20040F	M20	49	50	34.5		12		150				
VC00TANG16040F	M16	46	46.5	33		10		60				
SD08-98	M12x1.75	18	77	65		10		70				
LHM12x1.75x30-C	M12	18	36.9	30		8		70				
VC004762I10035F	M10	16	45	34.5		8		60				
FCS3	M3x0.5	5.5	16	12		2.5						
FCS6	M6x1	10	26	20		5						
 <p>(Steel) FSHM*-H</p>	FSHM8-30	M8x1.25	11	30	27		5		25			
	FSHM8-30H								25			
	FSHM10-40	M10	14	40	36.5			6		40		
	FSHM10-40H									40		
 <p>(Steel)</p>	SHCM4-10	M4x0.7	6	14	10		3		3			
	SHCM4-12			16	12							
	SHCM4-16			20	16							
 <p>(Steel)</p>	CTS-M6	M6x1	10	25	16.4		4		5			
 <p>(Steel)</p>	RSFTS-050M	M10	25	52	42.5		6					

Grade
Insert
Ext. Toolholder
Int. Toolholder
Threading
Grooving
Miniature tool
Milling cutter
Endmill
Drilling tool
Tooling System
User's Guide
Index

A
B
C
D
E
F
G
H
I
J
K
L
M

User's Guide - Parts for Tools

Screws

Shape	Designation	Dimension (mm)						Torque (N·m)
		a	øb	c	d	e	T / f	
 (Steel)	MCS520-2.5	M5×0.8		20	7	6	2.5	3
	MCS620-3	M6×1				7	3	6
	MCS625-3		25	10	8			
	MCS825-4	M8×1			12.5	6.5	4	8
	MCS828-4			28.5	12	10.5		
	NDS-8A		30	11.5	11.5			
	NDS-8S	M8×1.25	20	8	8			
	RSRGR5M40	M4		9	3.67	4.17	T8	
	SR PS 118-0273	M10		40	16.5	15	5	40
 (Steel)	DS-5T	M5×0.8		12	5	5	T10	3.5
	DS-6T	M6		15	6	6	T15	3.5
	DS-6P	M6×1		21	7	7	15IP	6
	FDS-8ST	M8×1		20	8	8	T27	10
	FDS-8ST-18			18	8	6		
 (Steel)	DS-6	M6×1		15	6	6	3	6
	DS-8	M8×1.25		16	7	7	4	8
	DS-8S			13	5.5	5.5		
	DS-10	M10×1.5		26		12	5	8
	FDS-6Z	M6×0.75		20.5	10	5.5	3	6
	FDS-8	M8×1		26		10	4	8
	FDS-8S			20	8	8		
	FDS-8SS			18.5	8	6.5		
 (Steel)	SS100	1/4-20UNC			19.05			
	S-412	10-32UNF			19.05			
 (Steel)	SHM8x1.25x35-C	M8	13	43	23	8	6	25
	SHM10x1.5x30-C	M10	16	40	17	10	8	40
	SHM16x2x35-C	M16	24	51	18	16	14	100
	SHM20x2.5x40-C	M20	30	58	20	18	17	150
 Hex. socket screw (Flat end)(JISB1177)	SSHM2.5-3	M2.5		3			1.5	1
	SSHM3-3	M3		3				
	SSHM3-4			4				
	SSHM3-6			6				
	SSHM4-4	M4		4			2	1.5
	SSHM4-5			5				
	SSHM4-6			6				
	SSHM4-8			8				
	SSHM4-10			10				
	SSHM4-14			14				
	SSHM5-6	M5		6			2.5	2
	SSHM5-10			10				
	SSHM5-16			16				
	SSHM6-12	M6		12			3	3
	SSHM6-16			16				
	SSHM6-18			18				
	SSHM6-20			20				
	SSHM8-8	M8		8			4	5
SSHM8-10			10					
SSHM8-12			12					
SSHM8-14			14					
SSHM8-16			16					
SSHM8-18			18					
 Hex. socket screw (Cylindrical end)(JISB1177)	M5×7	M5	3.5	7	1.25	-	2.5	2
	M5×8			8	-			
	M5×10			10	-			
	M6×30	M6	4	30	1.5	-	3	3
 (Steel)	JDS-3525	M3.5x0.35	M2.5 x0.45	7.5	3	2.5	2	1
	JDS-5040	M5x0.5	M4 x0.7	10	4	4	2.5	1

User's Guide - Parts for Tools

Grade

Insert

Toolholder

Ext. Toolholder

Int. Toolholder

Threading

Grooving

Miniature tool

Milling cutter

Endmill

Drilling tool

Tooling System

User's Guide

Index












Screws

Shape	Designation	Dimension (mm)						Torque (N·m)
		a	b	c	d	e	T / f	
<p>LCS2 has a hex. socket in threaded end only.</p>	LCS2	M5	5	14	6.5		2	1.5
	LCS3	M6	6	17				2.5
	LCS3B			15				
	LCS4	M8	8		21	9.6	3	3
	LCS4K				6.5			
	LCS4CA					17.5		
	LCS5				25			
	LCS5CA				20.5			
	LCS6	M10	9.8	27.2	9.9		4	5
	LCS8	M12	11.8	36	12.8		5	8
LCS8C	M10	9.8	30.2	13.3		4	5	
(Steel)	LCS22	M5	M5	10	4.7		2	1.5
	LCS22A	M6	M6	10.7				
	LCS23A	M5	M5	13.1	5.1		2.5	2
	LCS33	M5	M5	12	6.2		2	1.5
	LCS43	M6	M6	13.5	7.3		2.5	2
(Steel)	DTS5-3.5	M5	6.3	8.65	M3.5		3.5	4
	DTS5-3.5SS			6.8				
	DTS5-3.5S			7				
	DTS6-4	M6	7.7	10.2	M4		4	5
	DTS6-4.5	M6	7.5	10	M4.5		4.5	5
(Steel)	DLCS33	M5	9	31.5	10		3	3
	DLCS43	M6	12	34	9.5		4	5
	DLCS54	M8x1	14	41	11		5	8
	DLCS64	M10x1	16	50	15		5	8
(Steel)	ACS-5W	M5	8	20	8.5		T15	4
	ACS-6W	M6	10	26	12.1		T20	6.4
(Steel)	ACS3	M5x0.8	7.5	25.6	12-15		3	4
	ACS4	M6x1	9	27.7	14-17		4	7
(Steel)	WCS3	M6	9.5	22.5	8		3	3
(Steel)	PT1/4GN		13.175	10	-		6	9.5
	1/8-28		9.728	7	-		5	8
(Steel)	LS-8	M8	6	33	20		4	5
(Steel)	CCS4-A							
	BH5-10-A							
	BH4-10-A							
	BH-40050-A							
(Steel)	TMBA-M10	M10x1.5	27	30	21		8	40
	TMBA-M12	M12x1.75		33	36	26	10	70
	TMBA-M12H	M12x1.75	34.5					
	TMBA-M16	M16x2	40	50	40		14	100
	TMBA-M16H	M16x2						
	TMBA-M20	M20x2.5	50	56	42		17	150
	TMBA-M20H	M20x2.5						
	TMBA-M24	M24x3	65	69	55		19	150
	TMBA-M24H	M24x3						
	TMBA-0.500H	1/2-20UNF	33	33.9	25.4		7.94	70
	TMBA-0.750H	3/4-16UNF	50	58.28	47.28		12.7	150
	SR-10400611	M4X0.5		6.6	3	1	2	

User's Guide - Parts for Tools

Shims

Shape	Designation	Dimension (mm)			
		a	b	c	ød
	AST322	9.3	13.2	3.2	4.4
	AST422	12.5	18		
	MST-322	9.1	12.9	3.24	5.8
	MST-432	12.5	17.9	4.8	7.3
	MST-533	15.6	22.2		9.7
	MST-644	18.8	26.6	6.4	11.3
	LST317	9.3	13.2	2.7	5
	LST42	12.5	18	3.2	6.7
	LST53	15.7	22.3	4.8	7.7
	LST42K	10.9	15.6	3.2	6.7
	LST317CA	9.3	13.2	2.7	5
	LST42CA	12.5	18	3.2	6.7
 <p>Right hand (R) shown</p>	ELST42	11.5	16.5	3.2	6.5
	ELST317	8.5	12	2.7	4.9
	ELST317BR				
	ELST317BL				
	PAT-32	8.2	11.7	3.2	3.5
	*PAT-53	13.4	19.8	4.8	5
	NAT-32	9.5	13.4	3.2	3.5
	NAT-42E	12.4	17.8		3.1
 <p>Right hand (R) shown</p>	LST317BR	9.3	13.2	2.7	5
	LST317BL				
	SST32	8.5	11.9	3.2	5.4













Note: * marked shims are made of steel.

User's Guide - Parts for Tools

Grade

A

Shims

Shape	Designation	Dimension (mm)				
		a	b	c	ød	e
	ASS422	12.5		3.2	4.4	
	CS44-A			4.7		
	ASS533	15.7		4.8	5.5	
	ASS634	18.9				
	ELSS32	8.5		3.2	4.9	
	LSS33	9.3		4.3	5	
	ELSS42	11.7		3.2	6.5	
	LSS42	12.5			6.7	
	ELSS53	14.7		4.8	8	
	LSS53	15.7			7.7	
	ELSS63	17.9			9.7	
	LSS63	18.9				
	ELSS84	24.2		6.4	12.9	
	LSS84	25.2			13.1	
	NAS-42	12.7		3.2	3.5	
	NAS-04	31.5		6.4	9.1	
	MSS-432	12.5		4.8	7.3	
	MSS-442			6.4		
	SSS32	8.5		3.2	5.4	
	LSS42BR	12.5		3.2	6.7	
	LSS42BL					
	PAS-32	8.2		3.2	3	
	PAS-42	11.4			3.5	
	*PAS-63	17		4.8	5	
	LSS42CA	12.5		3.2	6.7	8°
	LSS53CA	15.7		4.8	7.7	10°
	FSSA1102	11.6		2	5.5	13°
	FSSP1102	11		2	5.5	17°
	ASC322	9.3		3.2	4.4	
	ASC422	12.5				
	ASC533	15.7		4.8	5.5	
	ASC634	18.9				
	CC44-A	12.5				

Note: * marked shims are made of steel.

Insert

B

Ext. Toolholder

C

Int. Toolholder

D

Threading

E

Grooving

F

Miniature tool

G

Milling cutter

H

Endmill

I

Drilling tool

J

Tooling System

K

User's Guide













L

Index

M

User's Guide - Parts for Tools

Shims

Shape	Designation	Dimension (mm)				
		a	b	c	ød	e
 (D30)	MSC-432	12.5		4.8	7.3	
	MSC-442			6.4		
	MSC-533	15.6		4.8	9.7	
	MSC-543			6.4		
	MSC-634	18.8		6.4	11.3	
 (D30)	ELSC32	8.5		3.2	6.2	
	LSC42	12.5			6.5	
	ELSC42	11.7		4.8	7.7	
	LSC53	15.7			8.1	
	ELSC53	14.7			9.7	
	ELSC63	17.9				
	LSC63	18.9				
	LSC317	9.3		2.7	5	
 (D30)	SSC32	8.5		3.2	5.4	
	SSC4T3	11.4		4	6.6	
 (D30)	SSC4T3-P	11.4		4	6.6	5°
	SSC54-P	13.4				5°
 (D30)	LSC42CA	12.5		3.2	6.7	8°
	LSC53CA	15.7		4.8	7.7	10°
 (D30)	LSC42BR	12.5		3.2	6.7	
	LSC42BL					
 (D30)	ZSA1102	10.5	11	2	5.475	11°
	ZSA1502	15.6	12.4		6	11°
 (D30)	ASD322	9.3		3.2	4.4	
	ASD423	12.5		3.2	4.4	
	ASD432	12.5		4.8	4.4	
	CD44-A	12.5		4.7		
 (D30)	ELSD32	8.5		3.2	4.9	
	ELSD42	11.7			6.5	
	LSD42	12.5			6.7	
	LSD42A					
	LSD43					
LSD43A			4.8			
 (D30)	MSD-322	9.3		3.2	5.8	
	MSD-432	12.5		4.8	7.3	
	MSD-442			6.4		
 (D30)	SSD32	8.5		3.2	5.4	
 (D30)	ELSD317BR	8.5		2.7	4.9	
	ELSD317BL					
	LSD42BR	12.5		3.2	6.7	
	LSD42BL					

User's Guide - Parts for Tools

Grade

Insert

Ext. Toolholder

Int. Toolholder

Threading

Grooving

Miniature tool

Milling cutter

Endmill
















Drilling tool

Tooling System

User's Guide


Index

Shims

Shape	Designation	Dimension (mm)			
		ϕa	b	c	ϕd
 <p>Left hand (L) shown (D30)</p>	LSZ42BR	12.5		3.2	6.7
	LSZ42BL				
 <p>(D30)</p>	ASV322	9.3		3.2	4.4
	CV34-A	9.3		4.7	
 <p>(D30)</p>	MSV-322	9.26		3.2	5.8
	SSV32	8.4			5.4
	SSV42	11			6.3
 <p>Left hand (L) shown (D30)</p>	CSK54R	9.4	14.8	4.8	3.5
	CSK54L				
 <p>(D30)</p>	ASW322	9.33	11.5	3.2	4.4
	ASW422	12.5	15.2		
 <p>LSW312BR type shown (D30)</p>	LSW312	9.33	11.5	2.7	5
	LSW42	12.5	15.5	3.2	6.7
 <p>LSW312BR type shown (D30)</p>	LSW312BR	9.33	11.5	2.7	5
	LSW312BL				
 <p>(D30)</p>	MSW-432	12.8	15.8	4.8	7.3
	MSW-533	16	19.7		9.7
	MSW-633	19.2	23.7		11.3
 <p>Right hand (R) shown (D30)</p>	MSW-432BR	12.8	15.8	4.8	7.3
	MSW-432BL				
 <p>(D30)</p>	CH44-A		12.5	4.7	
 <p>(D30)</p>	ASR420	12.5		3.2	4.4
 <p>(D30)</p>	LSR32	8.9		3.2	5
	LSR32C	8.4			
	LSR42	12.1			
	LSR42C	9.9		4.8	6.7
	LSR53C	14			5
	LSR63C	17.2			6.7
LSR84C	21.9		6.4	9.7	
 <p>(D30)</p>	MSR-43	12.5		4.8	7.3
	MSR-44			6.4	
 <p>(D30)</p>	SSR32	8.7		3.18	5.2
 <p>Right hand (R) shown (D30)</p>	G16EL/IR	9.5	-	3.2	4
	G16ER/IL			3.2	
	G16EL/IR-DT			3.97	5.4
	G16ER/IL-DT			3.97	

User's Guide - Parts for Tools

Shims

Shape	Designation	Dimension (mm)			
		ϕa	l	Lead angle	
	AE16-4DT	9.5	5.4	4°	
	AE16-3DT		5.4	3°	
	AE16-2DT		5.4	2°	
	A16-1DT		5.4	1°	
	AE16-0DT		5.4	0°	
	AE16-99DT		5.4	-1°	
	AE16-98DT		5.4	-2°	
	AE16-4		4	4°	
	AE16-3		4	3°	
	AE16-2		4	2°	
	A16-1		4.3	1°	
	AE16-0		4	0°	
	AE16-99		4	-1°	
	AE16-98		4	-2°	
	AN16-4DT		9.5	5.4	4°
	AN16-3DT			5.4	3°
	AN16-2DT			5.4	2°
	AN16-0DT			5.4	0°
	AN16-99DT			5.4	-1°
	AN16-98DT			5.4	-2°
	AN16-4			4	4°
	AN16-3	4		3°	
	AN16-2	4		2°	
	AN16-0	4		0°	
	AN16-99	4		-1°	
	AN16-98	4		-2°	
	GXE16-98	9.5		4	-2°
	GXE16-98DT			5.4	-2°
	GXE16-99			4	-1°
	GXE16-99DT		5.4	-1°	
	GXE16-0		4	0°	
	GXE16-0DT		5.4	0°	
	GXE16-1		4.3	1°	
	GX16-1DT		5.4	1°	
	GXE16-2		4	2°	
	GXE16-2DT		5.4	2°	
	GXE16-3		4	3°	
	GXE16-3DT		5.4	3°	
	GXE16-4		4	4°	
	GXE16-4DT		5.4	4°	
	GXE22-98DT		12.7	6.6	-2°
	GXE22-99DT	-1°			
GXE22-0DT	0°				
GX22-1DT	1°				
GXE22-2DT	2°				
GXE22-3DT	3°				
GXE22-4DT	4°				
GXN16-98	9.5	4			-2°
GXN16-98DT		5.4	-2°		
GXN16-99		4	-1°		
GXN16-99DT		5.4	-1°		
GXN16-0		4	0°		
GXN16-0DT		5.4	0°		
GXN16-1		4.3	1°		
GXN16-2		4	2°		
GXN16-2DT		5.4	2°		
GXN16-3		4	3°		
GXN16-3DT		5.4	3°		
GXN16-4		4	4°		
GXN16-4DT		5.4	4°		
GXN22-98DT		12.7	6.6	-2°	
GXN22-99DT				-1°	
GXN22-0DT	0°				
GXN22-2DT	2°				
GXN22-3DT	3°				
GXN22-4DT	4°				

(D30)

User's Guide - Parts for Tools

Grade

Insert

Ext. Toolholder

Int. Toolholder

Threading

Grooving

Miniature tool

Milling cutter

Endmill


Drilling tool





Tooling System





User's Guide

Index

Shims











Shape	Designation	Dimension (mm)				Lead angle
		a	øa	ℓ	c	
	NXE22-98	12.7	12.7	4		-2°
	NXE22-99					-1°
	NXE22-0					0°
	NXE22-1					1°
	NXE22-2	15.9	15.9	4.5		2°
	NXE22-3					3°
	NXE22-4					4°
	NXE27-98					-2°
	NXE27-99	-1°				
	NXE27-0	0°				
	NXE27-1	1°				
	NXE27-2	15.9	15.9	4.5		2°
	NXE27-3					3°
	NXE27-4					4°
	NXN22-98					-2°
	NXN22-99	-1°				
	NXN22-0	0°				
	NXN22-1	1°				
	NXN22-2	12.7	12.7	4.5		2°
	NXN22-3					3°
NXN22-4	4°					
NXN27-98	-2°					
NXN27-99	-1°					
NXN27-0	0°					
NXN27-1	1°					
NXN27-2	15.9	15.9	4.5		2°	
NXN27-3					3°	
NXN27-4					4°	
(D30) TSL12R					12	
TSL12L	12		4.7	4.5	4.5°	
TSL16R	15.9		6.4	5	5°	
TSL16L	15.9		6.4	5	5°	
TSL24R	23.8		9.4	7.1	7°	
TSL24L	23.8		9.4	7.1	7°	
TSL12RI	10.7		4.7	4.5	4.5°	
TSL12LI	10.7		4.7	4.5	4.5°	
TSL16RI	18.8		6.4	5	5°	
(D30) TSL16LI	18.8		6.4	5	5°	

Shape	Designation
	SL-1R
	SL-1L
(Steel) Right hand (R) shown	
	SL-2R
	SL-2L
(Steel) Right hand (R) shown	
	SL-3R
	SL-3L
(Steel) Right hand (R) shown	
	SL-6R
	SL-6L
(Steel) Right hand (R) shown	

Shape	Designation
	SL-7R
	SL-7L
(Steel) Right hand (R) shown	
	SL-8R
	SL-8L
(Steel) Right hand (R) shown	
	SGSR151
	SGSL151
(D30) Right hand (R) shown	
	STN62R
	STN62L
(D30) Right hand (R) shown	

User's Guide - Parts for Tools

Clamps

Shape	Designation	Dimension (mm)					
		a	b	c	d	e	ℓ
 (Steel)	MCL-5M	14.7	11	7.8	4	M5	10.8
	MCL-6	18.6	11.5	9.5		M6	13.8
	MCL-8S	19.1	13.5	10.9	5	M8	13.6
	MCL-8M	22.5			17		
	MCL-8L	25.5	14.5	4	20		
 (Steel)	MCPM-6	14.7	11.2	7.9	4	M5	10.8
	MCPM-9	19.1	16.8	10.9	5	M8×1	13.6
	MCPM-12	22.5					17
	MCPM-20	18.6	9.5	9.5	4	M6	13.8
	MCPM-21		12.2				
	MCPM-22	21.5	13.2	10.9	5	M8×1	16.7
	MCPM-30	25.5	16.8				20
 (Steel)	DCPM-33	16	9.3	10.5	2.4		8.5
	DCPM-43	21.2	11.5	13.5	3		13.2
	DCPM-54	25.8	15.25	14	3.5		
	DCPM-64	28.4	15.5	16	4		
 (Steel)	ACP3S	22.8	9.5	10			15
	ACP3S-E	21.7	9.5	10			13.9
	ACP4S	25.7	12	13			17.7
	ACP5S	30.1	12.9	15	-	-	20.7
	ACP6S	33.4	12.8	16.5	-	-	24
	ACP3	17.9	10	10	6.5	6.3	
 (Steel)	ACP4	25.9	13.9	12	7	10.8	
 (Steel)	CTC-3R	29	8.8	16	2.2	8	
	CTC-3L						
	CTC-4R			17	3.2		
	CTC-4L						
	CTC-5R			18	4.2		
	CTC-5L						
 (Steel)	CP81A	28	10.5	12	3.5	8	
	CP81B						
 (Steel)	TC-3	19	12.5	8.3	-	-	-
	TC-4	21.6		8			
 (Steel)	TF-72	22	11.3				
	TF-73	22	11.3				
	TF-184	22	11.3				
	TF-185	22	11.3				
 (Steel)	CCR2	34.7	14.9	10.7	1.2	10.5	
	CCL2						
	CCR3				2.2		
	CCL3						
	CCR4				2.8		
	CCL4						
	CCR5				3.2		
	CCL5						
	CCR6				3.9		
	CCL6						
	CCR8				4.9		
CCL8							

User's Guide - Parts for Tools

Grade

A

Clamps

Insert

B

Ext. Toolholder

C

Int. Toolholder

D

Threading

E

Grooving

F

Miniature tool

G

Milling cutter

H

Endmill

I

Drilling tool

J

Tooling System



K







User's Guide






L

Index

M





Shape	Designation	Dimension (mm)				
		a	b	c	d	e
 <p>Right hand (R) shown</p>	CFG-3SR	22	11	23.1	2	6
	CFG-3SL					
	CFG-4SR					
	CFG-4SL					
	CFG-4DR	32			3	16
	CFG-4DL					
	CFG-5SR					
	CFG-5SL	22		4	6	
	CFG-5DR					
	CFG-5DL					
	CFG-6SR	23		5	7	
	CFG-6SL					
	CFG-6DR					
	CFG-6DL	33		17		
	CFG-8SR				28	27.1
CFG-8SL						
CFG-8DR						
CFG-8DL	38	18				
(Steel)						
	CCP4-A	29.1		14		
(Steel)						



Shape	Designation
 <p>M8 Left-hand thread</p>	NF-84A
(Steel)	
 <p>M6 Left-hand thread</p>	CP536
(Steel)	
	CP91
(Steel)	
	CP900
(Steel)	
	CP910
(Steel)	
	JCP-1
(Steel)	



Shape	Designation
	JCP-2
(Steel)	
	JCP-3 JCP-3N
(Steel)	
	CQ-1
(Steel)	
 <p>Right hand (R) shown</p>	CPK5R CPK5L
(Steel)	
 <p>Right hand (R) shown</p>	C11R-5 C11L-5
(Steel)	

User's Guide - Parts for Tools

Clamp Sets

Shape	Designation	Dimension (mm)						
		a	b	c	d	e	ℓ	T / f
 (Steel)	CSG-5S	M5×0.8	13.5	13.8	7	1.8	8.5	2.5
	CSG-5		15.5					
	CSG-6S		M6×1	18	16.3	8.5	2.5	10
	CSG-6	21.5						
	CSG-6L	21						
	CSG-8S	M8×1	23.5	20.5	11	3.5	12.5	4
	CSG-8							
 (Steel)	CSW-00	M4×0.7	11.5	12	8	2	7.5	2.5
	CSW-1	M5×0.8	16.5	16.5	9.5	4	10	3
	CSW-0	M4×0.7	11.5	13.8	8.5	2.5	8	2.5
	CSW-2	M6×1	20	20.5	11	6	13	4
	CSW-40	M4×0.7	12	13.2	8	2	7.5	2.5
	CSW-50	M5×0.8	15	16.9	10		9.5	3
	 (Steel)	CSP16	M5×0.8	15.5	14.4	6.9	3.2	9.1
CSP22		M6×1	20	18.1	8.9	4.2	11.5	T20
CSP27		M8×1.25	23.5	24.4	11.9	3.9	15.6	4
 (Steel)	CSY-15	M4×0.7	11.6	11.5	7	3	6	15IP
	CSY-20	M5×0.8	12	18	9.5	4	11	20IP

Shape	Designation
 (Steel)	CSG-5T
 (Steel)	CSX20

Shape	Designation
 (Steel)	CSW-0T
 (Steel)	CSL-4

User's Guide - Parts for Tools

Grade

Insert

Ext. Toolholder

Int. Toolholder

Threading

Grooving

Miniature tool

Milling cutter

Endmill








Drilling tool

Tooling System

User's Guide




Index




Levers




Shape	Designation	Dimension (mm)			
		a	b	c	d
 (Steel)	LCL3	10	12	3.7	3.6
	LCL4	14.6	14	4.7	4.7
	LCL5	17.1	17	6	6
	LCL6	20.5	21	7.5	7.5
	LCL8	25.4	25.4	8.6	8.6
 (Steel)	LCL3C	10.8	11.8	3.4	3
	LCL4C	13	13.4	3.7	3.4
	LCL5C	18.6	17.7	4.7	4.5
	LCL6C	20.5	19	6	5.7
	LCL8C	24.2	23.5	7.5	6.2
 (Steel)	LCL22N	7.5	6.5	2.6	2.06
	LCL32N	10	7.8	3.2	3.2
	LCL33NL	11.5	9.5	3.1	3.6
	LCL33N	10	9.4	3.2	3.2
	LCL43N	13.4	10	4.7	4.7
 (Steel)	LCL23	7.8	8.5	2.6	2.1
	LCL33	10.1	12.1	3.6	3.7
	LCL33L	12	11.5	3.1	3.6
	LCL43S	13.5	13.2	4.7	4.7
	LCL43M				
	LCL44	16.1	14.6	4.7	4.7
	LCL54	16.5	17.2	6.1	6
 (Steel)	DLCL43	15.55	14	5	4.7
	DLCL54	19.1	19.1	6.1	6
	DLCL64	21.5	21	7.5	7.5
 (Steel)	SLLV-1		7.75	3.4	2.43
	SLLV-2		7.75	3.4	2.75
 (Steel)	FCL4	5	7.78	3.81	
	FCL8	10	14.3	5.39	

User's Guide - Parts for Tools

Pins









Shape	Designation	Dimension (mm)					
		ϕa	b	ϕc	ϕd	e	f
 (Steel)	MLP32L	3.9	8.8	M5×0.8	5.6	3.5	2
	MLP33	3.7					
	MLP34L	3.7	13.1	M6.3×1	7.8	5.5	2.5
	MLP46	5	17.2				
	MLP46L		18.6	M8×1	10.3	6.9	3
	MLP58	6.2	21.9				
	MLP68	7.8	24.1	M10×1	11.9	9.1	4
	MLP68L						
 (Steel)	MLP44	5	13.2	M6.3×1	7.1	5.5	2.5
	MLP33L	3.7	10.4	M5×0.8	5.6	5.1	2
 (Steel)	SW99	8	47.5				

Shape	Designation
 (Steel)	SP-8
 (Steel)	SP-6
 (Steel)	BP-3

Shape	Designation
 (Steel)	BP-360
 (Steel)	BP-490
 (Steel)	SL-PI-2

User's Guide - Parts for Tools

Chipbreaker Pieces

Shape	Designation	Dimension (mm)			
		a	b	c	
 <p>(TX30)</p>	CBT-2S	8.8	7.6	2.5	
	CBT-2M	7.4	6.6		
	CBT-3S	13.3	12.1		
	CBT-3M	12.3	11.1		
	CBT-3L	11.3	10.1		
	CBT-4S	18.8	16.9		
	CBT-4M	17.8	15.9		
	CBT-4L	16.8	14.4		
	NCT-2S	14.2	11.8		
	NCT-2M	13	10.8		
	NCT-2L	11.9	9.8		
 <p>(TX30)</p>	CBS-3S	9.5	8.3	2.5	
	CBS-3M		7.3		
	CBS-4S	12.7	11.6		
	CBS-4SN				
	CBS-4M		10.6		
	CBS-4L		9.1		
	NCS-3S		11.2		
	NCS-3M		10.2		
	NCS-3L		8.7		
 <p>Right hand (R) shown (TX30)</p>	B11 R-5	24	13	5	
	B11 L-5				
 <p>(TX30)</p>	CBS-4SN	11.5	11.5	2.5	
	CBS-4MN	10.5	10.5		
	CBS-4LN	9	9		
	NCS-3SN	11.2	11.2		
	NCS-3MN	10.2	10.2		
	NCS-3LN	8.7	8.7		
 <p>(TX30)</p>	CBC-4SN	11.5	11.5	2.5	
	CBC-4MN	10.5	10.5		
	CBC-4LN	9.5	9.5		
 <p>Right hand (R) shown (TX30)</p>	CBD-4SR	12.7	11.5	2.5	
	CBD-4MR		10.5		
	CBD-4ML		9.5		
	CBD-4LR				
 <p>(TX30)</p>	CBD-4SN	11.5	11.5	2.5	
	CBD-4MN	10.5	10.5		
 <p>(TX30)</p>	CBR-4SN	12.7	11.9	2.5	
	CBR-4MN		10.9		

Grade

Insert

Ext. Toolholder

Int. Toolholder

Threading

Grooving

Miniature tool

Milling cutter

Endmill

Drilling tool

Tooling System








Index

User's Guide



User's Guide - Parts for Tools

Springs (Springs for Shims)



Shape	Designation	Dimension (mm)					
		a	b	c	d		
 (Steel)	SP-2.5	12	2.7				
 (Steel)	SP-16-L14	13.6	2.85				
 (Steel)	LSP3	5.5	3	5.9			
	LSP3L	7					
	LSP4		6	4	7.6		
	LSP4S						
	LSP5	8.5	4.5	8.8			
	LSP6	11	5.9	10.9			
	LSP6C	8.5	4.8	9.3			
	LSP8	12	10	15.4			
 (Steel)	PSP-2.5	10	2.7				
	PSP-4.0	16	4.2				
	PSP301	7.6	3				
 (Steel)	PSP-16	9.75	2.85				
 (Steel)	BP-0	3.6	13				
	BP-5-A						
	BP-7	7	11				
	BP-8.8	8.8	10				
	BP-9	8.3					
	BP-10	9.1					
	SP913	9	13				
 (Steel)	BSP-1	7.8	7.5	4.8	6		

User's Guide - Parts for Tools

Grade

A

Coolant Supply Attachment

Shape	Designation	Dimension (mm)				
		a	b	c	Thread	
 (Plastic)	EA-20	20	10	15		
	EA-25	25				
	EA-32	32	16			
 (Plastic)	CA-16	16	8		M6	
	CA-20	20	8.5		M6	
	CA-25	25	11.5		R1/8	
	CA-32	32	11.5		R1/8	
	CA-40	40	11.5		R1/8	

Insert

B


Int. Toolholder

C

Ext. Toolholder

D

Pistons

Shape	Designation	Dimension (mm)			
		a	øb		
 (Steel)	DPIS33	12.6	9		
	DPIS43	11.8	10		
	DPIS44	13.4	10		
	DPIS54	16	13		
	DPIS64		15		


Int. Toolholder

E

Threading

F


Nuts

Shape	Designation
	SRW11


Grooving

G

Coolant Pipe & Nozzle

Shape	Designation
	PNZ5

Coolant Nozzle

Shape	Designation
	CNZ125
	SATZ-M8X1-M3
	SATZ-M10X1-M5
	EZ104
	EZ83


Miniature tool

H

Milling cutter

I

Coolant unit


Shape	Designation	Dimension (mm)	
		a	ℓ
	CU-CW-CHP	20.8	29.7
	CU-D-CHP	20.8	29.6
	CU-V-CHP	20.8	30

Endmill

J

Drilling tool


K

Shape	Designation	Dimension (mm)	
		a	ℓ
	S-CU-CHP	7	16.2

Tooling System

L

O-ring for TungTurn-Jet

Shape	Designation	Dimension (mm)			
		a	øb		
 (Rubber)	OR6.4X0.9N	8.2	0.9		
	OR14X2.5NN	19	2.5		


User's Guide

M


Index

User's Guide - Parts for Tools






Coolant screw for TungTurn-Jet

Shape	Designation	Dimension (mm)			
		a	c		T / f
 (Steel)	SRM4X4 TL360	M4	4		2

Mounting screw for TungTurn-Jet

Shape	Designation	Dimension (mm)				
		a	øb	c	d	T / f
 (Steel)	SRM3	M3X0.5	4.2	7	4.9	T8

Sizing Plates

Shape	Designation	Dimension (mm)					
		a	b	c	d		
 (Steel)	S0816A	55	15.5	0.8			
	S1016A			1			
	S0816B	50	15.5	0.8			
	S1016B			1			
	S0816C	45	15.5	0.8			
	S1016C			1			
	S0820A	61	19.5	0.8			
	S1020A			1			
	S0820B	54.5	19.5	0.8			
	S1020B			1			
	SM-00	18	8	1			
 (Steel)	SW04	25.5	5.8	0.25			
				0.5			
	SW05	37	8.3	0.25			
	SW06	36	10.8	0.5			
 (Steel)	SW08	35.5	12.3	2			
	S0810	40	11	0.8			
S1010	1						
 Attached with fix screw and wrench. (Steel)	PSTR08	24	11	1.5			
	PSTL08						
	PSTR10	42	16.5	2			
	PSTL10						
	PSTR12	47	19	2			
	PSTL12						
 (Steel)	AP0801	26	9.5	0.5	3		
	AP0802			1			
	AP0803			1.5			
	AP0804			2			
	AP0805			2.5			
	AP1101	30	11.5	0.5	5		
	AP1102			1			
	AP1103			1.5			
	AP1104			2			
	AP1105			2.5			
	AP1106			3			

SW04 is composed of three plates and SW05 to SW08 are composed of four plates.

Note on fixing screws: PSTR/L08 is attached with CSSM2-4 and other types are attached with CSHM3-8.

User's Guide - Parts for Tools

Grade

Insert

Ext. Toolholder

Int. Toolholder

Threading

Grooving

Miniature tool

Milling cutter

Endmill

Drilling tool

Tooling System

User's Guide

Index



Washers










Shape	Designation	Dimension (mm)					
		øa	øb				
	VA4	7.6	4.1				
	VA5	9.2	5.1				
	VA6	10.5	6.1				
	CPW5						
	CDW6						

Wrenches and Drivers

Shape	Designation	Dimension (mm)						
		a	b	c	d	f	T	
	CRW23	9.7	78.5	55.0				
	CRW33	9.3						
	T-6F	2	35	14.5	15		T6	
	T-7F			19	19		T7	
	T-8F	2.5	40	23.5	20		T8	
	T-9F	3					T9	
	T-15F	3.5	45	28	21		T15	
	T-20F	4					T20	
	IP-6F	2	35	14.8	14.9		6IP	
	SET T-15/5	3.5	45	28	21		T15	
	T-20TORX	3.9	49	30	22		T20	
	T-6L		48	16			T6	
	T-8L							T8
	T-9L							T9
	T-15L		59	22			T15	
	T-25TORX		66	23.3			T25	
	KEYV-T20		60	22			T20	
	KEYV-T25		65	23			T25	
	KEYV-T30L		190	37			T30	
	KEYV-T40L		208	43			T40	
	KEYV-T50L		232	48			T50	
	P-2F	4	44	20	12.5	2		
	P-2.5F	5	45	25	20	2.5		
	HW2.0/5RED	3	38	15	15	2		
	P-2.5T		42		15	2.5		
	T-1008/5	6.5	85	28	25	-	T10/T8	
	T-2010/5					-	T10/T20	





User's Guide - Parts for Tools

Wrenches, Drivers and Lubricant

Shape	Designation	Dimension (mm)					
		a	b	c	d	f	T
	1/4HEX					6.35	
	5/32HEX					3.97	
	1/8HEX					3.18	
	3/32HEX					2.38	
	P-2					2	
	P-2.5					2.5	
	P-3					3	
	P-3.5					3.5	
	P-4					4	
	P-4.5					4.5	
	P-5					5	
P-6					6		
	TP-3A		70		45.5	3	
	TP-4					4	
	TP-5		85		53	5	
	T-27T	5	85		42		T27
	T-15T						T15
	T-20T	4	100		100		T20
	IP-20T						20IP
 <p>Handle shape somewhat varies depending on the type number from the above figure.</p>	T-6D	2.5		70			T6
	T-7D	2	45				T7
	T-8D	2.6	61	67.5			T8
	T-9D	3	65	80			T9
	T-10D	3.3	70	90			T10
	T-15D	3.65	71				T15
	T-20D	4.6	90	100			T20
	T-25D	4.4	87	86			T25
	IP-6DB		45	70			6IP
	IP-7D	2.5	45	75			7IP
	IP-8D	3	55	80			8IP
	IP-10D	3.3	71	89			10IP
	IP-15D	4	80	100			15IP
	IP-20D	4	90	100			20IP
		KS-21	21	195			
KS-24		24	215				
KS-27		27	235				
KS-32		32	275				
KS-36		36	305				
M-1000							
	BT15S	3.9	50	90		6	T15
	BT15M	3.9	50	118		6	T15
	BT20S	4.6	50	90		6	T20
	BT20M	4.6	50	118		6	T20
	BLD IP15/S7	3.9	50	90		6	15IP
	BLD IP15/M7	3.9	50	118		6	15IP
	BLD IP20/S7	4.6	50	90		6	20IP
	BLD IP20/M7	4.6	50	118		6	20IP
	BLD T10/S7	3.9	57	75		6	T10
	BLD T10/S7-A	3.9	57	75		6	T10
	H-TB		100		37	6	
	H-TBS		75		37	6	
	H-TB2W		95		31.4	6	
	AJC08		11		17	4.1	

User's Guide - Parts for Tools

Wrenches and Drivers

Shape	Designation	Dimension (mm)					
		a	b	c	d	f	T
	ECW-456EF	87	15	4	11.5		
	ECW-456I	80.5	22	4	10.5		
	KEYV-S05	4	5.5	100			
	KEYV-S06	5.4	8	125			
	KEYV-S08	6.6	10	150			
	KEYV-S10	7.7	13	175			
	KEYV-S12	9.4	16	250			
	KEYV-W20						
	KEYV-177	29	110				
	KEYV-217	29	110				
	KGDT-100	32	108.5				
	KGDT-110	32	108.5				
	KGDT-120	32	108.5				
	KGDT-130	32	108.5				
	KGDT-140	32	108.5				
	KGDT-150	32	108.5				

Grade

Insert

Ext. Toolholder

Int. Toolholder

Threading

Grooving

Miniature tool

Milling cutter

Endmill

Drilling tool

Tooling System

User's Guide

Index



User's Guide - Parts for Tools

Locators

Designation	Applicable Tool
LD150R	TXD15125R ~ TXD15315R
LD440R/L	TMD44 TGD4400R/L-A TFD44
LD442R/L	EGD4400R
LD540R/L	TMD54
LE302R	ESE3050R (RS**) ~ 3063R (RS**)
LE303R/L	TSE3003R/LIA ~ 3006R/LIA
LE402AR	ESE4050RA ESE4063RA
LE403R/L	TSE4003R/LIA TSE4004R/LIA ESE4003RIA-S32
LE405R/L	TSE4005R/LIA ~ 4012R/LIA
LE413R/L	THE40
LE444R/L	TME4403R/LI ~ 4405R/LI TME4403R/LB ~ 4405R/LB EME4405R ~ 4404RI
LE446R/L	TME4406R/LI ~ 4412R/LI TME4406R/LB ~ 4412R/LB
LE540R/L	TME54
LF440R/L	THF44
LF540R/L	THF54
LF602R	ERF6050R ~ ERF6063R
LF602R/L	TRF6003R/LI ~ TRF6006R/LI TRF6008R/LI ~ TRF6012R/LI
LMS56R/L	MS08R/L ~ MS12R/L
LN423R/L	TGN42
LN645R/L	TPN64
LP403R/L	TSP4003R/LIA ~ TSP4004R/LIA TFP4004R/LIA
LP405R/L	TSP4005R/LIA ~ TSP4012R/LIA TFP4005R/LIA ~ TFP4012R/LIA
LP413R/L	TGP41 TGP42
LP514R/L	TGP51
LPP16R	TPP16
LR602R/L	ERD6050RA ~ ERD6063RA
LR603R/L	TRD6003R/L TRD6004R/L ~ TRD6008R/L
LV525R/L	VSN 1
LV530R/L	VSN 2
LV556R/L	VSN60
LW400R	EFP4063R
LW400R/L	TFD44 TFP4000 SFP4000
LW402R	EFP4050R

Insert locking wedges

Designation	Applicable Tool
FDS-8SST	EDPD09063R EDPD09063RB
FDS-8ST-18	EDP09080R EDPD09080RB DPD09100R~DPD09160R DPD09100RB~DPD09160RB
FW-242R/L	ø63
FW-243R/L	ø80~100
FW-245R/L	ø125 ~
FW304R/L-D	DAD15 DPD15 EDPD15 QPP15
WF150R	TXD15125R ~ TXD15315R
WF310R/L	TGP4100BA TGP4103R/LIA
WF330N	TSE4003R/LIA TSE4004R/LIA ESE4003RIA-S32 TSP4003R/LIA ~ TSP4004R/LIA TFP4004R/LIA
WF330R/L	TSE3003R/LIA ~ 3006R/LIA
WF444R/L	TME4403R/LI ~ 4405R/LI TME4403R/LB ~ 4405R/LB EME4405R ~ 4404RI TME4406R/LI ~ 4412R/LI TME4406R/LB ~ 4412R/LB
WF500R	TSE4005R/LIA ~ 4012R/LIA TSP4005R/LIA ~ TSP4012R/LIA TFP4005R/LIA ~ TFP4012R/LIA
WF500R/L	TMD54 TGP51 THF54
WF50R/L	TME54
WF602R	ERF6050R ~ ERF6063R
WF603R/L	TRF6003R/LI ~ TRF600R/LI
WF608R/L	TRF6008R/LI ~ TRF6012R/LI
WF875N	TPYD06 EPYD06
WN645R/L	TPN64
WP193TR/L	EGD4400R
WP440R/L	TMD44 TGD4400R/L-A TFD44 TGP4100IA ~ TGP4112R/LIA TGP42 THF44 THE40
WR602R/LW	ERD6050RA ~ ERD6063RA
WR603R/L	TRD6003R/L TRD6004R/L ~ TRD6008R/L
WT402R	ESE4050RA ESE4063RA
WT402R/L	EME4450RB ~ 4404RB

User's Guide - Parts for Tools

Locator adjusting wedges

Designation	Applicable Tool
FW-305	TFD44 TFP40 SFP4000 EFP4063
FW325R/L-D	DAD15 QPP15 DPD15 EDPD15
RSFTC1008	TPYP12...
RSFTC1009	EPYP12M032C25.0R05
RSFTC1011	EPYP12M025C25.0R03

Fine adjusting screws

Designation	Applicable Tool
AJM5	DPD09 EDPD09
ASM34L	DPD24

Cover

Designation	Applicable Tool
RSFTS6063M	TPYP12M063B22.0R10
RSFTS6080	TPYP12*080B**R12
RSFTS6100	TPYP12*100B**R16
RSFTS6125	TPYP12*125B**R20

Grade

Insert

Ext. Toolholder

Int. Toolholder

Threading

Grooving

Miniature tool

Milling cutter

Endmill

Drilling tool

Tooling System



User's Guide

Index


User's Guide - Technical Reference

Turning Tools

Name of tools parts




Relating angles between tool and workpiece



- a_p ... Depth of cut (Distance between work surface and machined surface)
- a_e ... Length of cutting edge engaging in cutting.
- k ... Cutting edge angle (Angle to be made by cutting edge and work surface)
- f ... Feed per revolution
- h ... Thickness to be cut per revolution
- Machined surface ... Workpiece surface after having machined.
- Work surface ... Workpiece surface to be cut.

Effect of side cutting edge angle



Honing

TAC indexable inserts of steel cutting grades are honed. Honing specifications are shown in the following table.

Edge condition	Shape
Sharp edge	
Round honing	
Chamfered honing	

Effects of tool geometry on cutting phenomena

Phenomena	Flank wear	Crater wear	Edge strength	Cutting force	Surface finish	Chattering	Cutting edge temperature	Chip shape and flow
Increasing Cutting edge inclination	-	Decrease	Lower	Radial force decrease	-	Less tendency	Lower	Effect on flow direction
Side rake angle	-	Decrease	Lower	Decrease	-	-	Lower	Effect on shape
Relief angle	Decrease	-	Lower	Decrease	-	Likely to occur	Lower	-
End cutting edge angle	Decrease	-	Lower	Radial force decrease	Roughen	Less tendency	Lower	-
Side cutting edge angle	Decrease	Decrease	Increase	Radial force decrease	-	Likely to occur	Increase	Decrease thickness
Nose radius	Decrease to some level		Increase	Increase	Improve	Likely to occur	Increase	Effect on flow direction
Honing width	Increase	-	Increase	Increase	-	Likely to occur	Increase	-

User's Guide - Technical Reference

Turning Tools

Relations between cutting force and cutting conditions or cutting phenomena

Condition	Grey cast iron (HB130)	Stainless steel (HB145)	Carbon steel (HB230)
Cutting speed and cutting force $f = 0.2 \text{ mm/rev}$ $a_p = 2 \text{ mm}$ Side cutting edge angle 0° Corner radius RE 0.4			
Depth of cut and cutting force $V_c = 100 \text{ m/min}$ $f = 0.2 \text{ mm/rev}$ Side cutting edge angle 0° Corner radius RE 0.4			
Feed and cutting force $V_c = 100 \text{ m/min}$ $a_p = 2 \text{ mm}$ Side cutting edge angle 0° Corner radius RE 0.4			
Corner radius and cutting force $V_c = 100 \text{ m/min}$ $f = 0.2 \text{ mm/rev}$ $a_p = 1.2 \text{ mm}$ Side cutting edge angle 0°			
Side cutting edge angle and cutting force $V_c = 100 \text{ m/min}$ $f = 0.2 \text{ mm/rev}$ $a_p = 2 \text{ mm}$ Corner radius RE 0.4			
Side rake angle and cutting force $V_c = 100 \text{ m/min}$ $f = 0.2 \text{ mm/rev}$ $a_p = 2 \text{ mm}$ Side cutting edge angle 0° Corner radius RE 0.2			

* 9.8N = 1kgf




User's Guide - Technical Reference

Turning Tools

Calculation formulas for turning

●Cutting speed



When calculating cutting speed from number of revolutions:

$$V_c = \frac{\pi \times \phi D \times n}{1000}$$

V_c : Cutting speed (m/min)
 n : Number of revolution (min^{-1})
 ϕD : Diameter of workpiece (mm)
 $\pi \approx 3.14$


When calculating required number of revolutions from cutting speed:

$$n = \frac{V_c \times 1000}{\pi \times \phi D}$$

Example : Calculating the cutting speed when turning a $\phi 150$ mm-diameter workpiece at 250 min^{-1}

$$V_c = \frac{3.14 \times 150 \times 250}{1000} = 117 \text{ m/min}$$

●Cutting time on external and internal turning




$$T = \frac{\ell}{f \times n}$$

(min)

T : Cutting time (min)
 ℓ : Cutting length (mm)
 f : Feed (mm/rev)
 n : Number of revolution (min^{-1})

●Cutting time on face turning




$$T = \frac{\pi \times (\phi a^2 - \phi b^2)}{4000 \times v_c \times f}$$

(min)

V_c : Cutting speed (m/min)
 f : Feed (mm/rev)
 T : Cutting Time (min)

●Theoretical surface roughness



$$h = \frac{f^2}{8 \times r} \times 1000$$

(μm)

h : Surface roughness (μm)
 f : Feed (mm/rev)
 r : Nose radius (mm) (RE)
 () The notation in the brackets is the one used in the catalog (ISO compliant)

●Calculation of power consumption (kW)

$$P_c = \frac{F \times V_c}{60000}$$


(kW)

P_c : Power requirement (kW)
 F : Cutting force (N)
 V_c : Cutting speed (m/min)

Turning Tools

Cutting forces

- (1) Finding from the diagram based on experimental data.
- (2) In case determining by simplified equation:



$$F = k_c \times a_p \times f$$

(N)

F : Cutting force (N)
 k_c : Specific cutting force (N/mm²)
 [Refer to the Table below]
 a_p : Depth of cut (mm)
 f : Feed (mm/rev)

Example :
 Calculating the cutting force when cutting a high carbon steel (ISO C55) at $f = 0.2$ mm/rev and $a_p = 3$ mm.
 $F = 3430 \times 3 \times 0.2 = 2058$ N

Calculating power requirement

$$P_c = \frac{k_c \times a_p \times v_c \times f}{60 \times 1000}$$


(kW)

P_c : Net power requirement (kW)
 k_c : Specific cutting force (N/mm²)
 [Refer to the Table below]
 v_c : Cutting speed (m/min)
 a_p : Depth of cutting (mm)
 f : Feed (mm/rev)

Value of specific cutting force (k_c)

Workpiece material (JIS)	Tensile strength (MPa)	Hardness (HB)	Value of specific cutting force on feed k_c (N/mm ²)				
			0.04 (mm/rev)	0.1 (mm/rev)	0.2 (mm/rev)	0.4 (mm/rev)	1.0 (mm/rev)
SS400, S15C	390	100	3430	2840	2450	2080	1700
S35C, S40C	590	170	4220	3490	2940	2500	2080
S50C, SCr430	785	230	4900	4020	3430	2940	2400
SCM440, SNCM439	980	300	5390	4410	3780	3240	2650
SDK	1765 (56HRC)	56HRC	8390	6870	5880	5000	4120
FC200	(160HB)	160	2550	1960	1630	1340	1030
FCD600	(200HB)	200	3330	2550	2110	1750	1340
Aluminium alloy	(89HB)	89	1350	1130	950	810	670
Aluminium			1050	870	740	640	520
Magnesium alloy			390	390	390	390	390
Brass			1080	1080	1080	1080	1080

Bending stress and tool deflection



Bending stress

(1) Square shank

$$S = \frac{6 \times F \times L}{b \times h^2}$$

(MPa)

S : Bending stress in shank (MPa)
 F : Cutting force (N)
 L : Overhang length of tool (mm)
 b : Shank width (mm): (B)
 h : Shank height (mm): (H)
 d : Shank diameter (mm): (DCONMS)
 E : Modulus of elasticity of shank material (MPa)

(2) Round shank

$$S = \frac{32 \times F \times L}{\pi \times d^3}$$

(MPa)

Tool deflection (mm)

(1) Square shank

$$\delta = \frac{4 \times F \times L^3}{E \times b \times h^3}$$

(mm)

(2) Round shank

$$\delta = \frac{64 \times F \times L^3}{3 \times \pi \times E \times d^4}$$

(mm)

() The notation in the brackets is the one used in the catalog (ISO compliant)

(Ref.) Values of E

Material	MPa (N/mm ²)	{kgf/mm ² }
Steel	210,000	21,000
Cemented Carbide	560,000-620,000	56,000-62,000


User's Guide - Technical Reference

Turning Tools


Machining program compensation for wiper -SW / -FW insert

The nose radius on a wiper insert has a different configuration from that on standard ISO insert's. Machining program adjustments are, therefore, required to generate a correct offset for the wiper insert to machine the correct workpiece dimension. No compensation is needed, however, for the positive, CCMT-SW wiper insert.

Wiper effectiveness (surface finish quality improvement) by applications CNMG or WNMG insert



DNMG or TNMG insert



Program compensations by insert shapes and applications

Match your insert shape and application to find the proper compensation method.

Application	Insert shape	CNMG/WNMG -SW/FW	DNMG/TNMG -SW/FW	CCMT-SW
		Type L	Type J, G, F	Type L
Internal, External and Face turning		Proceed to Compensation ① (See Page L033)	Proceed to Compensation ④ (See Page L034)	No compensation needed
Including tapered surface		Proceed to Compensation ①, ② (See Page L033)	Proceed to Compensation ④, ⑤ (See Page L034 - L035)	↑
Including corner radius		Proceed to Compensation ①, ③ (See Page L033)	Proceed to Compensation ④ (See Page L034) Proceed to Compensation ⑥ (See Page L035)	↑
Including tapered surface and corner radius		Proceed to Compensation ①, ②, ③ (See Page L033)	Proceed to Compensation ④, ⑤, ⑥ (See Page L034 - L035)	↑



Turning Tools

Compensations for CNMG/WNMG -SW / -FW

Compensations ① Tool offsets (Compensations for X- and Z-axis)

Match the insert approach angle and the insert style to find the value and compensate the machining program for the insert radius.
*This compensation procedure will not be necessary if the insert is compensated with the built-in tool presetter after insert replacement.

CNMG/WNMG-SW/-FW (Type L)

Nose Radius	X-axis direction	Z-axis direction
R0.4	0.03	0.03
R0.8	0.05	0.05
R1.2	0.05	0.05

Compensations ② Program compensations for tapered surface (proceed after ①)

To machine tapered surfaces, compensate the nose radius position in the x-axis position to obtain the correct workpiece dimension.


Compensations for x-axis when using CNMG or WNMG-SW/-FW (Tool approach angle: L) insert

Match the insert nose radius and the angle of the surface taper to find the value in Table 1 below to compensate the x-axis position.

For CNMG/WNMG-SW/-FW (Type L)

Compensation values for x-axis (mm)

Nose radius (mm)	Taper angle α (θ)																		
	0	5	10	15	20	25	30	35	40	45	50	55	60	65	70	75	80	85	90
R0.4	0	0.01	0.02	0.03	0.04	0.05	0.05	0.06	0.06	0.07	0.07	0.08	0.09	0.10	0.11	0.11	0.11	0.11	0
R0.8	0	0.01	0.03	0.05	0.06	0.07	0.08	0.09	0.09	0.10	0.11	0.13	0.14	0.16	0.17	0.18	0.17	0.13	0
R1.2	0	0.01	0.03	0.05	0.06	0.07	0.08	0.09	0.10	0.10	0.11	0.13	0.14	0.16	0.17	0.18	0.18	0.16	0



Compensations ③ Program compensation for corner radii (proceed after ①)

To achieve the correct corner radius dimension on the workpiece, compensate the tool position, using the values listed below for respective insert styles.

CNMG/WNMG-SW/-FW (Type L)

Nose Radius	Deviation on the corner radius	Compensate radius by
R0.4	0.05	+0.12
R0.8	0.07	+0.17
R1.2	0.07	+0.18

User's Guide - Technical Reference

Turning Tools

Compensations for CNMG/WNMG -SW / -FW

Compensations ④ Tool offsets (Compensations for X- and Z-axis)

Match the insert approach angle and the insert style to find the value and compensate the machining program for the insert radius. *This compensation procedure will not be necessary if the insert is compensated with the built-in tool presetter after insert replacement.

DNMG-SW/-FW (Type J)

Nose Radius	X-axis direction	Z-axis direction
R0.4	0.24	0.03
R0.8	0.23	0.04
R1.2	0.12	0.03

TNMG-SW/-FW (Type J)

Nose Radius	X-axis direction	Z-axis direction
R0.4	0.24	0.04
R0.8	0.21	0.05
R1.2	0.16	0.04

TNMG-SW/-FW (Type G)


Nose Radius	X-axis direction	Z-axis direction
R0.4	0.24	0.02
R0.8	0.21	0.02
R1.2	0.15	0.02

TNMG-SW/-FW (Type F)

Nose Radius	X-axis direction	Z-axis direction
R0.4	0.02	0.24
R0.8	0.02	0.21
R1.2	0.02	0.15

Compensations ⑤ Program compensations for tapered surface (proceed after ④)

To machine tapered surfaces with DNMG or TNMG-SW/-FW insert, compensate both the x-axis and z-axis positions. Since these inserts are commonly used for profiling, to machine a tapered surface with a gradual reduction in diameter, the z-axis position has to be compensated in the negative direction.



Compensations for x- and z-axes when using DNMG or TNMG-SW/-FW

Match the insert nose radius and the angle of the surface taper to find the value in below to compensate the x-axis and/or z-axis positions.

For DNMG-SW/-FW (Type J)

X-axis compensation values for plus-tapered surface (increase in diameter)

Nose radius (mm)	Taper angle α (θ)																		
	0	5	10	15	20	25	30	35	40	45	50	55	60	65	70	75	80	85	90
R0.4	0	-0.01	-0.01	-0.01	-0.01	-0.02	-0.03	-0.04	-0.06	-0.08	-0.10	-0.14	-0.19	-0.20	-0.20	-0.19	-0.19	-0.19	0
R0.8	0	0.01	0.02	0.02	0.03	0.03	0.02	0.01	-0.00	-0.02	-0.05	-0.09	-0.15	-0.17	-0.15	-0.13	-0.12	-0.11	0
R1.2	0	0.02	0.04	0.05	0.06	0.07	0.07	0.06	0.04	0.02	-0.02	-0.09	-0.17	-0.19	-0.16	-0.14	-0.13	-0.15	0

Z-axis compensation values for minus-tapered surface (reduction in diameter)

Nose radius (mm)	Taper angle α (θ)				
	-25	-20	-15	-10	-5
R0.4	0.33	0.34	0.34	0.34	0.34
R0.8	0.30	0.32	0.33	0.34	0.34
R1.2	0.33	0.35	0.38	0.40	0.40

* Match the taper angle and insert nose radius to find the value in Table 2 and compensate the NC program by either adding or deducting the value.

Example:

Tapering a surface of +45° (increase in diameter) with a R0.8 mm insert.

Current NC program: X100

Compensation value: -0.02

Parameter after compensation: X99.98

Turning Tools

Compensations for **DNMG / TNMG -SW / -FW**

Compensations ⑤ Program compensations for tapered surface (proceed after ④)

For TNMG-SW/-FW (Type J)

X-axis compensation values for plus-tapered surface (increase in diameter)



Nose radius (mm)	Taper angle α (θ)																		
	0	5	10	15	20	25	30	35	40	45	50	55	60	65	70	75	80	85	90
R0.4	0	0	0	-0.01	-0.01	-0.02	-0.03	-0.04	-0.05	-0.07	-0.10	-0.14	-0.18	-0.25	-0.28	-0.28	-0.27	-0.27	0
R0.8	0	0.01	0.02	0.03	0.04	0.04	0.04	0.03	0.02	0.00	-0.02	-0.06	-0.11	-0.19	-0.22	-0.20	-0.19	-0.21	0
R1.2	0	0.02	0.05	0.07	0.08	0.09	0.10	0.09	0.08	0.06	0.03	-0.02	-0.10	-0.22	-0.26	-0.25	-0.25	-0.31	0

Z-axis compensation value for minus-tapered surface (reduction in diameter)

Nose radius (mm)	Taper angle α (θ)				
	-25	-20	-15	-10	-5
R0.4	0.42	0.42	0.42	0.41	0.40
R0.8	0.35	0.32	0.33	0.34	0.33
R1.2	0.42	0.36	0.38	0.39	0.37

For TNMG-SW/-FW (Type G)


X-axis compensation values for plus-tapered surface (increase in diameter)



Nose radius (mm)	Taper angle α (θ)																		
	0	5	10	15	20	25	30	35	40	45	50	55	60	65	70	75	80	85	90
R0.4	0	0.00	-0.01	-0.01	-0.02	-0.03	-0.04	-0.05	-0.07	-0.09	-0.12	-0.16	-0.22	-0.28	-0.29	-0.29	-0.29	-0.32	0
R0.8	0	0.01	0.02	0.02	0.03	0.02	0.02	0.01	-0.01	-0.03	-0.06	-0.10	-0.17	-0.25	-0.25	-0.25	-0.28	-0.40	0
R1.2	0	0.03	0.06	0.08	0.09	0.10	0.11	0.10	0.09	0.07	0.04	-0.01	-0.09	-0.18	-0.18	-0.18	-0.20	-0.34	0

For TNMG-SW/-FW (Type F)

X-axis compensation values for plus-tapered surface (increase in diameter)



Nose radius (mm)	Taper angle α (θ)																		
	0	5	10	15	20	25	30	35	40	45	50	55	60	65	70	75	80	85	90
R0.4	0	-0.03	-0.05	-0.08	-0.10	-0.13	-0.13	-0.11	-0.10	-0.09	-0.08	-0.07	-0.06	-0.05	-0.05	-0.04	-0.03	-0.02	0
R0.8	0	-0.04	-0.05	-0.07	-0.09	-0.12	-0.10	-0.07	-0.05	-0.03	-0.01	0.01	0.03	0.05	0.07	0.09	0.11	0.13	0
R1.2	0	-0.03	-0.04	-0.05	-0.07	-0.09	-0.05	-0.01	0.03	0.07	0.11	0.15	0.18	0.22	0.25	0.28	0.32	0.35	0

Compensations ⑥ Program compensation for corner radii (proceed after ④)

To achieve the correct corner radius dimension on the workpiece, compensate the tool position, using the values listed below for respective insert styles.

DNMG-SW/-FW (Type J)

Nose Radius	Deviation on the corner radius	Compensate radius by
R0.4	0	0
R0.8	0.02	+0.20
R1.2	0.10	+0.34

TNMG-SW/-FW (Type J)

Nose Radius	Deviation on the corner radius	Compensate radius by
R0.4	0	0
R0.8	0.03	+0.13
R1.2	0.11	+0.36

TNMG-SW/-FW (Type G, Type F)

Nose Radius	Deviation on the corner radius	Compensate radius by
R0.4	0	0
R0.8	0.02	+0.15
R1.2	0.09	+0.38



User's Guide - Technical Reference

Turning Tools

Additional information on offsetting -SW / -FW wiper inserts


Compensations ①, ④ Tool offsets (Compensations for X- and Z-axis)

Why need to offset ?

Ex. When using DNMG150412

The wiper insert does not provide the exact corner radius. A deviation from the standard nose radius shape as shown below will always occur when going into a corner. An additional program adjustment is, therefore, required to achieve the correct corner radius or tapered surface dimension on the workpiece.


Before offset



Wiper nose radius' contour is slightly smaller than the nominal radius.

→ The nose radius profile deviates from the required corner radius, thus the actual corner profile will be **incorrect**.

After offset



Wiper nose radius' contour is partially larger than the nominal radius.

→ No compensations necessary for ID, OD, or face turning.
 Meanwhile, due to these deviations, compensations to the NC program are necessary when turning corners and tapered surfaces for the correct workpiece dimensions.

Compensations ③, ⑥ Program compensation for corner radii (proceed after ①, ④)

Compensation for corner radius

Ex. When using DNMG150412

Example: to machine a corner radius = R2.0 mm, using insert nose radius = R1.2 mm.


For standard ISO insert: DNMG150412-**

Input R0.8 for G2 or G3 (circular interpolation) to compensate the nose radius deviation.

Wiper insert

For wiper insert: DNMG150412-SW/-FW





















Input **R1.14** (= R1.2 + 0.34 from the list) for the nose radius, instead of R0.8, to compensate the nose radius deviation.



User's Guide - Technical Reference

Turning Tools

Troubleshooting in turning

Typical tool failure		Countermeasure		
		Tool grade	Cutting conditions	
Flank wear		<ul style="list-style-type: none"> Change to more wear resistant grades P, M, K30 → 20 → 10 	<ul style="list-style-type: none"> Reduce cutting speed Change to appropriate feed Change to wet cutting 	<ul style="list-style-type: none"> Decrease honing width Increase relief angle Increase end cutting edge angle Increase corner radius Select free-cutting chipbreaker Increase rake angle
				
Crater wear		<ul style="list-style-type: none"> Change to more wear resistant grades P, M, K30 → 20 → 10 	<ul style="list-style-type: none"> Reduce cutting speed Reduce feed Reduce depth of cut Change to wet cutting 	<ul style="list-style-type: none"> Increase rake angle Select an appropriate chipbreaker Increase side cutting edge angle Increase corner radius
				
Notch wear		<ul style="list-style-type: none"> Change to more wear resistant grades P, M, K30 → 20 → 10 	<ul style="list-style-type: none"> Reduce cutting speed Reduce feed 	<ul style="list-style-type: none"> Increase rake angle Increase side cutting edge angle
				
Fracture		<ul style="list-style-type: none"> Change to tougher grades Change to thermal-shock resistant grades P, M, K10 → 20 → 30 	<ul style="list-style-type: none"> Reduce feed Reduce depth of cut Improve holding rigidity of work and tool Reduce overhang length of toolholder Improve looseness in machine 	<ul style="list-style-type: none"> Reduce rake angle Select a chipbreaker with high edge strength Increase honing width Increase side cutting edge angle Select larger shank size Increase corner radius
				
Chipping		<ul style="list-style-type: none"> Change to tougher grades P, M, K10 → 20 → 30 	<ul style="list-style-type: none"> Reduce cutting speed Reduce feed Reduce depth of cut Improve holding rigidity of work and tool Reduce overhang length of toolholder Improve looseness in machine 	<ul style="list-style-type: none"> Reduce rake angle Select a chipbreaker with high edge strength Increase honing width Increase side cutting edge angle Select larger shank size
				
Flaking		<ul style="list-style-type: none"> Change to tougher grades P, M, K10 → 20 → 30 	<ul style="list-style-type: none"> Reduce cutting speed Reduce feed 	<ul style="list-style-type: none"> Reduce rake angle Increase corner radius Increase honing width
				
Plastic deformation		<ul style="list-style-type: none"> Change to more wear resistant grade P, M, K30 → 20 → 10 	<ul style="list-style-type: none"> Reduce cutting speed Change to appropriate feed Reduce depth of cut Supply cutting fluid in adequate volume 	<ul style="list-style-type: none"> Increase relief angle Increase rake angle Reduce corner radius Reduce side cutting edge angle Select a free-cutting chipbreaker
				
Chip welding		<ul style="list-style-type: none"> Use a grade which has a low tendency to adhere to workpiece material Cemented carbide → Coated carbide or cermet 	<ul style="list-style-type: none"> Increase cutting speed Increase feed Change to water-insoluble cutting fluid Change to wet cutting 	<ul style="list-style-type: none"> Increase rake angle Select a free-cutting chipbreaker Decrease honing width
				
Built-up edge		<ul style="list-style-type: none"> Use a grade which has a low tendency to adhere to workpiece material Cemented carbide → Coated carbide or cermet 	<ul style="list-style-type: none"> Increase cutting speed Increase feed Change to water-insoluble cutting fluid Change to wet cutting 	<ul style="list-style-type: none"> Increase rake angle Select a free-cutting chipbreaker Decrease honing width
				
Thermal cracking		<ul style="list-style-type: none"> Change to tougher grades Change to thermal-shock resistant grades P, M, K10 → 20 → 30 	<ul style="list-style-type: none"> Reduce cutting speed Reduce feed Change to dry cutting Supply cutting fluid in adequate volume Reduce depth of cut Change to water-insoluble cutting fluid 	<ul style="list-style-type: none"> Increase rake angle Select a free-cutting chipbreaker Decrease honing width
				

Grade
Insert
Ext. Toolholder
Int. Toolholder
Threading
Grooving
Miniature tool
Milling cutter
Endmill
Drilling tool
Tooling System
User's Guide
Index



User's Guide - Technical Reference

Turning Tools

Problem	Cause	Countermeasure	
		Tool	Cutting conditions and others
Deteriorated surface roughness	<ul style="list-style-type: none"> Increased tool wear 	<ul style="list-style-type: none"> Select a more wear resistant grade Use an insert with a larger rake angle Select a freer-cutting chipbreaker type Use an insert with a larger nose radius Use a more lightly honed insert Use an insert of closer tolerance (from M class to G class) 	<ul style="list-style-type: none"> Select a proper feed Decrease the cutting speed Use a cutting fluid
	<ul style="list-style-type: none"> Edge chipping 	<ul style="list-style-type: none"> Use a tougher grade Select a chipbreaker with strong cutting edges Use a largely honed insert Increase the side cutting edge angle Use a larger shank size 	<ul style="list-style-type: none"> Decrease the depth of cut Decrease the feed Use a more rigid machine Improve the holding rigidity of the tool and workpiece Shorten the overhang of the toolholder Improve the machine looseness
	<ul style="list-style-type: none"> Chip welding Built-up-edge 	<ul style="list-style-type: none"> Select a grade with less affinity with the Workpiece material Use an insert with a larger rake angle Select a freer-cutting chipbreaker type Use a more lightly honed insert Use an insert of closer tolerance (from M class to G class) 	<ul style="list-style-type: none"> Increase the cutting speed Increase the feed Use a water-insoluble cutting fluid Use a cutting fluid
	<ul style="list-style-type: none"> Vibration and chatter 	<ul style="list-style-type: none"> Use a tougher grade Use an insert with a larger rake angle Select a freer-cutting chipbreaker type Use an insert with a smaller nose radius Decrease the side cutting edge angle Use a more lightly honed insert Use a larger shank size 	<ul style="list-style-type: none"> Use a proper cutting speed Decrease the feed Decrease the depth of cut Improve the holding rigidity of the tool and workpiece Shorten the overhang of the toolholder Improve the machine looseness
Deteriorated dimensional accuracy	<ul style="list-style-type: none"> Improper insert accuracy 	<ul style="list-style-type: none"> Use an insert of closer tolerance (from M class to G class) 	
	<ul style="list-style-type: none"> Incomplete engagement of tool and workpiece 	<ul style="list-style-type: none"> Use an insert with a larger rake angle Select a freer-cutting chipbreaker type Use an insert with a smaller nose radius Use a more lightly honed insert 	<ul style="list-style-type: none"> Improve the holding rigidity of the tool and workpiece Shorten the overhang of the toolholder Improve the machine looseness
Burr occurrence	<ul style="list-style-type: none"> Unsuitable cutting speed 		<ul style="list-style-type: none"> Decrease the cutting speed Increase the feed Use a cutting fluid
	<ul style="list-style-type: none"> Worn tool or improper cutting edge geometry 	<ul style="list-style-type: none"> Use a harder grade Use an insert with a larger rake angle Select a freer-cutting chipbreaker type Increase the relief angle Use an insert with a smaller nose radius Decrease the side cutting edge angle Use a more lightly honed insert 	
Edge breakout	<ul style="list-style-type: none"> Improper cutting speed 		<ul style="list-style-type: none"> Decrease the feed Decrease the depth of cut
	<ul style="list-style-type: none"> Worn tool or improper cutting edge geometry 	<ul style="list-style-type: none"> Use a harder grade Use an insert with a larger rake angle Select a freer-cutting chipbreaker type Increase the side cutting edge angle Use an insert with a larger nose radius Use a more lightly honed insert Use a larger shank size 	<ul style="list-style-type: none"> Improve the holding rigidity of the tool and workpiece Shorten the overhang of the toolholder Improve the machine looseness
Fuzzy surface finish	<ul style="list-style-type: none"> Improper cutting conditions 		<ul style="list-style-type: none"> Increase the cutting speed Select a proper feed Use a water-insoluble cutting fluid Use a cutting fluid
	<ul style="list-style-type: none"> Worn tool or improper cutting edge geometry 	<ul style="list-style-type: none"> Use a harder grade. Select a grade with less affinity with the Workpiece material Use an insert with a larger rake angle Select a freer-cutting chipbreaker type Use a more lightly honed insert 	

User's Guide - Technical Reference

Chipbreakers

Chip controllability

Necessity of chip control

- ① Why is chip control needed?
- ② Effect of improper chip control

① Why is chip control needed?

What is chip?

For making a product from a workpiece, removed objects produced by a tool which is set to cut to a specified depth with the relative motion of the tool and the workpiece.

Problems when chips are not properly controlled

Necessity of chip control (Problems and effects)

Problems	Effects
1. Scattering of chips and coolant. 2. Wrapping around the workpiece and the tool. 3. Accumulation on the tool, jig, and machining facilities.	1. Disturbs unmanned and automated machining. 2. Disturbs high-speed and high-efficiency machining. 3. Degrades finished surface. 4. Threatens operator's safety. 5. Reduced operation rate.

Additional problems when chips are not properly controlled

② Effect of improper chip control

Effects on quality

- Defective work.
- Defective surface finish
- Chip entangling

Effects on operation












- Increased number of man-hours for handling.
- Increased tool costs.
- Troublesome chip handling.
- Machine stoppage and reduced operation rate.

Effect on safety and health.

- Stain and damage on machine caused from improper carrying-out of chips.
- Dangerous effects on the human body. (Injury and burns on hand, etc.)

Effective measures


"Chipbreaker"

Classification	Chip shape		Description of chip shape	Acceptability	Effect
	Depth of cut: small	Depth of cut: large			
Shape A			Chips irregularly entangled	Not acceptable	<ul style="list-style-type: none"> • Wrapping around the tool or workpiece or accumulation around the cutting point, hindering cutting • Possible damage to the machined surface
Shape B			Long continuous spiral chips $l > 50$ mm	 Acceptable	<ul style="list-style-type: none"> • Bulky during transport in the automatic line • May be preferred when one operator handles one machine
Shape C			Short spiral chips $l < 50$ mm		<ul style="list-style-type: none"> • Smooth chip flow • Difficult to scatter • Favorable shape
Shape D			"C" or "9" shaped chips (Around one coiling)		<ul style="list-style-type: none"> • Favorable shape if not scattering • Not bulky and easy to transport
Shape E			Excessively broken chips. Thin pieces or connected in a form of wave as shown in the figure left	Not acceptable	<ul style="list-style-type: none"> • Readily scattering. If scattering is the only trouble, it may be acceptable because the chip cover, etc. may be used. • Tend to cause chatter, causing harm on the finished surface roughness or tool life.

User's Guide - Technical Reference

Chipbreakers

Factors affecting chip control





User's Guide - Technical Reference


Grooving and Parting Tools


How to install and remove the blade and insert **TUNGALOY SYSTEM**

● Assembly

- 

1 Remove all 4 screws and ensure the O rings are all in place.
- 


2 Place the blade and tighten 2 bottom clamping screws.
- 


3 Place the insert in the pocket and tighten the fixing screw in the center.
- 

4 Place the long screw in the angular direction and tighten to clamp the insert.

Please follow the installation order as shown above. When the screws are tightened in the 4→3 order, the insert clamping may be insufficient and unstable.


● Disassembly

- 

1 First loosen the long screw in the angular direction.
- 


2 Loosen the Fixing screw in the center and remove the insert.


Loosening the long screw alone may not release the insert.




※ All parts listed here are included in the tool holder.

PROCEDURE TO CLAMP AND UNCLAMP INSERT **EASYMCUT^{ULTI}**

- 

1 Put the insert in the pocket
- 

2 Turn the wrench and push the insert into the pocket to clamp
- 


3 Unclamp

User's Guide - Technical Reference

Fundamentals of screw threads


● Relationship between lead, lead angle and pitch

1. Lead is the axial distance a screw advances in one rotation. In single start screw, the lead is equal to the pitch.
2. The inclination angle of a threaded groove is called lead angle. In screws of the same diameter, the lead angle increases as the pitch increases.
3. The side face of a completed thread groove is called flank. The distance between the crest and the root is called thread height.



● Single and multi start thread

1. The single start thread has a single groove. Two start thread or three start thread has two grooves or three grooves respectively.
2. The pitch of multi start thread is the distance of adjoining groove.
3. When viewing the section of the multi start thread, the pitch is same as that of the single start thread. The lead of the two or three start thread is twice or three times the pitch. The multi start thread is mainly used for trapezoidal threads.



● Tolerance class of threads

Tolerance classes of screw threads are expressed as follows:
Metric coarse external thread: 6h, 6g Metric coarse internal thread: 5H, 6H

These classes are ranked with tolerances of thread diameter, pitch, thread angle, etc. For fastening applications, 6H- and 6g-class (former JIS second class) threads, manufactured by

cutting or rolling, are generally used. 5H- and 4h-class threads (former JIS first class) are generally finished by grinding.

For example, M8-6g means metric coarse external thread of 6g tolerance class.

TAC threading insert


● Difference between full-profile and partial-profile insert

● Full-profile insert


In the full-profile insert, the major diameter of the thread is finished by the profiled finishing edge as shown in Figure below. Therefore, about 0.1 mm of finishing stock must be left on the outer surface of the workpiece before threading. In trapezoidal threads, since slants of 15° to 30° are left on the crest of the

thread as shown in Figure below, these portions must be finished by another tool later.

Full-profile insert could produce no burr and good thread by the profiled finishing edge.



● When machining trapezoidal threads:



● Partial-profile insert

Partial-profile inserts can not be used for finishing of the crest, but can be applied to a wide range of pitches.

For example

Designation	Pitch (mm)	TPI	Insert radius RE (mm)
16ERA60	0.5 ~ 1.5	48 ~ 16	0.06
16ERG60	1.75 ~ 3	14 ~ 8	0.22

Corner radii of inserts are fitted to the thread of the smallest pitch.

● Difference between external and internal use inserts

In full-profile inserts for metric and unified threads, the corner radius and thread height differ from those for the external and internal use insert respectively. Therefore, the right hand insert for external use and the left hand insert for internal use are not the same tool.

Since the rake angles of toolholders are -10° for external toolholders and -15° for internal toolholders, the external / internal toolholders can not be used for machining internal / external thread.

In Whitworth thread, though the external thread and internal thread have the same thread form, the external and internal toolholders are incompatible because of the different rake angle.

For example

Designation	Applicable inserts	Insert radius R RE (mm)	Thread height (mm)	Rake angle of holders
16ER20ISO	External	0.25	1.52	-10°
16IL20ISO	Internal	0.14	1.3	-15°

Shim replacement method of ST-type tools

Compensation for the lead angle and tool relief angle

When the pitch is large or the screw diameter is small, the lead angle becomes large and the effective relief angle on the advance flank side β_2 becomes small. In particular, this will cause shorter life of the insert in the case of trapezoidal screw with small flank angle. It is ideal without any interference for the thread cutting insert to have an equal relief angle on both right and left. Replace the shim so that the rake face of insert faces the thread groove direction (that is, $\beta = \beta_3$).

Calculating the lead angle

The lead angle is calculated as follows:

$$\beta = \tan^{-1}(\ell / \pi d) = \tan^{-1}(nP / \pi d)$$

β : Lead angle
 ℓ : Lead
 n : No. of threads
 P : Pitch
 d : Pitch diameter

Calculating the relief angle

The relief angle β_1 is calculated as follows:

$$\beta_1 = \tan^{-1}(\tan \theta \cdot \tan \alpha)$$

The α of a standard toolholder is 10° for external threading and 15° for internal threading.

Included angle 2θ	θ	β_1	
		External threading tool	Internal threading tool
60°	30°	5.8°	8.8°
55°	27.5°	5.2°	7.9°
30°	15°	2.7°	4.1°
29°	14.5°	2.6°	4°

Accordingly, the effective relief angle is calculated as follows:

$$\beta_2 = \beta_1 + \beta_3 - \beta$$




β : Lead angle
 β_2 : Effective relief angle
 β_3 : Lead angle compensation value

In other words, $\beta_1 = \beta_2$ when the thread lead angle is equal to the compensation value. Namely, the relief angle of the tool itself is equal to the effective relief angle. If the wrong compensation value is used, $\beta_1 > \beta_2$. The effective relief angle becomes smaller and cause the interference between the flank side of insert and the thread groove. Therefore, carry out compensation of the lead angle so that the following range is obtained:

- $\pm 1^\circ$ when the thread angle is 60° and 55°
- $\pm 3^\circ$ when the thread angle is 30° and 29°

Compensation of lead angle for shim less internal toolholders

When using internal threading toolholders without shim, the above-mentioned method can not be applied for lead angle compensation. Therefore, special toolholders for large lead angles are available as



User's Guide - Technical Reference

Shim replacement method of ST-type tools

Type of shim and the compensation value of lead angle

The designation of the shim and compensated lead angles are shown in the table.

Compensated lead angles	-2°	-1°	0°	1°	2°	3°	4°
Shim	□□□-98	□□□-99	□□□-0	□□□-1	□□□-2	□□□-3	□□□-4

Note: The last numeral of the shim designation is the compensated lead angle.

Toolholders and applicable shims

Screw-on / clamp-on dual toolholders

Toolholder designation	Shim	
	R	L
CER/L□□□□□16DT	AE16-□DT	AN16-□DT
CER/L□□□□□22DT	GXE22-□DT	GXN22-□DT
TCNR/L□□□□□16DT	AN16-□DT	AE16-□DT
TCNR/L□□□□□22DT	GXN22-□DT	GXE22-□DT


Note: Standard shim is AE16-1DT or GX22-1DT. Other types are optional.

Clamp-on type toolholders


Toolholder designation	Shim	
	R	L
CER/L□□□□□16-T	AE16-□	AN16-□
CER/L□□□□□22-T	NXE22-□	NXN22-□
CER/L□□□□□27-T	NXE27-□	NXN27-□
CNR/L□□□□□16	AN16-□	AE16-□
CNR/L□□□□□22	NXN22-□	NXE22-□
CNR/L□□□□□27	NXN27-□	NXE27-□
B-CER/L□□□□□16	AE16-□	AN16-□

Note: Standard shim is □□□□□-1. Other types are optional.

Shim selection guide for screw-on / clamp-on dual ST-type tools




* For the multi start thread lead (multiplied by the pitch and No. of threads)




List of exchangeable shims

	Designation	D30	Designation	D30	Designation	D30	Designation	D30
$\beta_3 = 4^\circ$	AE16-4DT	●	AN16-4DT	●	GXE22-4DT	●	GXN22-4DT	●
$\beta_3 = 3^\circ$	AE16-3DT	●	AN16-3DT	●	GXE22-3DT	●	GXN22-3DT	●
$\beta_3 = 2^\circ$	AE16-2DT	●	AN16-2DT	●	GXE22-2DT	●	GXN22-2DT	●
$\beta_3 = 1^\circ$ Standard shim	A16-1DT	●	A16-1DT	●	GX22-1DT	●	GX22-1DT	●
$\beta_3 = 0^\circ$	AE16-0DT	●	AN16-0DT	●	GXE22-0DT	●	GXN22-0DT	●
$\beta_3 = -1^\circ$	AE16-99DT	●	AN16-99DT	●	GXE22-99DT	●	GXN22-99DT	●
$\beta_3 = -2^\circ$	AE16-98DT	●	AN16-98DT	●	GXE22-98DT	●	GXN22-98DT	●
Applicable toolholders	CER--16DT TCNL--16DT		CEL--16DT TCNR--16DT		CER--22DT TCNL--22DT		CEL--22DT TCNR--22DT	

Shim selection guide for clamp-on type ST-tools



* For the multi start thread lead (multiplied by the pitch and No. of threads)















List of exchangeable shims

	Designation	D30	Designation	D30	Designation	D30	Designation	D30	Designation	D30	
$\beta_3 = 4^\circ$	AE16-4	●	AN16-4	●	NXE22-4	●	NXN22-4	●	NXE27-4	●	NXN27-4
$\beta_3 = 3^\circ$	AE16-3	●	AN16-3	●	NXE22-3	●	NXN22-3	●	NXE27-3	●	NXN27-3
$\beta_3 = 2^\circ$	AE16-2	●	AN16-2	●	NXE22-2	●	NXN22-2	●	NXE27-2	●	NXN27-2
$\beta_3 = 1^\circ$ Standard shim	A16-1	●	A16-1	●	NXE22-1	●	NXN22-1	●	NXE27-1	●	NXN27-1
$\beta_3 = 0^\circ$	AE16-0	●	AN16-0	●	NXE22-0	●	NXN22-0	●	NXE27-0	●	NXN27-0
$\beta_3 = -1^\circ$	AE16-99	●	AN16-99	●	NXE22-99	●	NXN22-99	●	NXE27-99	●	NXN27-99
$\beta_3 = -2^\circ$	AE16-98	●	AN16-98	●	NXE22-98	●	NXN22-98	●	NXE27-98	●	NXN27-98
Applicable toolholders	CER--16T CNL--16 B-CER--16		CEL--16T CNR--16 B-CEL--16		CER--22T CNL--22		CEL--22T CNR--22		CER--27T CNL--27		CEL--27T CNR--27

● : Line up

Threading Methods and Combinations

External threading																					
Right hand thread	Left hand thread																				
 <table border="1"> <tr><td>Work rotation</td><td>Regular</td></tr> <tr><td>Feed direction</td><td>Push</td></tr> <tr><td>Hand of toolholder</td><td>Right</td></tr> <tr><td>Hand of insert</td><td>Right</td></tr> <tr><td>Standard shim</td><td>①</td></tr> </table>	Work rotation	Regular	Feed direction	Push	Hand of toolholder	Right	Hand of insert	Right	Standard shim	①	 <table border="1"> <tr><td>Work rotation</td><td>Reverse</td></tr> <tr><td>Feed direction</td><td>Push</td></tr> <tr><td>Hand of toolholder</td><td>Left</td></tr> <tr><td>Hand of insert</td><td>Left</td></tr> <tr><td>Standard shim</td><td>②</td></tr> </table>	Work rotation	Reverse	Feed direction	Push	Hand of toolholder	Left	Hand of insert	Left	Standard shim	②
Work rotation	Regular																				
Feed direction	Push																				
Hand of toolholder	Right																				
Hand of insert	Right																				
Standard shim	①																				
Work rotation	Reverse																				
Feed direction	Push																				
Hand of toolholder	Left																				
Hand of insert	Left																				
Standard shim	②																				
 <table border="1"> <tr><td>Work rotation</td><td>Regular</td></tr> <tr><td>Feed direction</td><td>Pull</td></tr> <tr><td>Hand of toolholder</td><td>Left</td></tr> <tr><td>Hand of insert</td><td>Left</td></tr> <tr><td>Standard shim</td><td>④</td></tr> </table>	Work rotation	Regular	Feed direction	Pull	Hand of toolholder	Left	Hand of insert	Left	Standard shim	④	 <table border="1"> <tr><td>Work rotation</td><td>Reverse</td></tr> <tr><td>Feed direction</td><td>Pull</td></tr> <tr><td>Hand of toolholder</td><td>Right</td></tr> <tr><td>Hand of insert</td><td>Right</td></tr> <tr><td>Standard shim</td><td>③</td></tr> </table>	Work rotation	Reverse	Feed direction	Pull	Hand of toolholder	Right	Hand of insert	Right	Standard shim	③
Work rotation	Regular																				
Feed direction	Pull																				
Hand of toolholder	Left																				
Hand of insert	Left																				
Standard shim	④																				
Work rotation	Reverse																				
Feed direction	Pull																				
Hand of toolholder	Right																				
Hand of insert	Right																				
Standard shim	③																				
 <table border="1"> <tr><td>Work rotation</td><td>Reverse</td></tr> <tr><td>Feed direction</td><td>Push</td></tr> <tr><td>Hand of toolholder</td><td>Right</td></tr> <tr><td>Hand of insert</td><td>Right</td></tr> <tr><td>Standard shim</td><td>①</td></tr> </table>	Work rotation	Reverse	Feed direction	Push	Hand of toolholder	Right	Hand of insert	Right	Standard shim	①	 <table border="1"> <tr><td>Work rotation</td><td>Regular</td></tr> <tr><td>Feed direction</td><td>Push</td></tr> <tr><td>Hand of toolholder</td><td>Left</td></tr> <tr><td>Hand of insert</td><td>Left</td></tr> <tr><td>Standard shim</td><td>②</td></tr> </table>	Work rotation	Regular	Feed direction	Push	Hand of toolholder	Left	Hand of insert	Left	Standard shim	②
Work rotation	Reverse																				
Feed direction	Push																				
Hand of toolholder	Right																				
Hand of insert	Right																				
Standard shim	①																				
Work rotation	Regular																				
Feed direction	Push																				
Hand of toolholder	Left																				
Hand of insert	Left																				
Standard shim	②																				
 <table border="1"> <tr><td>Work rotation</td><td>Reverse</td></tr> <tr><td>Feed direction</td><td>Pull</td></tr> <tr><td>Hand of toolholder</td><td>Left</td></tr> <tr><td>Hand of insert</td><td>Left</td></tr> <tr><td>Standard shim</td><td>④</td></tr> </table>	Work rotation	Reverse	Feed direction	Pull	Hand of toolholder	Left	Hand of insert	Left	Standard shim	④	 <table border="1"> <tr><td>Work rotation</td><td>Regular</td></tr> <tr><td>Feed direction</td><td>Pull</td></tr> <tr><td>Hand of toolholder</td><td>Right</td></tr> <tr><td>Hand of insert</td><td>Right</td></tr> <tr><td>Standard shim</td><td>③</td></tr> </table>	Work rotation	Regular	Feed direction	Pull	Hand of toolholder	Right	Hand of insert	Right	Standard shim	③
Work rotation	Reverse																				
Feed direction	Pull																				
Hand of toolholder	Left																				
Hand of insert	Left																				
Standard shim	④																				
Work rotation	Regular																				
Feed direction	Pull																				
Hand of toolholder	Right																				
Hand of insert	Right																				
Standard shim	③																				

Internal threading																					
Right hand thread	Left hand thread																				
 <table border="1"> <tr><td>Work rotation</td><td>Regular</td></tr> <tr><td>Feed direction</td><td>Push</td></tr> <tr><td>Hand of toolholder</td><td>Right</td></tr> <tr><td>Hand of insert</td><td>Right</td></tr> <tr><td>Standard shim</td><td>②</td></tr> </table>	Work rotation	Regular	Feed direction	Push	Hand of toolholder	Right	Hand of insert	Right	Standard shim	②	 <table border="1"> <tr><td>Work rotation</td><td>Reverse</td></tr> <tr><td>Feed direction</td><td>Push</td></tr> <tr><td>Hand of toolholder</td><td>Left</td></tr> <tr><td>Hand of insert</td><td>Left</td></tr> <tr><td>Standard shim</td><td>①</td></tr> </table>	Work rotation	Reverse	Feed direction	Push	Hand of toolholder	Left	Hand of insert	Left	Standard shim	①
Work rotation	Regular																				
Feed direction	Push																				
Hand of toolholder	Right																				
Hand of insert	Right																				
Standard shim	②																				
Work rotation	Reverse																				
Feed direction	Push																				
Hand of toolholder	Left																				
Hand of insert	Left																				
Standard shim	①																				
 <table border="1"> <tr><td>Work rotation</td><td>Reverse</td></tr> <tr><td>Feed direction</td><td>Pull</td></tr> <tr><td>Hand of toolholder</td><td>Left</td></tr> <tr><td>Hand of insert</td><td>Left</td></tr> <tr><td>Standard shim</td><td>③</td></tr> </table>	Work rotation	Reverse	Feed direction	Pull	Hand of toolholder	Left	Hand of insert	Left	Standard shim	③	 <table border="1"> <tr><td>Work rotation</td><td>Regular</td></tr> <tr><td>Feed direction</td><td>Pull</td></tr> <tr><td>Hand of toolholder</td><td>Right</td></tr> <tr><td>Hand of insert</td><td>Right</td></tr> <tr><td>Standard shim</td><td>④</td></tr> </table>	Work rotation	Regular	Feed direction	Pull	Hand of toolholder	Right	Hand of insert	Right	Standard shim	④
Work rotation	Reverse																				
Feed direction	Pull																				
Hand of toolholder	Left																				
Hand of insert	Left																				
Standard shim	③																				
Work rotation	Regular																				
Feed direction	Pull																				
Hand of toolholder	Right																				
Hand of insert	Right																				
Standard shim	④																				

Standard shim			
No.	New	No.	New
①	A16-1DT	②	A16-1DT
	A16-1		A16-1
	GX22-1DT		GX22-1DT
	NXE22-1		NXN22-1
③	AE16-99DT	④	AN16-99DT
	AE16-99		AN16-99
	GXE22-99DT		GXN22-99DT
	NXE22-99		NXN22-99
	NXE27-99		NXN27-99

User's Guide - Technical Reference

Infeed per Pass and Number of Passes

ISO metric full-profile inserts (for external)

Pitch	0.5		0.75		1		1.25		1.5		1.75		2		2.5		3		3.5		4		4.5		5		5.5		6								
	Height of thread	Total depth of cut																																			
Number of passes	1	0.15	0.18	0.25	0.25	0.3	0.3	0.3	0.3	0.35	0.35	0.4	0.4	0.4	0.45	0.5	0.5																				
	2	0.12	0.12	0.2	0.2	0.25	0.25	0.25	0.25	0.3	0.3	0.35	0.35	0.35	0.35	0.4																					
	3	0.1	0.12	0.13	0.15	0.2	0.2	0.2	0.25	0.25	0.3	0.3	0.3	0.3	0.3																						
	4	0.05	0.1	0.1	0.14	0.15	0.16	0.2	0.23	0.2	0.25	0.25	0.25	0.25	0.25																						
	5		0.05	0.05	0.1	0.1	0.15	0.15	0.2	0.2	0.21	0.2	0.2	0.25	0.23	0.25																					
	6				0.05	0.05	0.1	0.12	0.15	0.15	0.2	0.2	0.2	0.2	0.2	0.2																					
	7						0.05	0.1	0.15	0.15	0.15	0.15	0.2	0.2	0.2	0.2																					
	8							0.05	0.1	0.15	0.15	0.15	0.15	0.18	0.15	0.15																					
	9								0.05	0.1	0.15	0.15	0.15	0.15	0.15	0.15																					
	10									0.1	0.1	0.13	0.15	0.15	0.15	0.15																					
	11										0.05	0.1	0.1	0.15	0.13	0.15	0.15																				
	12											0.05	0.1	0.1	0.1	0.15	0.15																				
	13												0.1	0.1	0.1	0.15	0.15																				
	14													0.05	0.1	0.1	0.1	0.15																			
	15														0.1	0.1	0.1	0.1																			
	16															0.05	0.1	0.1	0.1																		
	17																0.1	0.1	0.1																		
	18																	0.05	0.1	0.1																	
	19																			0.1	0.1																
	20																				0.05	0.1															
	21																						0.1														
	22																								0.05												
	23																																				
	24																																				

ISO metric full-profile inserts (for internal)

Pitch	0.5		0.75		1		1.25		1.5		1.75		2		2.5		3		3.5		4		4.5		5		5.5		6				
	Height of thread	Total depth of cut																															
Number of passes	1	0.08	0.1	0.14	0.15	0.2	0.2	0.2	0.25	0.25	0.3	0.3	0.35	0.35	0.4	0.4																	
	2	0.07	0.09	0.13	0.13	0.16	0.18	0.18	0.22	0.22	0.25	0.25	0.25	0.25	0.25	0.25																	
	3	0.07	0.08	0.11	0.12	0.14	0.16	0.17	0.2	0.2	0.22	0.22	0.22	0.22	0.22	0.22																	
	4	0.06	0.08	0.1	0.11	0.12	0.14	0.16	0.18	0.18	0.2	0.2	0.2	0.2	0.2	0.2																	
	5	0.06	0.07	0.08	0.1	0.12	0.12	0.14	0.16	0.16	0.18	0.18	0.18	0.18	0.2	0.2	0.19																
	6	0.05	0.06	0.07	0.09	0.1	0.1	0.12	0.15	0.15	0.16	0.18	0.18	0.18	0.18	0.18																	
	7		0.05	0.05	0.07	0.08	0.09	0.1	0.1	0.14	0.14	0.16	0.16	0.16	0.16	0.17																	
	8				0.05	0.05	0.07	0.08	0.1	0.13	0.13	0.14	0.14	0.14	0.14	0.16																	
	9						0.05	0.06	0.08	0.12	0.12	0.14	0.14	0.14	0.14	0.15																	
	10							0.05	0.06	0.1	0.11	0.12	0.12	0.13	0.13	0.14																	
	11								0.05	0.08	0.1	0.12	0.12	0.13	0.13	0.14																	
	12									0.06	0.1	0.1	0.12	0.12	0.13	0.13																	
	13										0.05	0.07	0.1	0.11	0.12	0.12	0.13																
	14											0.05	0.09	0.1	0.12	0.12	0.13																
	15												0.07	0.1	0.11	0.12	0.12																
	16													0.05	0.09	0.1	0.12	0.12															
	17														0.08	0.1	0.1	0.12															
	18															0.05	0.1	0.1	0.1														
	19																0.08	0.1	0.1														
	20																	0.05	0.1	0.1													
	21																		0.08	0.1													
	22																			0.05	0.1												
	23																					0.08											
	24																							0.05									

Unified full-profile inserts

TPI	For external								For internal							
	24	20	18	16	14	12	8	24	20	18	16	14	12	8		
Height of thread	0.67	0.8	0.89	1.01	1.15	1.34	2.01	0.61	0.74	0.82	0.92	1.05	1.23	1.84		
Total depth of cut	0.77	0.9	0.99	1.11	1.25	1.44	2.11	0.71	0.84	0.92	1.02	1.15	1.33	1.94		
Number of passes	1	0.25	0.25	0.28	0.3	0.3	0.3	0.35	0.2	0.2	0.2	0.2	0.25	0.25	0.3	
	2	0.22	0.2	0.23	0.25	0.25	0.25	0.3	0.16	0.16	0.18	0.18	0.2	0.2	0.25	
	3	0.15	0.16	0.18	0.18	0.23	0.21	0.25	0.12	0.13	0.15	0.16	0.18	0.18	0.22	
	4	0.1	0.14	0.15	0.15	0.18	0.18	0.22	0.1	0.12	0.14	0.14	0.16	0.16	0.2	
	5	0.05	0.1	0.1	0.1	0.14	0.15	0.2	0.08	0.1	0.1	0.11	0.13	0.13	0.18	
	6		0.05	0.05	0.08	0.1	0.12	0.2	0.05	0.08	0.1	0.1	0.1	0.1	0.16	
	7				0.05	0.05	0.1	0.16		0.05	0.05	0.08	0.08	0.1	0.14	
	8						0.08	0.16			0.05	0.05	0.08	0.12		
	9						0.05	0.12					0.08	0.12		
	10							0.1					0.05	0.1		
	11								0.05					0.1		
	12														0.05	
	13															
	14															

Whitworth full-profile inserts

TPI	For external								For internal										
	20	19	18	16	14	12	11	10	8	20	19	18	16	14	12	11	10	8	
Height of thread	0.83	0.88	0.92	1.04	1.19	1.39	1.51	1.66	2.08	0.83	0.88	0.92	1.04	1.19	1.39	1.51	1.66	2.08	
Total depth of cut	0.93	0.98	1.02	1.14	1.29	1.49	1.61	1.76	2.18	0.93	0.98	1.02	1.14	1.29	1.49	1.61	1.76	2.18	
Number of passes	1	0.25	0.28	0.3	0.3	0.3	0.3	0.3	0.35	0.35	0.2	0.2	0.22	0.22	0.25	0.25	0.25	0.3	0.35
	2	0.2	0.22	0.24	0.25	0.25	0.25	0.25	0.3	0.3	0.18	0.18	0.18	0.18	0.21	0.21	0.21	0.25	0.3
	3	0.18	0.18	0.18	0.18	0.23	0.2	0.2	0.23	0.25	0.16	0.16	0.17	0.17	0.2	0.2	0.2	0.22	0.25
	4	0.15	0.15	0.15	0.14	0.2	0.18	0.18	0.2	0.23	0.14	0.16	0.16	0.16	0.18	0.18	0.18	0.2	0.22
	5	0.1	0.1	0.1	0.12	0.16	0.15	0.15	0.15	0.22	0.12	0.13	0.14	0.14	0.16	0.16	0.16	0.16	0.2
	6	0.05	0.05	0.05	0.1	0.1	0.14	0.14	0.14	0.2	0.08	0.1	0.1	0.12	0.14	0.14	0.14	0.14	0.18
	7				0.05	0.05	0.12	0.12	0.12	0.18	0.05	0.05	0.05	0.1	0.1	0.1	0.12	0.12	0.16
	8						0.1	0.12	0.12	0.16				0.05	0.05	0.1	0.1	0.12	0.14
	9	</																	

User's Guide - Technical Reference

Infeed per Pass and Number of Passes

30° Trapezoidal (TR) inserts

		For external					For internal				
Pitch		2	3	4	5	6	2	3	4	5	6
Height of thread		1.25	1.75	2.25	2.75	3.5	1.25	1.75	2.25	2.75	3.5
Total depth of cut		1.35	1.85	2.35	2.85	3.6	1.35	1.85	2.35	2.85	3.6
Number of passes	1	0.25	0.25	0.3	0.3	0.3	0.2	0.22	0.25	0.25	0.25
	2	0.2	0.22	0.25	0.25	0.25	0.18	0.2	0.22	0.22	0.22
	3	0.2	0.2	0.22	0.2	0.23	0.18	0.18	0.2	0.2	0.21
	4	0.18	0.18	0.2	0.2	0.2	0.16	0.16	0.2	0.18	0.2
	5	0.15	0.17	0.18	0.18	0.18	0.15	0.16	0.17	0.18	0.18
	6	0.12	0.16	0.16	0.16	0.18	0.13	0.16	0.16	0.16	0.18
	7	0.1	0.14	0.15	0.16	0.16	0.1	0.14	0.16	0.16	0.16
	8	0.1	0.14	0.14	0.15	0.16	0.1	0.14	0.14	0.15	0.16
	9	0.05	0.12	0.14	0.14	0.16	0.1	0.12	0.14	0.14	0.16
	10		0.12	0.12	0.14	0.16	0.05	0.12	0.12	0.14	0.16
	11		0.1	0.12	0.14	0.16		0.1	0.12	0.14	0.16
	12		0.05	0.12	0.12	0.15		0.1	0.12	0.12	0.15
	13			0.1	0.12	0.15		0.05	0.1	0.12	0.15
	14			0.1	0.12	0.15			0.1	0.12	0.15
	15			0.05	0.12	0.14			0.1	0.12	0.14
	16				0.1	0.14			0.05	0.1	0.14
	17				0.1	0.12				0.1	0.12
	18				0.1	0.12				0.1	0.12
	19				0.05	0.12				0.1	0.12
	20					0.12				0.05	0.12
	21					0.1					0.1
	22					0.1					0.1
	23					0.05					0.1
	24										0.05
	25										
	26										

29° Trapezoidal (TR) inserts

		For external			For internal		
TPI		8	6	5	8	6	5
Height of thread		1.88	2.41	2.92	1.88	2.41	2.92
Total depth of cut		1.98	2.51	3.02	1.98	2.51	3.02
Number of passes	1	0.25	0.25	0.25	0.22	0.22	0.22
	2	0.22	0.22	0.22	0.2	0.2	0.2
	3	0.2	0.2	0.2	0.18	0.18	0.18
	4	0.18	0.18	0.18	0.16	0.18	0.18
	5	0.16	0.17	0.18	0.16	0.16	0.16
	6	0.16	0.16	0.16	0.16	0.15	0.16
	7	0.16	0.16	0.16	0.15	0.15	0.15
	8	0.14	0.14	0.14	0.14	0.14	0.14
	9	0.14	0.14	0.14	0.14	0.14	0.14
	10	0.12	0.14	0.14	0.12	0.14	0.14
	11	0.1	0.14	0.14	0.1	0.14	0.14
	12	0.1	0.12	0.14	0.1	0.12	0.14
	13	0.05	0.12	0.12	0.1	0.12	0.12
	14		0.12	0.12	0.05	0.12	0.12
	15		0.1	0.12		0.1	0.12
	16		0.1	0.12		0.1	0.12
	17		0.05	0.12		0.1	0.12
	18			0.12		0.05	0.12
	19			0.1			0.1
	20			0.1			0.1
	21			0.05			0.1
	22						0.05
	23						
	24						
	25						
	26						

PT full-profile inserts

		For external				For internal		
TPI		28	19	14	11	19	14	11
Height of thread		0.6	0.86	1.16	1.48	0.86	1.16	1.48
Total depth of cut		0.7	0.96	1.26	1.58	0.96	1.26	1.58
Number of passes	1	0.25	0.28	0.3	0.3	0.22	0.25	0.25
	2	0.2	0.2	0.25	0.25	0.2	0.22	0.22
	3	0.1	0.18	0.2	0.22	0.18	0.18	0.18
	4	0.1	0.15	0.15	0.18	0.16	0.14	0.18
	5	0.05	0.1	0.11	0.15	0.1	0.12	0.15
	6		0.05	0.1	0.12	0.05	0.1	0.13
	7			0.1	0.11	0.05	0.1	0.12
	8			0.05	0.1		0.1	0.1
	9				0.1		0.05	0.1
	10				0.05			0.1
	11							0.05
	12							
	13							
	14							
	15							
	16							
	17							
	18							
	19							
	20							
	21							
	22							
	23							
	24							
	25							
	26							

NPT full-profile inserts

		For external				For internal		
TPI		18	14	11.5	8	14	11.5	8
Height of thread		1.14	1.47	1.79	2.58	1.47	1.79	2.58
Total depth of cut		1.24	1.57	1.89	2.68	1.57	1.89	2.68
Number of passes	1	0.2	0.25	0.25	0.3	0.22	0.22	0.25
	2	0.18	0.22	0.22	0.25	0.2	0.2	0.2
	3	0.17	0.2	0.2	0.2	0.18	0.18	0.2
	4	0.16	0.18	0.18	0.2	0.18	0.18	0.2
	5	0.14	0.17	0.18	0.2	0.16	0.16	0.2
	6	0.12	0.16	0.17	0.2	0.14	0.16	0.2
	7	0.12	0.12	0.16	0.18	0.12	0.16	0.18
	8	0.1	0.12	0.14	0.18	0.12	0.14	0.18
	9	0.05	0.1	0.12	0.16	0.1	0.12	0.16
	10		0.05	0.12	0.16	0.1	0.12	0.16
	11			0.1	0.14	0.05	0.1	0.14
	12			0.05	0.14		0.1	0.14
	13				0.12		0.05	0.12
	14				0.1			0.1
	15				0.1			0.1
	16				0.05			0.1
	17							0.05
	18							
	19							
	20							
	21							
	22							
	23							
	24							
	25							
	26							



User's Guide - Technical Reference

Standard Cutting Conditions and Infeed Methods

Threading guidelines





Determine the infeed per pass and number of threads whilst referring to the table and description below.

Pitch	0.5	0.75	1	1.25	1.5	1.75	2	2.5	3	3.5	4	4.5	5 ~
TPI	48	32	24	20	16	14	12	10	8	7	6	5.5	5 ~
No. of passes	4 ~ 6	4 ~ 7	4 ~ 8	5 ~ 9	6 ~ 10	7 ~ 12	7 ~ 12	8 ~ 14	10 ~ 16	11 ~ 18	11 ~ 18	11 ~ 19	12 ~ 24

Note:

- When using the full-profile insert, set the total infeed amount by taking the finish stock of 0.1mm into account.
- Set the first infeed to 150 ~ 200% of nose R and do not allow it to exceed 0.5 mm.
- The infeed amount during the final pass must be a minimum of 0.05 mm. No zero cuts should be made. (Extra small infeed or zero cutting of work hardened surfaces will reduce tool life.)
- The partial-profile insert or inside diameter insert has small nose R. Reduce the infeed per pass and increase the no. of passes.
- Regarding standard infeed per passes and no. of passes, please refer to our catalogue.

Infeed methods for threading tools

Infeed method	Features
 <p>Straight infeed (radial infeed)</p>	<ul style="list-style-type: none"> • Most simple and usual method • Suitable for relatively small pitch threads of easily machinable material. • Chip contact length on right and left is longer, causing chattering, with increased load on the nose end. • When the half included angle is not symmetrical to the right and left, infeeding in the direction of 1/2 of the included angle will ensure equal machining with right and left cutting edges.
 <p>Single edge infeed (flank infeed)</p>	<ul style="list-style-type: none"> • Suitable for large pitch threads or easy to tear materials. Effectively prevents chattering. • Chips are discharged in one direction only. Satisfactory chip control. • Edge on the right (with zero infeed) tends to be worn heavily.
 <p>Modified single-edge infeed (flank infeed)</p>	<ul style="list-style-type: none"> • Suitable for large pitch threads or easy to tear materials. Effectively prevents chattering. • Chips are discharged in one direction only. Satisfactory chip control. • Edge on the right performs some cutting, therefore wear of this edge can thus be suppressed.
 <p>Alternating flank infeed</p>	<ul style="list-style-type: none"> • Suitable for large pitch threads or easy to tear material. Effectively prevents chattering. • Chips are discharged alternately in right and left directions, resulting possibly in entanglement. • Right and left edges are used alternately, ensuring uniform wear and extending tool life.

User's Guide - Technical Reference

Selection of ST-type Toolholders

Selection of Internal Toolholders—Relationship between thread sizes, toolholders, and inserts—Part 1

■ Metric coarse screw thread (ISO)

Nominal size	Pitch	Pitch diameter	Lead angle	Shank material Insert size Holder Cat. No. Insert Cat. No.	Steel shank											Carbide shank					*Tsuyari-ichiban*											
					6IR				11IR			16IR		22IR		27IR		6IR			11IR		16IR		22IR							
					SNR0006H06-2	SNR0006H06-3	SNR0008H06-2	SNR0008H06-3	SNR0010K11-2	SNR0010K11-3	SNR0013L11-2	SNR0013L11-3	SNR0016M16-2	SNR0016M16-3	SNR0020G22-2	SNR0020G22-3	CNR0025R22	CNR0032S22	(CNR0040T22)	CNR0040T27	(CNR0050U27)	SNR0006K06SC-2	SNR0006K06SC-3	SNR0008K06SC-2	SNR0008K06SC-3	SNR0010M11SC-2	SNR0010M11SC-3	SNR0016R16SC-2	(SNR0016R16SC-3)	TCNR0025S22DT	(TCNR0032T22DT)	
M10	1.5	9.03	3°02'	IR15ISO																												
M11	1.5	10.03	2°44'	IR15ISO																												
M12	1.75	10.86	2°56'	IR175ISO																												
M14	2	12.7	2°52'	IR20ISO																												
M16	2	14.7	2°29'	IR20ISO																												
M18	2.5	16.38	2°47'	IR25ISO																												
M20	2.5	18.38	2°29'	IR25ISO																												
M22	2.5	20.38	2°14'	IR25ISO																												
M24	3	22.05	2°29'	IR30ISO																												
M27	3	25.05	2°11'	IR30ISO																												
M30	3.5	27.73	2°18'	IR35ISO																												
M33	3.5	30.73	2°05'	IR35ISO																												
M36	4	33.4	2°11'	IR40ISO																												
M39	4	36.4	2°00'	IR40ISO																												
M42	4.5	39.08	2°06'	IR45ISO																												
M45	4.5	42.08	1°57'	IR45ISO																												
M48	5	44.75	2°02'	IR50ISO																												
M52	5	48.75	1°52'	IR50ISO																												
M56	5.5	52.43	1°55'	IR55ISO																												
M60	5.5	56.43	1°47'	IR55ISO																												
M64	6	60.1	1°49'	IR60ISO																												
M68	6	64.1	1°42'	IR60ISO																												

② : Change the shim to NXN22-2 ← ② : Change the shim to NXN27-2 ← ② : Change the shim to GXN22-2DT ←

■ Metric fine screw thread (ISO)

1/4

Nominal size	Pitch	Pitch diameter	Lead angle	Shank material Insert size Holder Cat. No. Insert Cat. No.	Steel shank											Carbide shank																
					6IR				11IR			6IR				11IR																
					SNR0006H06-2	SNR0006H06-3	SNR0008H06-2	SNR0008H06-3	SNR0010K11	SNR0010K11-2	SNR0010K11-3	SNR0013L11	SNR0013L11-2	SNR0013L11-3	SNR0006K06SC-2	SNR0006K06SC-3	SNR0008K06SC-2	SNR0008K06SC-3	SNR0010M11SC	SNR0010M11SC-2	SNR0010M11SC-3	SNR0012P11SC	SNR0012P11SC-2	SNR0012P11SC-3								
M9x0.75	0.75	8.51	1°36'	IR075ISO																												
M9x1	1	8.32	2°11'	IR10ISO																												
M10x0.75	0.75	9.51	1°26'	IR075ISO																												
M10x1	1	9.35	1°57'	IR10ISO																												
M10x1.25	1.25	9.19	2°29'	IR125ISO																												
M11x0.75	0.75	10.51	1°18'	IR075ISO																												
M11x1	1	10.35	1°46'	IR10ISO																												
M12x1	1	11.35	1°36'	IR10ISO																												
M12x1.25	1.25	11.19	2°02'	IR125ISO																												
M12x1.5	1.5	11.03	2°29'	IR15ISO																												
M14x1	1	13.35	1°22'	IR10ISO																												
M14x1.25	1.25	13.19	1°44'	IR125ISO																												
M14x1.5	1.5	13.03	2°06'	IR15ISO																												
M15x1	1	14.35	1°16'	IR10ISO																												
M15x1.5	1.5	14.03	1°57'	IR15ISO																												
M16x1	1	15.35	1°11'	IR10ISO																												
M16x1.5	1.5	15.03	1°49'	IR15ISO																												
M17x1	1	16.35	1°07'	IR10ISO																												
M17x1.5	1.5	16.03	1°42'	IR15ISO																												
M18x1	1	17.35	1°03'	IR10ISO																												
M18x1.5	1.5	17.03	1°36'	IR15ISO																												
M18x2	2	16.7	2°11'	IR20ISO																												
M20x1	1	19.35	0°57'	IR10ISO																												
M20x1.5	1.5	19.03	1°26'	IR15ISO																												
M20x2	2	18.7	1°57'	IR20ISO																												

Note : The above tables show correspondence of internal toolholders at the time of setting clearance between thread and toolholder to 3 mm (1 mm in case of SN type) and the finishing stock to 0.1 mm.

User's Guide - Technical Reference

Selection of ST-type Toolholders

Whitworth British Standard (BSW) (for pipe)

Nominal size	TPI	Pitch diameter	Lead angle	Shank material Insert size Holder Cat. No. Insert Cat. No.	Steel shank										Carbide shank		"Tsuppari-Ichiban"			
					16IR					22IR					16IR		16IR		22IR	
					SNR0016M16	SNR0016M16-2	SNR0016M16-3	CNR0020P16	CNR0025R16	CNR0032S16	SNR0020Q22	SNR0020Q22-2	SNR0020Q22-3	CNR0025R22	CNR0032S22	SNR0016M16	SNR0016M16-2	TSNR0016Q16	TCNR0020R16DT	TCNR0025S16DT
7/16	14	9.95	3°32'	IR14W																
1/2	12	11.34	3°40'	IR12W																
9/16	12	12.93	2°98'	IR12W																
5/8	11	14.4	2°92'	IR11W																
11/16	11	15.98	2°63'	IR11W																
3/4	10	17.42	2°66'	IR10W																
7/8	9	20.42	2°52'	IR9W																
1	8	23.37	2°48'	IR8W																
1 1/8	7	26.25	2°52'	IR7W																
1 1/4	7	29.43	2°25'	IR7W								○								
1 1/2	6	35.39	2°18'	IR6W								○								
1 3/4	5	41.2	2°25'	IR5W								•								②

② : Change the shim to NXN22-2 ←

② : Change the shim to GXN22-2DT ←

Whitworth British Standard Fine (BSF) (for pipe)

Nominal size	TPI	Pitch diameter	Lead angle	Shank material Insert size Holder Cat. No. Insert Cat. No.	Steel shank										Carbide shank		"Tsuppari-Ichiban"									
					6IR		11IR		16IR			22IR			6IR		16IR		16IR		22IR					
					SNR0006H06-2	SNR0008H06-2	SNR0010K11	SNR0010K11-2	SNR0016M16	SNR0016M16-2	SNR0016M16-3	CNR0020P16	CNR0025R16	SNR0020Q22	SNR0020Q22-2	SNR0020Q22-3	CNR0025R22	CNR0032S22	SNR0006H06SC-2	SNR0008H06SC-2	SNR0016M16	SNR0016M16-2	TSNR0016Q16	TCNR0020R16DT	TCNR0025S16DT	TSNR0020R22
7/16	18	10.21	2°52'	IR18W																						
1/2	16	11.68	2°48'	IR16W	○											○										
9/16	16	13.27	2°18'	IR16W	•	○										•	○									
5/8	14	14.71	2°25'	IR14W																						
11/16	14	16.3	2°03'	IR14W				○																		
3/4	12	17.69	2°18'	IR12W																						
7/8	11	20.75	2°03'	IR11W																						
1	10	23.77	1°95'	IR10W						○																
1 1/8	9	26.77	1°92'	IR9W						○										○						
1 1/4	9	29.94	1°72'	IR9W						•				②					○				②			
1 3/8	8	32.89	1°76'	IR8W						•				②					○				②			
1 1/2	8	36.07	1°61'	IR8W						•				②					○				•		②	
1 5/8	8	39.24	1°48'	IR8W					•					○					○				•		○	
1 3/4	7	42.13	1°57'	IR7W										○												②
2	7	48.48	1°37'	IR7W									•						○				•		○	
2 1/4	6	54.44	1°42'	IR6W									•						○				•		○	
2 1/2	6	60.79	1°27'	IR6W									•						○				•		○	
2 3/4	6	67.14	1°15'	IR6W									•						○				•		○	
3	5	72.95	1°27'	IR5W									•						○				•		○	
3 1/4	5	79.3	1°17'	IR5W									•						○				•		○	

② : Change the shim to AN16-2 ←

② : Change the shim to NXN22-2 ←

② : Change the shim to AN16-2DT ←

② : Change the shim to GXN22-2DT ←

Note : The above tables show correspondence of internal toolholders at the time of setting clearance between thread and toolholder to 3 mm (1 mm in case of SN type) and the finishing stock to 0.1 mm.

User's Guide - Technical Reference

Selection of ST-type Toolholders

Parallel pipe thread (G) (for pipe) This table is also applied to PF, Rp, and PS type threads.

Nominal size	TPI	Pitch	Pitch diameter	Lead angle	Shank material Insert size Holder Cat. No. Insert Cat. No.	Steel shank										Carbide shank						"Tsuppari-Ichiban"												
						6IR		11IR			16IR					6IR		11IR		16IR		16IR												
						SNR0006H06-2	SNR0008H06-2	SNR0010K11	SNR0010K11-2	SNR0013L11	SNR0013L11-2	SNR0016M16	SNR0016M16-2	CNR0020P16	CNR0025R16	CNR0032S16	(CNR0040T16)	(CNR0050U16)	SNR0006K06SC-2	SNR0006K06SC-3	SNR0008K06SC-2	SNR0008K06SC-3	SNR0010M11SC	SNR0010M11SC-2	SNR0012P11SC	SNR0012P11SC-2	SNR0016R16SC	SNR0016R16SC-2	TSNR0016Q16	TCONR0020R16DT	TCONR0025S16DT	(TCNR0032T16DT)		
						G1/4	19	1.34	12.30	1°59'	IR19W	•	○								•	○												
G3/8	19	1.34	15.81	1°33'	IR19W	•	•	○							•	○																		
G1/2	14	1.81	19.79	1°40'	IR14W			•											•			○												
G5/8	14	1.81	21.75	1°31'	IR14W			•		○									•			○												
G3/4	14	1.81	25.28	1°18'	IR14W			•		•		○							•		•		○		○									
G7/8	14	1.81	29.04	1°08'	IR14W			•		•		○							•		•		○		○		•	○						
G1	11	2.31	31.77	1°20'	IR11W					•		○											○			•	○							
G1-1/8	11	2.31	36.42	1°09'	IR11W					•		•		○									○			•	•	○						
G1-1/4	11	2.31	40.43	1°02'	IR11W					•		•		○									○			•	•	○						
G1-1/2	11	2.31	46.32	0°55'	IR11W					•		•		○									○			•	•	•	○					
G1-3/4	11	2.31	52.27	0°48'	IR11W					•		•		○									○			•	•	•	○					
G2	11	2.31	58.14	0°43'	IR11W					•		•		○									○			•	•	•	○					
G2-1/4	11	2.31	64.23	0°39'	IR11W					•		•		○									○			•	•	•	○					
G2-1/2	11	2.31	73.71	0°34'	IR11W					•		•		○									○			•	•	•	○					
G2-3/4	11	2.31	80.06	0°32'	IR11W					•		•		○									○			•	•	•	○					
G3	11	2.31	86.41	0°29'	IR11W									○																	○			
G3-1/2	11	2.31	98.85	0°26'	IR11W									○																	○			
G4	11	2.31	111.55	0°23'	IR11W									○																	○			
G4-1/2	11	2.31	124.25	0°20'	IR11W									○																	○			
G5	11	2.31	136.95	0°18'	IR11W									○																	○			
G6	11	2.31	162.35	0°16'	IR11W									○																	○			

○ : Change the shim to AN16-0

○ : Change the shim to AN16-0DT

Taper pipe thread (PT) (for pipe) This table is also applied to Rc type pipe thread.

Nominal size	TPI	Pitch	Pitch diameter	Lead angle	Shank material Insert size Holder Cat. No. Insert Cat. No.	Steel shank										Carbide shank						"Tsuppari-Ichiban"												
						6IR		11IR			16IR					6IR		11IR		16IR		16IR												
						SNR0006H06-2	SNR0006H06-3	SNR0008H06-2	SNR0008H06-3	SNR0010K11	SNR0010K11-2	SNR0013L11	SNR0013L11-2	SNR0016M16	SNR0016M16-2	CNR0020P16	CNR0025R16	CNR0032S16	(CNR0040T16)	(CNR0050U16)	SNR0006K06SC-2	SNR0006K06SC-3	SNR0008K06SC-2	SNR0008K06SC-3	SNR0010M11SC	SNR0010M11SC-2	SNR0012P11SC	SNR0012P11SC-2	SNR0016R16SC	SNR0016R16SC-2	TSNR0016Q16	TCONR0020R16DT	TCONR0025S16DT	(TCNR0032T16DT)
						PT1/4	19	1.34	12.30	1°59'	IR19PT	○																						
PT3/8	19	1.34	15.81	1°33'	IR19PT	•	○									•	○																	
PT1/2	14	1.81	19.79	1°40'	IR14PT					○											•		○											
PT3/4	14	1.81	25.28	1°19'	IR14PT							○									•		•		○		○							
PT1	11	2.31	31.77	1°20'	IR11PT							•		○											○		•	○						
PT1 1/4	11	2.31	40.43	1°02'	IR11PT							•		•		○									○		•	•	○					
PT1 1/2	11	2.31	46.32	0°55'	IR11PT							•		•		○									○		•	•	•	○				
PT2	11	2.31	58.14	0°43'	IR11PT							•		•		○									○		•	•	•	○				
PT2 1/2	11	2.31	73.71	0°34'	IR11PT							•		•		○									○		•	•	•	○				
PT3	11	2.31	86.41	0°29'	IR11PT																										○			
PT3 1/2	11	2.31	98.85	0°26'	IR11PT																										○			
PT4	11	2.31	111.55	0°23'	IR11PT																										○			
PT5	11	2.31	136.95	0°18'	IR11PT																										○			
PT6	11	2.31	162.35	0°16'	IR11PT																										○			
PT7	11	2.31	187.75	0°13'	IR11PT																										○			
PT8	11	2.31	213.15	0°12'	IR11PT																										○			
PT9	11	2.31	238.55	0°11'	IR11PT																										○			
PT10	11	2.31	263.95	0°10'	IR11PT																										○			
PT12	11	2.31	314.75	0°08'	IR11PT																										○			

○ : Change the shim to AN16-0

○ : Change the shim to AN16-0DT

Note : The above tables show correspondence of internal toolholders at the time of setting clearance between thread and toolholder to 3 mm (1 mm in case of SN type) and the finishing stock to 0.1 mm.

User's Guide - Technical Reference

THREADMILLING

Thread Milling CNC Program for Internal Thread

Right-hand thread (climb milling) from bottom up. Program is based on tool center.

This method of programming needs no tool radius compensation value, other than an offset for wear.

$$A = \frac{D_o - D}{2}$$

A = Radius of tool path
 D_o = Major thread diameter
 D = Cutting diameter

General Program

```
G90 G00 G54 G43 H1X0 Y0 Z10 S (n : Number of revolutions)
G00 Z-(to thread depth)
G01 G91 G41 D1 X (A/2) Y-(A/2) Z0 F (Center of tool)
G03 X(A/2) Y(A/2) R (A/2) Z(1/8 pitch) F (Cutting edge)
G03 X0 Y0 I-(A) J0 Z (pitch)
G03 X-(A/2) Y(A/2) R (A/2) Z(1/8 pitch)
G01 G40 X -(A/2) Y-(A/2) Z0
G90 X0 Y0 Z0
```

Internal Thread

Example: M20x2.0 IN-RH (Thread depth 20 mm)

Tool : MTEC1010C27 2.0ISO


(Cutting dia. 10 mm)

$$A = (D_o - D) / 2 = (20 - 10) / 2 = 5$$

$$A/2 = 2.5$$

(Tool compensation of radius=0)

```
G90 G0 G54 G43 G17 H1X0 Y0 Z10 S4000
G0 Z-20
G01 G91 G41 D1X 2.5 Y-2.5 Z0 F840
G03 X2.5 Y2.5 R2.5 Z0.25 F420
G03 X0 Y0 I-5.0 J0 Z2.0
G03 X-2.5 Y2.5 R2.5 Z0.25
G01 G40 X-2.5 Y-2.5 Z0
G90 G0 X0 Y0 Z0
M30
%
```




$$F \text{ (Center of tool)} = n \times f \times z$$

n : Number of revolutions


$$F \text{ (Cutting edge)} = \frac{D_o - D}{D_o} \times n \times f \times z$$

f : rev / tooth
 z : Number of edge

Internal Thread



External Thread



A thread milling operation is applicable for thread cutting in non-symmetrical parts utilizing the advantage of helical interpolation programs on modern machining centers.




For more details, please check ThreadMilling advisor.

User's Guide - Technical Reference

Milling tools


Nomenclature for face milling cutter



Cutter geometry and applications

Condition		Rake angle combination and applicability		
		Negative-Negative	Negative-Positive	Positive-Positive
Shapes of cutting edge	γ_p (GAMP)	-	+	+
	γ_f (GAMF)	-	-	+
	γ_0	-	+	+
Workpiece material	Carbon steels, alloy steels (< 300HB)	△	⊙	⊙
	Stainless steels (< 300HB)	×	⊙	○
	Die steels (< 300HB)	△	⊙	○
	Cast irons Ductile cast irons	⊙	○	○
	Aluminium alloys	×	○	⊙
	Copper and its alloys	×	○	⊙
	Titanium and its alloys	×	○	○
	Hardened steels (40 ~ 55HRC)	○	○	×
Features		· Higher cutting edge strength · Many usable corners of inserts	· Excellent chip removal · Higher cutting edge strength and Freer cutting action	· Most excellent cutting action
Typical examples of mills		DoPent	TungMill DoTripleMill	TFE12 DPD09

() The notation in the brackets is the one used in the catalog (ISO compliant)




User's Guide - Technical Reference

Milling tools

Calculation formulas for milling

●Cutting speed



●Cutting speed (Calculated from number of revolutions)

$$v_c = \frac{\pi \times D \times n}{1000}$$

(m/min)

v_c : Cutting speed (m/min)
 D : Effective diameter (mm) (DC, DCX)
 n : Number of revolutions (min^{-1})
 $\pi \approx 3.14$

●Number of revolution (Calculated from cutting speed)

$$n = \frac{1000 \times v_c}{\pi \times D}$$


(min^{-1})

●Feed speed and feed per tooth

$$v_f = f_z \times z \times n$$


(mm/min)

v_f : Feed speed (mm/min)
 f_z : Feed per tooth (mm/t)
 z : No. of teeth of the cutter
 n : Number of revolutions (min^{-1})



Feed speed is relative speed of cutter and Workpiece material and in the normal milling machine, it is the table speed. In milling, the feed per tooth is very important. The recommended cutting condition is expressed by v_c and f_z and using the above equation calculate n and v_f and input in the machine.

●Cutting time on face milling




$$T = \frac{L}{v_f}$$

(min)

T : Cutting time (min)
 L : Total table feed length.
 (l : Workpieces length (mm) + ϕD_c : Effective cutter diameter (mm) (DC, DCX))
 v_f : Feed speed (mm/min)
 () The notation in the brackets is the one used in the catalog (ISO compliant)


Depth of cut and width of cut



●Depth of cut

Determine by required allowance for machining and capacity of the machine. In case of mill, there are cutting limits according to shape and size of the insert. Please see spec in the catalogue.

a_p : Depth of cut (mm)



●Width of cut and engagement angle

There is an appropriate engage angle depending on the cutter diameter, cutting position, Workpiece material, etc., and ordinarily the values in the table below are used as a guide.

D : Cutter diameter (mm) (DC, DCX)
 E : Engage angle
 a_e : Width of cut (mm)
 () The notation in the brackets is the one used in the catalog (ISO compliant)

Center cutting

Workpiece material	Appropriate E	Cutter dia. and a_e
Steel	~ 42°	$a_e \cong \frac{2}{3} D$
Cast iron	~ 53°	$a_e \cong \frac{4}{5} D$

Shoulder cutting

Workpiece material	Appropriate E	Cutter dia. and a_e
Steel	~ 30°	$a_e \cong \frac{3}{5} D$
Cast iron	~ 40°	$a_e \cong \frac{3}{4} D$




Milling tools

Roughness of finished surface


(1) Theoretical surface roughness

Theoretical roughness as shown below, is the same as for single point turning


●With corner radius RE



●Without corner radius RE




R_{th} : Theoretical roughness (μm)
 f_z : Feed per tooth (mm/t)
 RE : Corner radius (mm)
 α : Corner angle
 β : Face cutting edge angle



(2) Actual surface roughness

A facemill cutter in practice is composed of multiple point cutting edges and is prone to create uneven peaks, or an axial runout error (R_p) on cutting edges. One or two cutting edges being non-coplanar to the rest invariably create the dominant mark on a face-milled surface, producing periodic patterns corresponding to the feed per revolution f (mm/rev) superimposing on the feed per tooth f_z (mm/t).

Improving surface roughness



Face run out must be minimized and a low feed and high speed should be used. Also, in order to attain good finished surface at high efficiency, there are the following methods:

- (1) In case of ordinary mill
Use wiper insert as shown in the figure at left.
- (2) Use of super finish mill for finishing.
 - Use of combination mills with finishing insert such as TFD4400-A and TFP4000IA ($a_p < 1.0$ mm).
 - Use of super finish mill for finishing such as NMS cutters and SFP4000 etc.

User's Guide - Technical Reference

Milling tools

Calculating power requirement

$$P_c = \frac{k_c \times a_p \times a_e \times v_f}{60 \times 1000 \times 1000} \quad (\text{kW})$$

Because practical power requirements depend on the type of mill (proportional to the true rake angle) and the motor efficiency of the machine used, the result calculated from the above formula should be considered as a rough guide.

P_c : Net power requirement (kW)

k_c : Specific cutting force (N/mm²)

[Refer to the Table below]

a_p : Depth of cut (mm)



a_e : Width of cut (mm)

v_f : Feed speed (mm/min)

●Values of specific cutting force (k_c)

Workpiece material (JIS)	Tensile strength MPa	Value of specific cutting force on feed per tooth k_c (N/mm ²)				
		0.1 (mm/t)	0.15 (mm/t)	0.2 (mm/t)	0.3 (mm/t)	0.4 (mm/t)
SS400	520	2150	2000	1900	1750	1650
S55C	770	1970	1860	1800	1760	1620
SCM435	730	2450	2350	2200	1980	1710
SKT4	(HB352)	2030	2010	1810	1680	1590
SC450	520	2710	2530	2410	2240	2120
FC250	(HB200)	1660	1450	1320	1150	1030
Al (Si)	200	660	580	522	460	410
Brass	500	1090	960	877	760	680

●Values of cutting force (k_c)



●Conversion from cutting speed to number of revolutions

(unit : min⁻¹)

Cutter diameter DC, DCX (mm)	Cutting speed (v_c) m/min												
	10	30	50	100	125	150	200	300	500	800	1,000	2,000	4,000
10	318	955	1,592	3,184	3,980	4,777	6,369	9,554	15,923	25,477	31,847	63,694	127,388
12	265	796	1,326	2,653	3,317	3,980	5,307	7,961	13,269	21,231	26,539	53,078	106,157
16	199	597	995	1,990	2,488	2,985	3,980	5,971	9,952	15,923	19,904	39,808	79,617
20	159	477	796	1,592	1,990	2,388	3,184	4,777	7,961	12,738	15,923	31,847	63,694
25	127	382	636	1,273	1,592	1,910	2,547	3,821	6,369	10,191	12,738	25,477	50,955
30	106	318	530	1,061	1,326	1,592	2,123	3,184	5,307	8,492	10,615	21,231	42,462
32	99	298	497	995	1,244	1,492	1,990	2,985	4,976	7,961	9,952	19,904	39,808
35	90	272	454	909	1,137	1,364	1,819	2,729	4,549	7,279	9,099	18,198	36,396
40	79	238	398	796	995	1,194	1,592	2,388	3,980	6,369	7,961	15,923	31,847
50	63	191	318	636	796	955	1,273	1,910	3,184	5,095	6,369	12,738	25,477
63	50	151	252	505	631	758	1,011	1,516	2,527	4,044	5,055	10,110	20,220
80	39	119	199	398	497	597	796	1,194	1,990	3,184	3,980	7,961	15,923
100	31	95	159	318	398	477	636	955	1,592	2,547	3,184	6,369	12,738
125	25	76	127	254	318	382	509	764	1,273	2,038	2,547	5,095	10,191
160	19	59	99	199	248	298	398	597	995	1,592	1,990	3,980	7,961
200	15	47	79	159	199	238	318	477	796	1,273	1,592	3,184	6,369
250	12	38	63	127	159	191	254	382	636	1,019	1,273	2,547	5,095
315	10	30	50	101	126	151	202	303	505	808	1,011	2,022	4,044

Note: In this table, the effects of centrifugal force on the rotating balance of the tool and the toolholder, flying risk of cutter parts, and limited value of toolholder destruction are not considered. Therefore, when using the tool at high speeds, be sure to observe the specified condition range.

User's Guide - Technical Reference

Milling tools

■ Trouble shooting in face milling

Trouble	Possible causes	Countermeasures
Rapid wear of cutting edge	• Improper insert grade selection (Insufficient wear resistance)	• Use a grade with high wear resistance P30 → P20
	• Excessive cutting speed	• Select cutting speed suited for Workpiece material and insert grade
	• Inadequate feed	• Use standard cutting condition in catalog as guide
Rapid chipping of cutting edge	• Improper Insert grade selection (Insufficient toughness)	• Use a grade with high fracture resistance P10 → P20
	• Cutting hard material and unfavorable surface condition	• Decrease cutting speed • Use cutter with strong cutting edge
	• Excessive feed	• Proper selection of feed conditions, using recommended cutting conditions in catalog as guide
	• Excessive pressure applied on cutting edge	• Proper selection of engaging angle
Fracturing	• Machining superalloys	• Use a negative-positive type cutter with large corner angle
	• Cracking due to thermal shock	• Select insert grade of stronger thermal shock resistance • Decrease cutting speed
	• Continuous use of excessively worn insert	• Shorten replacement standard time of insert
	• Cutting hard material	• Use cutter with stronger cutting edge • Use cutter of larger corner angle
	• Obstruction to chip flow • Recutting of chips after chip welding	• Use cutter with better chip expulsion • Select insert grades difficult for chips to adhere Cemented carbides → cermets, coated grades • Use air blow
Excessive chip welding or build-up on cutting edge	• Excessively slow cutting, too fine feed	• Select cutting speed and feed optimized for insert grade and Workpiece material
	• Cutting soft material such as aluminium, copper, mild steel	• Use cutter with large rake angle
	• Cutting stainless steel	• Coated grades (AH130, AH3135)
	• Use of cutter with negative rake or too small rake angle	• Use cutter with large rake angle
	Rough finish	• Effect of built-up edge
• Effect of face cutting edge run out		• Proper installing of inserts • Use insert of high dimensional accuracy • Cleaning of insert pocket
• Continuous use of excessively worn insert		• Shorten replacement standard time of insert
• Remarkable feed marks		• Feed per revolution to be set within flatland width • Use wiper insert type cutter such as T/EAW13 • Use cutter exclusively for finishing
Chattering	• Unstable clamping of workpiece	• Check clamping method of workpiece
	• Cutting of welded construction of thin steel plate	• Use cutter of large rake angle and small corner angle
	• Excessive cutting condition	• Re-examine allowable chip removal rate according to motor HP
	• Face milling of narrow width workpiece	• Use cutter of small cutter diameter and with many teeth
	• Too many simultaneous cutting teeth engagement	• Reduce No. of teeth

Grade

Insert

Toolholder

Ext. Toolholder

Int. Toolholder

Threading

Grooving

Miniature tool

Milling cutter

Endmill

Drilling tool

Tooling System

User's Guide

Index

A

B

C

D

E

F

G

H

I

J

K


L

M


User's Guide - Technical Reference

Solid Carbide Endmills

Part details




Types



Cutting condition of Endmills

● Cutting speed



● Cutting speed (Calculated from number of revolutions)

$$v_c = \frac{\pi \times D \times n}{1000}$$

(m/min)

v_c : Cutting speed (m/min)
 d : Effective diameter (mm) (DC)
 n : Number of revolutions (min^{-1})
 $\pi \approx 3.14$

● Number of revolution (Calculated from cutting speed)

$$n = \frac{1000 \times v_c}{\pi \times D}$$

(min^{-1})

● Feed speed and feed per tooth

$$v_f = f_z \times z \times n$$

(mm/min)

v_f : Feed speed (mm/min)
 f_z : Feed per tooth (mm/t)
 z : No. of teeth of the endmills
 n : Number of revolutions (min^{-1})
 () The notation in the brackets is the one used in the catalog (ISO compliant)


● Cutting

The necessary capacity of the machine is limited by the length of cut edge of the endmill.

● Up milling and down milling


Down milling generally produces better tool life and surface roughness.

In case of cast iron sand inclusion or welding surface, up milling is recommended.




Solid Carbide Endmills


Regrinding procedures of solid carbide endmill




1 Regrinding of end relief angle




2 Regrinding of peripheral rake angle



3 Regrinding of end rake angle (End gash)



4 Regrinding of end relief angle



Notice of regrinding

- If, after checking the damage of the cutting edge, the damage is as case "A" or "B" of the flow chart, the tool must be reground. Too much damage of the cutting edge requires too much stock removal and thus reduces tool life.
- Please use diamond grinding wheel.
- Peripheral relief angle must be ground between 18° and 10°. Relief angle of small diameter cutters for aluminium machining must be a large degree.
- First check if "C" in flow chart can be adapted for the case of coated endmill or not. If procedure "C" can be adapted for regrinding, tool life after the grinding would be more improved than new one. The reason is remaining coated layer of cutting edge and shorter tool length will keep much higher rigidity of the tool than before regrinding.
- Please check run out of peripheral cutting edge, face cutting edge, with Vee block after regrinding. The value of the run out must be controlled within 0.01 mm.

Notice for regrinding of ball nose endmill

- Regrinding of relief angle only is available. The dimension of nose radius will be smaller after grinding.
- Honing of cutting edge is necessary after regrinding.

User's Guide - Technical Reference

Solid Carbide Endmills

■ Trouble shooting in Endmilling

Trouble	Possible causes	Countermeasures
Breakage	<ul style="list-style-type: none"> ● At the start of machining ● At the end of machining 	<ul style="list-style-type: none"> ● Reduce feed. ● Reduce tool overhang length. ● Exchange to short cutting edge tool.
	When usual machining	<ul style="list-style-type: none"> ● Reduce feed. ● Managing tool life → Exchange in shorter time. ● Replace chuck or collet to new one. ● Reduce tool overhang length. ● Make optimum honing on the edge. ● Reduce flutes. E.g. 4 flutes → 3flutes, or 2flutes. ● Use enough coolant. Change direction of supplying coolant.
	When change the direction of feed	<ul style="list-style-type: none"> ● Use the circular interpolation in NC machine. Stop feed shortly before changing. ● Lower feed around changing part. ● Replace chuck or collet to new one.
Fracture on cutting edge	Chipping on corner edge	<ul style="list-style-type: none"> ● Chamfer the corner with hand-stick grinder. ● Down cutting ⇒ Upward milling.
	Chipping on boundary part	<ul style="list-style-type: none"> ● Change cutting direction, Down cutting → Upward milling. ● Reduce cutting speed.
	Chipping on central part or all edges.	<ul style="list-style-type: none"> ● Make slight honing on the edge. Or make honing bigger. ● Change spindle revolution number. ● Increase cutting speed. ● If chattering, increase feed. ● Use coolant or air blast. ● Replace chuck or collet to new one. ● Decrease cutting speed.
	Fracture on cutting edge	<ul style="list-style-type: none"> ● Decrease feed. ● Reduce flutes. E.g. 4 flutes → 3flutes, or 2flutes. ● Make slight honing on the edge. Or make honing bigger. ● Replace chuck or collet to new one. <p>[For Solid carbide endmill]</p> <ul style="list-style-type: none"> ● Decrease cutting speed. ● Use enough coolant. Change direction of supplying coolant.
Large wear in short time		<ul style="list-style-type: none"> ● Decrease cutting speed. ● Change cutting direction, Upward milling → down cutting. ● Increase feed. ● Use coolant or air blast. ● In reground tool, grind flank face with FINER wheel.

(Continued on next page)

User's Guide - Technical Reference

Solid Carbide Endmills

Trouble	Possible causes	Countermeasures
Poor surface finish	Bright, but Wavy surface	<ul style="list-style-type: none"> ● Reduce feed per tooth. ● Increase flutes; E.g. 2 flutes → 3flutes, or 4flutes.
	Small chips are welded on surface.	<ul style="list-style-type: none"> ● Increase cutting speed. ● Use coolant or air blast, or increase coolant. ● Make slight honing on the edge. ● Upward milling → Down cutting. ● Increase feed per tooth. Increase Depth of Cut.
	Scratches on the surface	<ul style="list-style-type: none"> ● Make slight honing on the edge. ● Use non-water soluble coolant. ● Down cutting → Upward milling.
	Poor surface by over cutting	<ul style="list-style-type: none"> ● Reduce depth of cut. ● Increase cutting speed. ● Reduce feed per tooth.
Poor accuracy	Finish size becomes a minus tendency.	<ul style="list-style-type: none"> ● Upward milling → Down cutting. ● Reduce depth of cut. ● Replace chuck or collet to new one. ● Reduce overhang length. ● Increase cutting speed.
	Poor straightness	<ul style="list-style-type: none"> ● Reduce depth of cut. ● Replace chuck or collet to new one. ● Reduce overhang length. ● Increase cutting speed. ● Increase flutes; E.g. 2 flutes → 4flutes. ● Reduce feed per tooth. ● Check the edge. Change tool, when needed.
Chattering		<ul style="list-style-type: none"> ● Increase feed per tooth. Reduce feed per tooth, when current feed is more than 0.07 mm/t. ● Change cutting speed. ● Replace chuck or collet to new one. ● Reduce overhang length. ● Use 2 flutes tool in roughing. Use 4 flutes tool in finishing. ● Down cutting → Upward milling.

Grade

Insert

Ext. Toolholder

Int. Toolholder

Threading

Grooving

Miniature tool

Milling cutter

Endmill

Drilling tool

Tooling System

User's Guide


Index



User's Guide - Technical Reference

Drilling Tools

Nomenclature for solid carbide drills



Cutting forces and power requirement

● Twist drill

Power requirement
$P_C = KD^2n (0.647 + 17.29f) \times 10^{-6}$ (kW)
Thrust force
$T_C = 570KDf^{0.85}$ (N)
Torque
$M_C = \frac{KD^2 (0.630 + 16.84f)}{100}$ (N·m)

- P_C : Power requirement (kW)
- T_C : Thrust force (N)
- M_C : Torque (N·m)
- D : Drill diameter (mm) {DC}
- f : Feed (mm/rev)
- n : No. of revolutions (min⁻¹)
- K : Material constant... Refer to the Table at right

() The notation in the brackets is the one used in the catalog (ISO compliant)

● Material constant compensating for power requirement and thrust force


Workpiece material	Tensile strength		Brinell hardness (HB)	Material constant (K)
	MPa(N/mm ²)	{Kgf/mm ² }		
Cast iron	210	21	177	1.00
Cast iron	280	28	198	1.39
Cast iron	350	35	224	1.88
Aluminium	250	25	100	1.01
Low carbon steel (JIS S20C)	550	55	160	2.22
Free cutting steel (JIS SUM32)	620	62	183	1.42
Manganese steel (JIS SMn438)	630	63	197	1.45
Nickel chromium steel (JIS SNC236)	690	69	174	2.02
4115 steel Cr0.5, Mo0.11, Mn0.8	630	63	167	1.62
Chromium molybdenum steel (JIS SCM430)	770	77	229	2.10
Chromium molybdenum steel (JIS SCM440)	940	94	269	2.41
Nickel chromium molybdenum steel (JIS SNCM420)	750	75	212	2.12
Nickel chromium molybdenum steel (JIS SNCM625)	1,400	140	390	3.44
Chromium vanadium steel				
Cr0.6, Mn0.6, V0.12	580	58	174	2.08
Cr0.8, Mn0.8, V0.1	800	80	255	2.22

Drilling Tools

Guidelines for correct usage of carbide drills

● Holders for solid carbide drills:


A collet chuck holder is recommended for use with carbide drills. When using a milling chuck holder, a collet chuck with a straight shank or straight collet should be used.



● Chucking drills:


Radial run out and lip height should be less than 0.02mm. If run out or lip height is larger (close to 0.05mm), machining is possible. However, less accurate holes or short tool life may be a result.

Overhang length should be as short as possible.




● Coolant Supply:

When using a drill without a coolant hole, such as the DSW-DE type, coolant should always be directed to the entrance of the hole. Maintaining this supplying is very important for stable drilling performance.




● Clamping workpieces:

As solid carbide drills have a higher thrust force, machining with low rigidity or inadequate support can cause fractures or breakages through vibration. It is important the workpiece is rigidly clamped and has adequate support.



● The criteria of tool life:

- Corner wear width: equal to margin width
- Feed mark: 1 - 2 feed marks on the margin
- Spindle load increase: 30% higher than starting level
- Irregular situation: worse chip control, hole diameter change, worse surface finish, larger burrs, bigger sound.



User's Guide - Technical Reference

Drilling Tools

Regrinding method [Applied to DSW]

Please refer to the following instructions prior to regrinding DSW type drills.


Before regrinding

Check the cutting edge for damage and wear. If any large fracture is found, remove with a silicon carbide wheel.

(1) Grinding the flank

- Use a 280 to 400 grit diamond cup type wheel of 100 ~ 200 mm in diameter.
- 1) Grind the relief surface so that primary relief angle (θ) of 2° can be formed as shown in Fig.1. After grinding the other side likewise, do sparkout grinding so that the difference of the lip height will be kept within 0.02 mm.
- 2) In the cases of DSW types: After grinding the primary relief angle (θ) 2° , without rotating the drill, grind the secondary relief surface so that the relief angle (θ) of 3° can be formed. In the same way as 2), take care to bring the ridge line formed between the primary and secondary relief surfaces to the drill center. (Values (θ) of $1^\circ \sim 3^\circ$ are shown in Table 1)

● Fig. 1 Grinding relief angle




(2) Thinning

- Use a 280 ~ 400 grit diamond straight-type wheel of 100 ~ 200 mm in diameter.
- Conduct thinning in the same manner as cross thinning (X-type).
- Values of β_1 to β_3 written in the figures are given in the Table 2.

Table 1	θ_1 (Point angle)	θ_2 (Primary relief angle)	θ_3 (Secondary relief angle)
DSW	-20°	$-6^\circ \sim -12^\circ$	$-23^\circ \sim -27^\circ$

Table 2	β_1	β_2	β_3
DSW	$147^\circ \sim 153^\circ$	$30^\circ \sim 42^\circ$	$95^\circ \sim 110^\circ$

● Fig. 2



(3) Honing

- The honing angle θ and width H should be varied depending on the drill type, diameter, and work material. Recommended honing specifications are given in the Table below.
- Honing procedures (refer to Fig.3)
 - (1) Round the R portion shown in Fig.3 in large.
 - (2) Then, roughly hone the cutting edge lines by using an electro-deposited diamond file of around 170 grit.
 - (3) Carry out finish honing by using a diamond hand stick of 400 to 600 grit.
- The honing width should be changed depending on the drill diameter. For smaller side of diameters, the width should be in smaller side of values given in the Table.


● Angle honing

	$\sim \phi 6$ mm	$\phi 6 \sim \phi 10$ mm	$\phi 10 \sim \phi 16$ mm
θ	-20°	-20°	-20°
H	0.03 ~ 0.05	0.05 ~ 0.08	0.08 ~ 0.1

● R Honing

Dimensions (mm)	R Honing R (mm)
$DC \leq \phi 6$	0.02 ~ 0.04
$\phi 6 < DC \leq \phi 16$	0.03 ~ 0.05

● Fig.3



After regrinding, check the following before use.

- The difference of the lip height is kept within 0.02 mm.
- Any damaged portion on the cutting edges is not left.
- Cutting edges are properly honed.
- Any grinding burr is not left.


Notes:

- For more details on regrinding, consult the nearest Tungaloy sales office.


Technical guidelines

When to change drill heads (Criteria for the end of tool life)


The criteria to identify the time for tool change are as follows:




Width of corner wear reaches 0.2 – 0.3 mm.




Spindle load exceeds 125% of the normal value.



Hole diameter is 0.15 mm larger or 0.03 mm smaller than the drill diameter.




Surface roughness deteriorates.




Vibration or unusual noise occurs.

How to clamp the drill head


① Clean and lubricate the pocket.



② Set the drill head into the pocket.



③ Set the clamping key on the drill head



④ Clamp





Coolant supply

Internal coolant supply is recommended.



The required coolant flow and pressure



Parts for Tools
Technical Reference

User's Guide - Technical Reference

Drilling Tools

● Applications that are not recommended

Drilling on slanted surface
 $\theta > 6^\circ$

Plunging

Counter Boring

● Run-out

Run-out should be less than 0.02 mm.

Max. 0.02 mm

Ideal : $\leq 0.02\text{mm}$
Acceptable : $\leq 0.05\text{mm}$
Not acceptable: $> 0.05\text{mm}$

■ Instruction of clamping head

Fig. #1

Fig. #2

Fig. #3

Procedure

- ① Clean the clamping areas on the drill body and the head with an air blast, lubricate them, and put the drill head in the pocket.
- ② Set the clamping key in the groove on the drill head. Push the head toward the pocket with equal torque on the right and the left sides, and turn the clamping key to clamp the head completely. (Fig. #1)
- ③ Be sure that there is no gap between the bottom of the head and the drill body. A shim in the thickness of around 0.01 mm is useful to check the gap. (Fig. #2)
- ④ If there is a gap thicker than 0.01 mm, unclamp the head and return to procedure No. ①
- ⑤ Check the run-out at the margin of the drill head. Run-out must be less than 0.05 mm. (Fig. #3) (Recommended value: less than 0.02 mm)

If the run-out exceeds 0.05 mm, unclamp the head and return to procedure No. ① .

Note #1: If the clamping torque is not equally applied on the right and the left sides of the drill head, there may be a gap between the head and the body, which increases the run-out of the head.

Note #2: Low accuracy in holding the drill body may affect the run-out. If the run-out is large, check the accuracy in holding the drill body.

■ KEY FOR MEASURING HEAD RELEASE TORQUE

The release torque in unclamping a head is measured with a torque driver to determine the body's tool life. Please refer to the below for the standard release torque value which indicates the end of tool life (The value less than the standard should be judged as the end of tool life).

Dedicated key designation :
KHS-TID10-19.99


*Can be connected with a commercially available torque driver.

Head designation	Release torque value to indicate tool replacement	
	(N · m)	(cN · M)
DMP100-109	0.2	20
DMP110-119	0.2	20
DMP120-129	0.25	25
DMP130-139	0.25	25
DMP140-149	0.3	30
DMP150-159	0.3	30
DMP160-169	0.35	35
DMP170-179	0.35	35
DMP180-189	0.4	40
DMP190-199	0.4	40

L072 www.tungaloy.com

Drilling Tools

■ Cutting edge failure of solid carbide drills




■ Change of chip shapes in drilling

● Change of chip shapes relating to cutting conditions

Photographs below show the change of chip shapes relating to change of the feed and the cutting speed. These chip shapes are all well controlled in a proper condition range.

When the speed and feed are low, the chip shows whitish color and the tail of the chip tends to lengthen gradually. In contrast, as the speed or the feed increases, the chip tends to increase in brightness and becomes a compact shape with a short tail. These changes in the shape depend on the cutting temperature. As the temperature increases, chips tend to be broken.



User's Guide - Technical Reference


Drilling Tools

Troubleshooting for solid carbide drills

Problem		Cause	Countermeasure
Abnormal wear	Relief surface	Inappropriate cutting speed	<ul style="list-style-type: none"> •Increase the cutting speed by 10 % within standard conditions if abnormal wear is around center. •Lower the cutting speed by 10 % within standard conditions if abnormal wear is on the periphery.
		Inappropriate cutting fluid	<ul style="list-style-type: none"> •Check the filter. •Use the cutting fluid superior in lubricity. (Increase the dilution rate)
	Margin	Inappropriate cutting speed	<ul style="list-style-type: none"> •Lower the cutting speed by 10 %.
		Regrinding timing, insufficient reground amount	<ul style="list-style-type: none"> •Shorten the regrinding timing.
		Insufficient rigidity of the machine and workpiece	<ul style="list-style-type: none"> •Change the clamp method to the one with rigidity.
		Insufficient drill rigidity	<ul style="list-style-type: none"> •Use smallest possible overhang.
		Inappropriate cutting fluid	<ul style="list-style-type: none"> •Check the filter. •Use the cutting fluid superior in lubricity. (increase the dilution rate)
Intermittent cutting when entering	<ul style="list-style-type: none"> •Avoid interruption at entry and exit. •Lower the feed by about 50 % during entering into and leaving from the workpiece. 		
Chipping and fracture	Chisel section (center of drill cutting edge)	Insufficient rigidity of the drill	<ul style="list-style-type: none"> •Reduce the drill overhang as much as possible. •Increase the feed at entry when the low speed feed is selected in standard cutting condition range. •Use a bushing or a center drill.
		Insufficient rigidity of the machine and workpiece	<ul style="list-style-type: none"> •Change the clamp method to the one with rigidity.
		Inappropriate entry into the workpiece	<ul style="list-style-type: none"> •Avoid interruption at entry into the workpiece. •Lower the feed by 10 % at entry.
		High workpiece hardness	<ul style="list-style-type: none"> •Lower the feed by 10 %.
		Inappropriate honing	<ul style="list-style-type: none"> •Check if honing has been made to the center of cutting edge.
	Peripheral cutting edge	Insufficient drill rigidity	<ul style="list-style-type: none"> •Lower the cutting speed by 10 %. •Increase the feed at entry when the low speed feed is selected in standard cutting condition range.
		Inappropriate drill mounting accuracy	<ul style="list-style-type: none"> •Check the run out accuracy after drill installation. (0.03 mm or less)
		Insufficient machinery and workpiece rigidity	<ul style="list-style-type: none"> •Change the clamp method to the one with rigidity. •Lower the feed during entering into and leaving from the workpiece.
		Inappropriate honing	<ul style="list-style-type: none"> •Check if honing has been made to the cutting edge periphery.
	Margin	Insufficient machine and workpiece rigidity	<ul style="list-style-type: none"> •Change the clamp method to the one with rigidity.
		Insufficient drill rigidity	<ul style="list-style-type: none"> •Use smallest possible overhang. •Use a bushing or center drill.
		Regrinding timing and insufficient amount of reground stock	<ul style="list-style-type: none"> •Shorten the regrinding timing.
		Intermittent cutting when entering or exiting the cut	<ul style="list-style-type: none"> •Avoid interruption at entry and exit. •Lower the feed by about 50 % during entering into and leaving from the workpiece.
Breakage	Tendency to cause chipping or develop abnormal wear	<ul style="list-style-type: none"> •Check the failure mode condition before breakage and find out the wear and chip countermeasures. 	
	Chip packing in the drill flutes	<ul style="list-style-type: none"> •Review the cutting conditions. •For internal coolant supply, raise the supply pressure of cutting fluid. •Use peck feed for deep holes. 	
	Insufficient machine output	<ul style="list-style-type: none"> •Review the cutting conditions. •Use the machine with high power. 	
Insufficient hole accuracy	Insufficient rigidity of the machinery and workpiece	<ul style="list-style-type: none"> •Change to the clamp method with rigidity 	
	Inappropriate drill installation accuracy	<ul style="list-style-type: none"> •Check the run out accuracy of drill mounting. (0.03 mm or less) 	
	Chip packing in the flutes.	<ul style="list-style-type: none"> •Review the cutting conditions. •Raise the cutting oil supply pressure. •Use peck-feed for deep holes. 	
	Inappropriate edge sharpening accuracy	<ul style="list-style-type: none"> •Check the edge shape accuracy. 	
Prolonged chips	Inappropriate cutting conditions	<ul style="list-style-type: none"> •Increase the feed by 10 % within standard conditions. 	
	Inappropriate honing	<ul style="list-style-type: none"> •Provide the appropriate honing. 	
	Cutting edge with chipping or breakage	<ul style="list-style-type: none"> •Lower the cutting speed by 10 %. 	



Drilling Tools

Nomenclature for Indexable drill



Calculation formulas for Indexable drill

●Cutting speed



●When calculating cutting speed from number of revolutions: (Drilling formulas)

$$v_c = \frac{\pi \times D \times n}{1000}$$

(m/min)

v_c : Cutting speed (m/min)
 D : Drill diameter (mm) (DC)
 n : Number of revolution (min^{-1})
 $\pi \approx 3.14$

●When calculating required number of revolutions from cutting speed: (Drilling formulas)

$$n = \frac{1000 \times v_c}{\pi \times D}$$

(min^{-1})

●When calculating cutting speed from number of revolutions: (Where the workpiece rotates.)

$$v_c = \frac{\pi \times D \times n}{1000}$$

(m/min)

v_c : Cutting speed (m/min)
 D : Drilling diameter (mm) (DC)
 n : Number of revolution (min^{-1})
 $\pi \approx 3.14$

●When calculating required number of revolutions from cutting speed: (Where the workpiece rotates.)

$$n = \frac{1000 \times v_c}{\pi \times D}$$

(min^{-1})

●Calculation of feed speed

$$v_f = f \times n$$

(mm/min)

v_f : Feed speed (mm/min)
 f : Feed (mm/rev)
 n : Number of revolution (min^{-1})

() The notation in the brackets is the one used in the catalog (ISO compliant)


User's Guide - Technical Reference

Drilling Tools


Chip shapes

● Chip shape produced with central insert

- A conical coil shape whose apex point coincides with the rotating center of the drill is the basic shape. The chips are broken into small sections with increases in feed. However, excessively high feed causes the chip to increase in thickness and develops vibration which disturbs stable machining.
- In TDX drills, ○ marked chips shown below are the most preferable shapes. This type of chip is broken into adequate lengths by centrifugal forces when used in tool-rotating condition. On the other hand, when used in work-rotating condition such as on a lathe, a continuously long chip is often produced without entangling.




● Relation between chip shapes and feeds (In the case of central insert)



● Example of chip shape in work-rotating applications (In the case of central insert)


($\phi 26$, JIS S45C, $V_c = 100$ m/min, $f = 0.1$ mm/rev)



Drilling Tools

● Chip shape produced with peripheral insert

- Chip problems such as entangling are mainly caused by chips produced with the peripheral insert. These problems are dependent on the types of Workpiece material and the cutting conditions.
- As shown below, when the feed is extremely low, the chips jump over the chipbreaker groove and the continuously long chips may wrap around the drill body.
- When the feed is too high, the chips increase in thickness and can not be curled.
- Therefore, it is important to select proper cutting conditions to suit the machining so that well controlled chips will be formed.



Medium to high carbon steels, alloy steels, etc.


As shown below, several turns of coil are an ideal shape.

As the feed increases, the curl radius and the number of turns tend to decrease.

● Typical chip shapes of general steels



● Variation of chip shapes relating to feeds



Stainless steels, low-carbon steels, low-alloy steels, etc.

- When machining long-chip materials such as stainless steels and mild steels, the wrong selection of cutting conditions results in chip entangling and tool breakage at worst. Therefore, cutting conditions should be carefully selected.
- “C” shaped, continuous coils of several to ten turns having adequately divided lengths are the ideal shape.

● Ideal chip shapes

	Stainless steel (JIS SUS 304) ($\phi 22$, $V_c = 100$ m/min, $f = 0.1$ mm/rev)	Mild steel (JIS SS400) ($\phi 22$, $V_c = 160$ m/min, $f = 0.08$ mm/rev)
DS chipbreaker		
DJ chipbreaker		

For machining stainless steels or low carbon steels, DS chipbreaker is recommended.

When using a TDX drill in tool-rotating condition, DS chipbreaker produces compact chips and allows more stable machining than DJ chipbreaker. When using it in work-rotating condition, DS chipbreaker provides outstanding affect on chip control.

User's Guide - Technical Reference

Drilling Tools


● Chip shapes which tend to entangle and remedies against them

① Apple-peel-like chips

These chips are often produced in machining mild steels or low-carbon steels at low-speeds and low-feeds.

Remedies

Increase the cutting speed in stages by 20% within the range of standard cutting conditions. If there is no effect, increase the feed by about 10 % as the cutting speed is raised by 20%.




Apple-peel-like chips (Without curling)

② Short-lead chips

These chips are often produced in machining stainless steels at low-feeds and tend to entangle to the tool in spite of short length.

Remedies

Increase the feed by about 10 %. If there is no effect, increase the cutting speed in stages by 10% within the range of standard cutting conditions.



Continuously curled "C" shape chips with short lead (P).

③ Very long chips

Often produced in machining mild steels or low-carbon steels under improper cutting conditions.

Remedies

Increase the cutting speed in stages by 20% within the range of standard cutting conditions. If there is no effect, decrease the feed by about 10 % as the cutting speed is raised by 20%.




Continuously coiled long chips

Cutting forces

The charts below show a guideline for cutting forces. Use TDX drills on a machine with ample power and sufficient rigidity.

● Guidelines for cutting forces



User's Guide - Technical Reference

Drilling Tools

Troubleshooting for indexable drills

Problem		Cause	Countermeasure		
Abnormal wear	Central cutting edge	Relief surface	Inappropriate cutting conditions		
	Peripheral cutting edge	Relief surface	Inappropriate cutting conditions		
	Common	Relief surface	Varieties and supply of cutting fluid	<ul style="list-style-type: none"> ● Confirm that the cutting fluid flow is higher than 7 liter/min. ● The concentration of cutting fluid must be higher than 5 %. ● Use the cutting fluid superior in lubricity. ● Change to internal cutting fluid supply from external one. 	
			Vibration in drilling	<ul style="list-style-type: none"> ● Change to the machine with higher torque. ● Change to the clamp method with rigidity. ● Change the drill setting method. 	
			Unsuitable for selection of grade	<ul style="list-style-type: none"> ● Change the grade to high wear resistant. 	
			Looseness of screws	<ul style="list-style-type: none"> ● Tighten the screw. 	
	Crater	Cutting heat is too high	<ul style="list-style-type: none"> ● Change to internal cutting fluid supply from external one. ● Increase the supply rate of the cutting fluid. (Higher than 10 liter/min.) ● Lower the feed by 20 % within standard conditions. ● Lower the cutting speed by 20 % within standard conditions. 		
		Excessive chip welding	<ul style="list-style-type: none"> ● Lower the feed by 20 % within standard conditions. ● Lower the cutting speed by 20 % within standard conditions. 		
	Chipbreaker	Chip packing	<ul style="list-style-type: none"> ● Increase the cutting speed by 20% and lower the feed by 20% within standard conditions. ● Raise the fluid pressure (for higher than 1.5 MPa). 		
	Chipping and fracture	Central cutting edge	The rotation center of drill	Misalignment for workpiece rotation	<ul style="list-style-type: none"> ● Set the misalignment to 0 ~ 0.2 mm.
				Large offset	<ul style="list-style-type: none"> ● Check the manual and use the tool in the allowable offset range.
				No flatness of machined surface	<ul style="list-style-type: none"> ● Flatten the entry surface in pre-machining. ● Set the feed for lower than 0.05 mm/rev in rough surface area.
High feed				<ul style="list-style-type: none"> ● Lower the feed by 20 ~ 50 % within standard conditions. 	
Peripheral cutting edge		Peripheral corner area	Using inserts in excess of tool-life	<ul style="list-style-type: none"> ● Exchange the corner or the insert before the nose wear reaches 0.3 mm. 	
			No flatness of machined surface	<ul style="list-style-type: none"> ● Flatten the entry surface in pre-machining. ● Set the feed for lower than 0.05 mm/rev at rough surface area. 	
			The existence of interrupted area	<ul style="list-style-type: none"> ● Set the feed for lower than 0.05 mm/rev in interrupted area. 	
			Using a chipped corner	<ul style="list-style-type: none"> ● Confirm the corner when exchanging inserts. 	
Common		The unused corner area and cutting edge	High hardness of workpiece	<ul style="list-style-type: none"> ● Increase the cutting speed by 20 % and lower the feed by 20 % within standard conditions. ● Raise the fluid pressure (for higher than 1.5 MPa). 	
			Chip packing	<ul style="list-style-type: none"> ● Lower the feed by 20 % within standard conditions. 	
			Machinery impact	<ul style="list-style-type: none"> ● Change to continuous feed in case of pick feeding. 	
		Contact boundary	Using inserts in excess of tool-life	<ul style="list-style-type: none"> ● Exchange the corner or the insert before the nose wear reaches 0.3 mm. 	
			Vibration in drilling	<ul style="list-style-type: none"> ● Change to the machine with higher rigidity. ● Change to the clamp method with rigidity. ● Change the drill setting method. 	
		Flaking	High hardness of workpiece	<ul style="list-style-type: none"> ● Set the feed for lower than 0.05 mm/rev. 	
			Thermal impact	<ul style="list-style-type: none"> ● Change to internal cutting fluid supply from external one. ● Lower the feed by 20 % within standard conditions. 	
		Common	Unsuitable for selection of grade	<ul style="list-style-type: none"> ● Change the grade to toughness. 	
Looseness of screws			<ul style="list-style-type: none"> ● Tighten the screw. 		

User's Guide - Technical Reference

Drilling Tools

Troubleshooting for indexable drills

Problem		Cause	Countermeasure	
Scratch marks on the tool	The tool periphery	Misalignment of workpiece rotation	● Set the misalignment to 0 ~ 0.2 mm.	
		Offset machining in excess of allowable range	● Use the tool in the allowable offset range.	
		Offset direction reduced diameter of workpiece	● Set offset direction extended diameter of workpiece	
		No flatness of the entry surface	● Flatten the entry surface in pre-machining. ● Set the feed for lower than 0.05 mm/rev in rough surface area.	
		Chipping of peripheral cutting edge	● Exchange the insert.	
		Bend of workpiece	● Change to the clamp method with rigidity.	
		Chip packing	● Increase the cutting speed by 20 % and lower the feed by 20 % within standard conditions. ● Raise the fluid pressure (for higher than 1.5 MPa).	
Inappropriate hole accuracy	Hole diameter	Misalignment for workpiece rotation	● Set the misalignment to 0 ~ 0.2 mm.	
		Inappropriate offset contents	● Adjust offset contents.	
		No flatness of the entry surface	● Flatten the entry surface in pre-machining. ● Set the feed for lower than 0.05 mm/rev at rough surface area.	
		Bend of workpiece	● Change to the clamp method with rigidity.	
	Roughness	Varieties and supply of cutting fluid	● The concentration of cutting fluid must be higher than 5 %. ● Use the cutting fluid superior in lubricity. ● Change to internal cutting fluid supply from external one.	
		Inappropriate cutting conditions	● Increase the cutting speed by 20 % within standard conditions. ● Lower the feed by 20 % within standard conditions.	
	Common	Failures of inserts	● Exchange the insert.	
Chip packing		● Increase the cutting speed by 20 % and lower the feed by 20 % within standard conditions. ● Raise the fluid pressure (for higher than 1.5 MPa).		
Looseness of screws		● Tighten the screw.		
Chip control	Prolonged and twisted of chips	Inappropriate cutting conditions	● Work within standard conditions. ● Increase the cutting speed by 10 % within standard conditions. ● Increase the feed by 10 % within standard conditions.	
		Failures of inserts	● Exchange inserts.	
		Machining by external fluid supply	● Change to internal cutting fluid supply from external one. ● Work by step feed. ● Use dwell function for 0.1 sec approximately.	
		Chips around the central cutting edge	● There is a tendency to shorten the chips when shifting to higher speed and feed.	
	Chip packing	Fluid supply	● Change to internal cutting fluid supply from external one. ● Raise the fluid pressure (for higher than 1.5 MPa).	
		Inappropriate cutting conditions	● Increase the cutting speed by 20 % and lower the feed by 20 % within standard conditions. ● Raise the fluid pressure (for higher than 1.5 MPa).	
	Common	Large failure of drill holders	● Exchange the drill holder.	
		Looseness of screws	● Tighten the screw.	
	Others	Chatter	Inappropriate cutting conditions	● Lower the cutting speed by 20 % within standard conditions. ● Increase the feed by 10 % within standard conditions.
			Large wear of inserts	● Exchange the insert.
Vibration in drilling			● Change to the machine with higher torque rigidity. ● Change to the clamp method with rigidity. ● Change the drill setting method.	
Looseness of screws			● Tighten the screw.	
Machine stop		Insufficient machine power and torque	● Use the range of number of revolutions suited machine spec. Lower the feed by 20 ~ 50%.	
		Burned inserts	● Exchange inserts before the failure becomes larger. ● Check the oil-hole plug screw is tightly screwed in place. ● Check that the fluid flows powerfully from the drill. ● Lower the cutting speed and the feed by 20 % within standard conditions.	
Large burr		Failures of inserts	● Exchange the insert.	
		Inappropriate cutting conditions	● Lower the feed by 20 ~ 50% just before leaving from the workpiece.	

User's Guide - Technical Reference

Grade

Insert

Ext. Toolholder

Int. Toolholder

Threading

Grooving

Miniature tool

Milling cutter

Endmill

Drilling tool

Tooling System


User's Guide

Index



Drilling Tools

Nomenclature for gun drill



Troubleshooting in gun drilling

Problem		Cause	Trigger	Countermeasure
Breaking of drill	At entry into workpiece	Machine	Clamping the workpiece is unstable.	Clamp the workpiece firmly.
			The guide bush is apart from the workpiece surface at the entry.	Contact the guide bush closely with the workpiece.
			The machine's rapid feed is used.	Use cutting feed.
			Whipping effect occurs.	Place a whip guide at the appropriate position.
		The shape of the guide bush is not suitable.	Use the guide bush in the shape suitable for the workpiece.	
		Drill	The drill is not set properly.	Set the drill with an appropriate torque, hydraulic pressure, etc.
		Regrinding is in poor quality.	Make sure no damage is left on the drill and that the cutting edge geometry is not changed.	
	Cutting condition	The feed (f) is too high.	Use low feed.	
	Workpiece	The workpiece surface is slanted.	Use low feed.	
	During drilling	Machine	Clamping the workpiece is unstable.	Clamp the workpiece firmly.
			The shape of the guide bush is not suitable.	Modify the shape of the guide bush. See "Chip packing" for the details.
			The feed speed (V_f) varies.	Use mechanical feed.
		Drill	The number of revolutions varies (decreases).	Increase the machine power or adjust the cutting conditions.
		Drill	Abnormal damage occurs.	See "Short tool life" for the details.
		Cutting condition	The feed (f) is not suitable.	Use an appropriate feed.
	Workpiece	Interrupted or cross drilling is required.	Change the tool to a standard gundrill.	
	Others	Chip packing occurs.	See "Chip packing" for the details.	
	At exit from workpiece	Drill	The tip is too long.	Make the tip length short.
The selection of the guide pads is not suitable.			Use 2 guide pads instead of 3.	
The clearance of the coolant hole is too large.			Reduce the clearance of the coolant hole.	
Cutting condition		The feed (f) is too high.	Use low feed.	
Workpiece	The workpiece surface is slanted.	Use low feed.		
During retracting	Machine	Clamping the workpiece is unstable.	Clamp the workpiece firmly.	
	Cutting condition	Burnishing torque (cutting power) is increased due to reduced hole diameter.	Reduce cutting speed (V_c).	

User's Guide - Technical Reference

Drilling Tools

Troubleshooting in gun drilling

Problem	Cause	Trigger	Countermeasure	
Hole accuracy	Rough surface finish	Machine	Clamping the workpiece is unstable.	Clamp the workpiece firmly.
			The type of coolant is not appropriate.	Use water-insoluble coolant.
			Foreign material is in the coolant.	Thoroughly filtrate the coolant (Use a filter with the filtration accuracy in 10 μ m or less).
			The run-out of the spindle is too large.	Minimize the run-out of the spindle.
			The clearance between the guide bush and the drill is not appropriate.	Replace the guide bush (The clearance should be between +0.003 and +0.008).
			The feed speed (V_f) varies.	Use mechanical feed.
			The number of revolutions varies (decreases).	Increase the machine power or adjust the cutting conditions.
		Drill	Abnormal damage occurs.	See "Short tool life" for the details.
			Regrinding is in poor quality.	Make sure no damage is left on the drill and that the cutting edge geometry is not changed.
		Cutting condition	The feed (f) is too high.	Reduce the feed.
	Others	Chip packing occurs.	See "Chip packing" for the details.	
	Unacceptable circularity, cylindricity, and oversize	Machine	The clearance between the guide bush and the drill is not appropriate.	Replace the guide bush (The clearance should be between +0.003 and +0.008).
			The guide bush is apart from the workpiece surface at the entry.	Contact the guide bush closely with the workpiece.
			The type of coolant is not appropriate.	Use water-insoluble coolant.
			The concentricity of the guide bush and the spindle is too large.	Decrease the concentricity of the guide bush and the spindle.
		Drill	Abnormal damage occurs.	See "Short tool life" for the details.
			Regrinding is in poor quality.	Make sure no damage is left on the drill and that the cutting edge geometry is not changed.
		Cutting condition	The feed (f) is not suitable.	Use an appropriate feed.
		Workpiece	Interrupted or cross drilling is required.	Change the tool to a standard gundrill.
	Others	Chip packing occurs.	See "Chip packing" for the details.	
	Bending of hole	Machine	Clamping the workpiece is unstable.	Clamp the workpiece firmly.
			The guide bush is apart from the workpiece surface at the entry.	Contact the guide bush closely with the workpiece.
			The concentricity of the guide bush and the spindle is too large.	Decrease the concentricity of the guide bush and the spindle.
			The clearance between the guide bush and the drill is not appropriate.	Replace the guide bush (The clearance should be between +0.003 and +0.008).
		Drill	The selection of the guide pads is not suitable.	Use 2 guide pads instead of 3.
			Regrinding is in poor quality.	Make sure no damage is left on the drill and that the cutting edge geometry is not changed.
		Cutting condition	The feed (f) is too high.	Reduce the feed.
Workpiece		The workpiece has blow holes or unevenness.	Use the workpiece without defect.	
		The workpiece surface is slanted at the entry.	Use low feed.	
		Interrupted or cross drilling is required.	Change the tool to a standard gundrill.	

User's Guide - Technical Reference

Drilling Tools

Troubleshooting in gun drilling

Problem		Cause	Trigger	Countermeasure
Short tool life	Abnormal wear	Machine	The type of coolant is not appropriate.	Use water-insoluble coolant.
			Foreign material is in the coolant.	Thoroughly filtrate the coolant (Use a filter with the filtration accuracy in 10µm or less).
			The clearance between the guide bush and the drill is not appropriate.	Replace the guide bush (The clearance should be between +0.003 and +0.008).
			Whipping effect occurs.	Place a whip guide at the appropriate position.
			The concentricity of the guide bush and the spindle is too large.	Decrease the concentricity of the guide bush and the spindle.
			The coolant temperature is too high.	Increase the capacity of the tank.
		Drill	The selection of the guide pads is not suitable.	Use 2 guide pads instead of 3.
			Regrinding is in poor quality.	Make sure no damage is left on the drill and that the cutting edge geometry is not changed.
			The drill's overall length is excessive.	Reduce the drill's overall length.
			Excessive wear occurs and the chip shape changes.	Regrind the gundrill (ease the tool life criteria).
		Cutting condition	The cutting speed (V_c) is too high.	Reduce the cutting speed.
			The feed (f) is too high.	Reduce the feed.
			The coolant pressure is not high enough.	Increase the coolant pressure.
		Workpiece	The material quality varies.	Reduce the cutting speed (V_c).
Chip control	Chip packing	Machine	The shape of the guide bush is not suitable.	Modify the tip of the guide bush to match the shape of the workpiece surface at the entry.
			The number of revolutions varies (decreases).	Increase the machine power or adjust the cutting conditions.
			The chip box is too small for smooth chip evacuation.	Enlarge the chip box.
		Cutting condition	The feed (f) is not suitable.	Use an appropriate feed.
			The coolant pressure is not high enough.	Increase the coolant pressure.
		Workpiece	Interrupted or cross drilling is required.	Change the tool to a standard gundrill.
			The operation is for stacked plates.	Change the cutting edge shape so that the cores become small.
			The material quality varies.	Increase the feed.
		Chip entanglement	Drill	The cutting edge is fractured or chipped.
	Wear on the outer corner is excessive.			Regrind the gundrill (ease the tool life criteria).
	Cutting condition		The feed (f) is too low.	Increase the feed.
	Workpiece		Drilling a center hole is required.	Make the center hole as small as the drill diameter and increase the coolant pressure.

Grade
 Insert
 Ext. Toolholder
 Int. Toolholder
 Threading
 Grooving
 Miniature tool
 Milling cutter
 Endmill
 Drilling tool
 Tooling System
 User's Guide
 Index




User's Guide - Technical Reference

Drilling Tools

Drilling procedure on machining centers and lathes

DEEPTRI-DRILL


Proceed as instructed below in order to maximize the tool performance.



① Drill a pilot hole

Hole diameter tolerance: $+0.01 - +0.1$ mm
Hole depth: $H = 20$ mm

Please use DrillMeister or DrillForce-Meister for a pilot hole
Use a drill with $3 \times D$ or smaller




② Start coolant

③ Slowly insert DeepTri-Drill into the pilot hole


No. of revolution: $n = 50 - 100 \text{ min}^{-1}$
Feed speed: $V_f = 100 - 300 \text{ mm/min}$

Caution: Do not rotate the drill at a full machining speed before engaging the pilot hole.



④ Stop the drill at 15 mm depth


⑤ Start rotating at full machining speed



⑥ Start feeding

At the entry ($H = 15 - 25$ mm):
→ Feed: $f = 80\%$ of programmed feed

Hole depth:
 $H \geq 25$ mm → Feed: $f = 100\%$



⑦ For a through hole

Continue drilling until the drill head passes through the workpiece by 5 mm

⑧ Stop the rotation and coolant


⑨ Return the drill

How to use a trlg type deeptri-drill on a horizontal machining center or boring machine


When using the TRLG drill on a conventional machining center or horizontal boring machine where there are no drilling-bush supports available, a pilot hole needs to be further deepened with a MCTR drill to better support the long gundrill. A long gundrill such as the TRLG type drill tends to "whip" when the pilot hole is too short to support the gundrill.



① Drill a pilot hole




② Expand the pilot hole deeper using a MCTR drill




③ Drill with a TRLG drill at a reduced rotation and feed. Use the following parameters:

No. of revolution: $n = 50 - 100 \text{ min}^{-1}$
Feed speed: $V_f = 100 - 300 \text{ mm/min}$



④ When DeepTri-Drill reaches all the way to the end of the pilot hole, increase drill rotation to full machining speed.



⑤ Start feeding to complete the drilling


(Caution)

Always use Step ② to prevent the gundrill from whipping, which may lead to drill breakage and a possible superfluous injury.

User's Guide - Technical Reference

Drilling Tools

Nomenclature for gun reamer



Troubleshooting in gun reaming

Trouble		Possible cause	Countermeasure		
Breaking of reamer	Increased burnishing torque due to excessively small stock allowance	● Chamfer angle small	● Enlarge chamfer angle and increase stock allowance		
		● Excessive wear in peripheral cutting edge.	● Reduce cutting speed to prevent peripheral wear of edge ● Increase lubricity of cutting fluid		
	Sticking	● Faulty filtering of cutting fluid ● Incorrect selection of cutting fluid ● Insufficient cutting fluid pressure	● Improve filtering accuracy ● Change to fluid with higher lubricity ● Increase fluid pressure		
Mechanical trouble			● Repair electrical system ● Improve clamping method of workpiece		
Faulty machining accuracy	Unacceptable surface roughness	Excessive feed rate per tooth	● Reduce fluid pressure ● Increase number of teeth		
		Improper tool specifications	● Excessive chamfer angle ● Excessive back taper ● Peripheral run out excessive	● Reduce chamfer angle ● Reduce back taper ● Improve run out accuracy	
	Too large and inconsistent over size	Faulty regrinding	● Cutting edge run out is large ● Residual damage of preceding process	● Improve run out accuracy ● Remove residual damage completely	
		Improper cutting fluid	● Excessive fluid pressure ● Improper selection of cutting fluid	● Reduce fluid pressure ● Increase activity and lubricity of the fluid	
	Faulty machine accuracy			● Correct spindle run out and bushing clearance and alignment	
	Faulty clamping of workpiece		● Clamping position wrong ● Clamping force inadequate	● Improper clamping position ● Increase clamping force	
	Defective out-of-roundness	Faulty machine accuracy		● Excessive bushing clearance ● Faulty spindle run out and alignment	● Correct bushing clearance ● Correct spindle run out and alignment
		Improper tool specifications		● Outer run out of reamer large ● Insufficient reamer rigidity	● Correct peripheral run out ● Increase reamer rigidity
		Faulty clamping position of workpiece			● Change clamping position
		Unevenness in wall thickness of workpiece			● Reduce reamer guide width (margin width)
Insufficient oversize allowance	Chamfer angle small		● Increase chamfer angle		
	Excessive wear in peripheral cutting edge	● Too high cutting speed ● Faulty lubricity of cutting fluid	● Decrease cutting speed ● Increase lubricating capacity		
	Faulty regrinding (residual damage)			● Increase regrinding stock amount	

User's Guide - Technical Reference

International Tolerance (IT Grade)

International Tolerance (IT Grade)


IT grades shows a tolerance allowable for difference of the diameters of a hole and a shaft. As the number added after IT increases, the tolerance becomes rough. Depending on the basic size, the tolerance value in each grade varies.

In the catalog, IT grades are shown as a guide of dimensional dispersion in the diameters of holes machined with the drill. For information, H8 tolerance for a ø8.0 hole is 0 to + 0.022 mm, the width of the value is the same as that of IT 8.

In the Table shown below, tolerance areas attainable with typical drilling tools are distinguished by using different colors. Solid drills are generally used for machining holes of IT 9 to 12. For machining a hole of better than IT 8, finishing process such as reaming is required. For a hole better than IT 5, high-precision finishing is required. Above description is based on machining of general steel. In practice, the IT grade attained with the tool varies widely depending on the hardness and the composition of the work material.

IT (International Tolerance) Grades

Basic size (mm)		International tolerance grade																	
		IT1	IT2	IT3	IT4	IT5	IT6	IT7	IT8	IT9	IT10	IT11	IT12	IT13	IT14	IT15	IT16	IT17	IT18
>	≤							(μm)						(mm)					
-	3	0.8	1.2	2	3	4	6	10	14	25	40	60	0.1	0.14	0.25	0.4	0.6	1	1.4
3	6	1	1.5	2.5	4	5	8	12	18	30	48	75	0.12	0.18	0.3	0.48	0.75	1.2	1.8
6	10	1	1.5	2.5	4	6	9	15	22	36	58	90	0.15	0.22	0.36	0.58	0.9	1.5	2.2
10	18	1.2	2	3	5	8	11	18	27	43	70	110	0.18	0.27	0.43	0.7	1.1	1.8	2.7
18	30	1.5	2.5	4	6	9	13	21	33	52	84	130	0.21	0.33	0.52	0.84	1.3	2.1	3.3
30	50	1.5	2.5	4	7	11	16	25	39	62	100	160	0.25	0.39	0.62	1	1.6	2.5	3.9
50	80	2	3	5	8	13	19	30	46	74	120	190	0.3	0.46	0.74	1.2	1.9	3	4.6
80	120	2.5	4	6	10	15	22	35	54	87	140	220	0.35	0.54	0.87	1.4	2.2	3.5	5.4
120	180	3.5	5	8	12	18	25	40	63	100	160	250	0.4	0.63	1	1.6	2.5	4	6.3
180	250	4.5	7	10	14	20	29	46	72	115	185	290	0.46	0.72	1.15	1.85	2.9	4.6	7.2
250	315	6	8	12	16	23	32	52	81	130	210	320	0.52	0.81	1.3	2.1	3.2	5.2	8.1
315	400	7	9	13	18	25	36	57	89	140	230	360	0.57	0.89	1.4	2.3	3.6	5.7	8.9
400	500	8	10	15	20	27	40	63	97	155	250	400	0.63	0.97	1.55	2.5	4	6.3	9.7
500	630	9	11	16	22	32	44	70	110	175	280	440	0.7	1.1	1.75	2.8	4.4	7	11
630	800	10	13	18	25	36	50	80	125	200	320	500	0.8	1.25	2	3.2	5	8	12.5
800	1000	11	15	21	28	40	56	90	140	230	360	560	0.9	1.4	2.3	3.6	5.6	9	14
1000	1250	13	18	24	33	47	66	105	165	260	420	660	1.05	1.65	2.6	4.2	6.6	10.5	16.5
1250	1600	15	21	29	39	55	73	125	195	310	500	780	1.25	1.95	3.1	5	7.8	12.5	19.5
1600	2000	18	25	35	46	65	92	150	230	370	600	920	1.5	2.3	3.7	6	9.2	15	23
2000	2500	22	30	41	55	78	110	175	280	440	700	1100	1.75	2.8	4.4	7	11	17.5	28
2500	3150	26	36	50	68	96	135	210	330	540	860	1350	2.1	3.3	5.4	8.6	13.5	21	33



User's Guide - Technical Reference

Deviations of Shafts to be Used in Commonly Used Fits

Deviations of Shafts to be Used in Commonly Used Fits (JIS B0401 extract)

Basic size step (mm)		Tolerance zone class of shaft (μm)															
>	≤	e9	f6	f7	f8	g5	g6	h5	h6	h7	h8	h9	js5	js6	js7	k5	k6
-	3	-14 -39	-6 -12	-6 -16	-6 -20	-2 -6	-2 -8	0 -4	0 -6	0 -10	0 -14	0 -25	±2	±3	±5	+4 0	+6 0
3	6	-20 -50	-10 -18	-10 -22	-10 -28	-4 -9	-4 -12	0 -5	0 -8	0 -12	0 -18	0 -30	±2.5	±4	±6	+6 +1	+9 +1
6	10	-25 -61	-13 -22	-13 -28	-13 -35	-5 -11	-5 -14	0 -6	0 -9	0 -15	0 -22	0 -36	±3	±4.5	±7	+7 +1	+10 +1
10	14	-32 -75	-16 -27	-16 -34	-16 -43	-6 -14	-6 -17	0 -8	0 -11	0 -18	0 -27	0 -43	±4	±5.5	±9	+9 +1	+12 +1
14	18																
18	24	-40 -92	-20 -33	-20 -41	-20 -53	-7 -16	-7 -20	0 -9	0 -13	0 -21	0 -33	0 -52	±4.5	±6.5	±10	+11 +2	+15 +2
24	30																
30	40	-50 -112	-25 -41	-25 -50	-25 -64	-9 -20	-9 -25	0 -11	0 -16	0 -25	0 -39	0 -62	±5.5	±8	±12	+13 +2	+18 +2
40	50																
50	65	-60 -134	-30 -49	-30 -60	-30 -76	-10 -23	-10 -29	0 -13	0 -19	0 -30	0 -46	0 -74	±6.5	±9.5	±15	+15 +2	+21 +2
65	80																
80	100	-72 -159	-36 -58	-36 -71	-36 -90	-12 -27	-12 -34	0 -15	0 -22	0 -35	0 -54	0 -87	±7.5	±11	±17	+18 +3	+25 +3
100	120																

In every step given in the table, the value on the upper side shows the upper deviation and the value on the lower side, the lower deviation.

Deviations of Holes to be Used in Commonly Used Fits. (JIS B0401 extract)

Basic size step (mm)		Tolerance zone class of hole (μm)																
>	≤	E7	E8	E9	F6	F7	F8	G6	G7	H6	H7	H8	H9	H10	JS6	JS7	K6	K7
-	3	+24 +14	+28 +14	+39 +14	+12 +6	+16 +6	+20 +6	+8 +2	+12 +2	+6 0	+10 0	+14 0	+25 0	+40 0	±3	±5	0 -6	0 -10
3	6	+32 +20	+38 +20	+50 +20	+18 +10	+22 +10	+28 +10	+12 +4	+16 +4	+8 0	+12 0	+18 0	+30 0	+48 0	±4	±6	+2 -6	+3 -9
6	10	+40 +25	+47 +25	+61 +25	+22 +13	+28 +13	+35 +13	+14 +5	+20 +5	+9 0	+15 0	+22 0	+36 0	+58 0	±4.5	±7	+2 -7	+5 -10
10	14	+50 +32	+59 +32	+75 +32	+27 +16	+34 +16	+43 +16	+17 +6	+24 +6	+11 0	+18 0	+27 0	+43 0	+70 0	±5.5	±9	+2 -9	+6 -12
14	18																	
18	24	+61 +40	+73 +40	+92 +40	+33 +20	+41 +20	+53 +20	+20 +7	+28 +7	+13 0	+21 0	+33 0	+52 0	+84 0	±6.5	±10	+2 -11	+6 -15
24	30																	
30	40	+75 +50	+89 +50	+112 +50	+41 +25	+50 +25	+64 +25	+25 +9	+34 +9	+16 0	+25 0	+39 0	+62 0	+100 0	±8	±12	+3 -13	+7 -18
40	50																	
50	65	+90 +60	+106 +60	+134 +60	+49 +30	+60 +30	+76 +30	+29 +10	+40 +10	+19 0	+30 0	+46 0	+74 0	+120 0	±9.5	±15	+4 -15	+9 -21
65	80																	
80	100	+107 +72	+126 +72	+159 +72	+58 +36	+71 +36	+90 +36	+34 +12	+47 +12	+22 0	+35 0	+54 0	+87 0	+140 0	±11	±17	+4 -18	+10 -25
100	120																	

In every step given in the table, the value on the upper side shows the upper deviation and the value on the lower side, the lower deviation.



User's Guide - Technical Reference

Symbols of Metals

● Carbon steel and alloy steel for structural use

Type	Japan	International	Other countries				
	JIS		ISO	U.S.A. AISI SAE	Great Britain BS BS/EN	Germany DIN DIN/EN	France NF NF/EN
Carbon steel	S10C	C10	1010	C10 C10E C10R	C10E C10R	C10E C10R	-
	S15C	C15E4 C15M2	1015	C15 C15E C15R	C15E C15R	C15E C15R	-
	S20C	-	1020	C22, C22E C22R	C22 C22E C22R	C22 C22E C22R	-
	S25C	C25 C25E4 C25M2	1025	C25 C25E C25R	C25 C25E C25R	C25 C25E C25R	-
	S30C	C30 C30E4 C30M2	1030	C30 C30E C30R	C30 C30E C30R	C30 C30E C30R	30Г
	S35C	C35 C35E4 C35M2	1035	C35 C35E C35R	C35 C35E C35R	C35 C35E C35R	35Г
	S40C	C40 C40E4 C40M2	1039 1040	C40 C40E C40R	C40 C40E C40R	C40 C40E C40R	40Г
	S43C	-	1042 1043	080A42	-	-	40Г
	S45C	C45 C45E4 C45M2	1045 1046	C45 C45E C45R	C45 C45E C45R	C45 C45E C45R	45Г
	S48C	-	-	-	-	-	45Г
	S50C	C50 C50E4 C50M2	1049	C50 C50E C50R	C50 C50E C50R	C50 C50E C50R	50Г
	S53C	-	1050 1053	-	-	-	50Г
	S55C	C55 C55E4 C55M2	1055	C55 C55E C55R	C55 C55E C55R	C55 C55E C55R	-
	S58C	C60 C60E4 C60M2	1059 1060	C60 C60E C60R	C60 C60E C60R	C60 C60E C60R	60Г

Type	Japan	International	Other countries				
	JIS		ISO	U.S.A. AISI SAE	Great Britain BS BS/EN	Germany DIN DIN/EN	France NF NF/EN
Nickel chromium steel	SNC236	-	-	-	-	-	40XH
	SNC415(H) SNC631(H) SNC815(H) SNC836	15NiCr13	- - - -	15NiCr13	15NiCr13	15NiCr13	- - - -
Alloy steel Nickel chromium molybdenum steel	SNCM220	20NiCrMo2 20NiCrMoS2	8615 8617(H) 8620(H) 8622(H)	20NiCrMo2-2 20NiCrMoS2-2	20NiCrMo2-2 20NiCrMoS2-2	20NiCrMo2-2 20NiCrMoS2-2	-
	SNCM240	41CrNiMo2 41CrNiMoS2	8637 8640	-	-	-	-
	SNCM415	-	-	-	-	-	-
	SNCM420(H)	-	4320(H)	-	-	-	20XH2M(20XHM)
	SNCM431	-	-	-	-	-	-
	SNCM439	-	4340	-	-	-	-
	SNCM447	-	-	-	-	-	-
	SNCM616	-	-	-	-	-	-
	SNCM625	-	-	-	-	-	-
	SNCM630	-	-	-	-	-	-
SNCM815	-	-	-	-	-	-	

Note: The above chart is based on published data and not authorized by each manufacturer.

User's Guide - Technical Reference

Symbols of Metals

● Alloy steel

Type	Japan	International	Other countries					
			U.S.A.		Great Britain	Germany	France	Russia
			JIS	ISO	AISI SAE	BS BS/EN	DIN DIN/EN	NF NF/EN
Alloy steel	Chromium steel	SCr415(H)	-	-	17Cr3 17CrS3	17Cr3 17CrS3	17Cr3 17CrS3	15X 15XA
		SCr420(H)	20Cr4(H) 20CrS4	5120(H)	-	-	-	20X
		SCr430(H)	34Cr4 34CrS4	5130(H) 5132(H)	34Cr4 34CrS4	34Cr4 34CrS4	34Cr4 34CrS4	30X
		SCr435(H)	34Cr4 34CrS4 37Cr4 37CrS4	5132	37Cr4 37CrS4	37Cr4 37CrS4	37Cr4 37CrS4	35X
		SCr440(H)	37Cr4 37CrS4 41Cr4 41CrS4	5140(H)	530M40 41Cr4 41CrS4	41Cr4 41CrS4	41Cr4 41CrS4	40X
	SCr445(H)	-	-	-	-	-	45X	
	Chromium molybdenum steel	SCM415(H)	-	-	-	-	-	-
		SCM418(H)	18CrMo4 18CrMoS4	-	18CrMo4 18CrMoS4	18CrMo4 18CrMoS4	18CrMo4 18CrMoS4	20XM
		SCM420(H)	-	-	708M20(708H20)	-	-	20XM
		SCM430	-	4130	-	-	-	30XM 30XMA
		SCM432	-	-	-	-	-	-
		SCM435(H)	34CrMo4 34CrMoS4	4137(H)	34CrMo4 34CrMoS4	34CrMo4 34CrMoS4	34CrMo4 34CrMoS4	35XM
		SCM440(H)	42CrMo4 42CrMoS4	4140(H) 4142(H)	42CrMo4 42CrMoS4	42CrMo4 42CrMoS4	42CrMo4 42CrMoS4	-
	SCM445(H)	-	4145(H) 4147(H)	-	-	-	-	
	Manganese steel and manganese chromium steel	SMn420(H)	22Mn6(H)	1522(H)	-	-	-	-
SMn433(H)		-	1534	-	-	-	30Г2 35Г2	
SMn438(H)		36Mn6(H)	1541(H)	-	-	-	35Г2 40Г2	
SMn443(H)		42Mn6(H)	1541(H)	-	-	-	40Г2 45Г2	
SMnC420(H)		-	-	-	-	-	-	
SMnC443(H)	-	-	-	-	-	-		
Aluminium chromium molybdenum steel	SACM645	41CrAlMo74	-	-	-	-	-	

● Stainless steel

Type	Japan	International	Other countries						
			U.S.A.		Great Britain	Germany	France	Russia	
			JIS	ISO	UNS	AISI SAE	BS BS/EN	DIN DIN/EN	NF NF/EN
Stainless steel	Austenitic	SUS201	X12CrMnNiN17-7-5	S20100	201			Z12CMN17-07Az	
		SUS202	X12CrMnNiN18-9-5	S20200	202	284S16			12X17T9AH4
		SUS301	X10CrNi18-8	S30100	301	301S21	X12CrNi17-7	Z11CN17-08	07X16H6
		SUS301L	X2CrNiN18-7				X12CrNi18-7		
		SUS301J1					X12CrNi17-7		
		SUS302		S30200	302	302S25		Z12CN18-09	12X18H9
		SUS302B	X12CrNiSi18-9-3	S30215	302B				
		SUS303	X10CrNiS18-9	S30300	303	303S21	X10CrNiS18-9	Z8CNF18-09	
		SUS303Se		S30323	303Se	303S41			12X18H10E
		SUS303Cu							
		SUS304	X5CrNi18-9	S30400	304	304S31	X5CrNi18-10	Z7CN18-09	08X18H10
		SUS304L	X2CrNi18-9	S30403	304L	304S11	X2CrNi19-11	Z3CN19-11	03X18H11
		SUS304N1	X5CrNiN18-8	S30451	304N			Z6CN19-09Az	
		SUS304N2		S30452					
		SUS304LN	X2CrNiN18-9	S30453	304LN		X2CrNiN18-10	Z3CN18-10Az	
		SUS304J1							
		SUS304J2							
SUS304J3		S30431	S30431						
SUS305	X6CrNi18-12	S30500	305	305S19	X5CrNi18-12	Z8CN18-12	06X18H11		

Note: The above chart is based on published data and not authorized by each manufacturer.



User's Guide - Technical Reference

Symbols of Metals

● Stainless steel

Type	Japan	International	Other countries						
	JIS		ISO	U.S.A.		Great Britain	Germany	France	Russia
			UNS	AISI SAE	BS BS/EN	DIN DIN/EN	NF NF/EN	ГОСТ	
Stainless steel	Austenitic	SUS305J1							
		SUS309S		S30908	309S			Z10CN24-13	
		SUS310S	X6CrNi25-21	S31008	310S	310S31		Z8CN25-20	10X23H18
		SUS315J1							
		SUS315J2							
		SUS316	X5CrNiMo17-12-2 X3CrNiMo17-12-3	S31600	316	316S31	X5CrNiMo17-12-2 X5CrNiMo17-13-3	Z7CND17-12-02 Z6CND18-12-03	
		SUS316F							
		SUS316L	X2CrNiMo17-12-2 X2CrNiMo17-12-3 X2CrNiMo18-14-3	S31603	316L	316S11	X2CrNiMo17-13-2 X2CrNiMo17-14-3	Z3CND17-12-02 Z3CND17-12-03	03X17H14M3
		SUS316N		S31651	316N				
		SUS316LN	X2CrNiMoN17-11-2 X2CrNiMoN17-12-3	S31653	316LN		X2CrNiMoN17-12-2 X2CrNiMoN17-13-3	Z3CND17-11Az Z3CND17-12Az	
		SUS316Ti	X6CrNiMoTi17-12-2	S31635			X6CrNiMoTi17-12-2	Z6CNDT17-12	08X17H13M2T
		SUS316J1							
		SUS316J1L							
		SUS317		S31700	317	317S16			
		SUS317L	X2CrNiMo19-14-4	S31703	317L	317S12	X2CrNiMo18-16-4	Z3CND19-15-04	
		SUS317LN	X2CrNiMoN18-12-4	S31753				Z3CND19-14Az	
		SUS317J1							
		SUS317J2							
		SUS317J3L							
		SUS836L		N08367					
		SUS890L	X1CrNiMoCu25-20-5	N08904	N08904	904S14		Z2NCU25-20	
		SUS321	X6CrNiTi18-10	S32100	321	321S31	X6CrNiTi18-10	Z6CNT18-10	08X18H10T
		SUS347	X6CrNiNb18-10	S34700	347	347S31	X6CrNiNb18-10	Z6CNNb18-10	08X18H12B
		SUS384	X3NiCr18-16	S38400	384			Z6CN18-16	
		SUSXM7	X3CrNiCu18-9-4	S30430	304Cu	394S17		Z2CNU18-10	
		SUSXM15J1		S38100				Z15CNS20-12	
		Austenitic Ferritic	SUS329J1		S32900	329			
			SUS329J3L	X2CrNiMoN22-5-3	S31803	31803		Z3CNDU22-05Az	08X21H6M2T
SUS329J4L	X2CrNiMoCuN25-6-3		S32250	32250		Z3CNDU25-07Az			
Ferritic	SUS405	X6CrAl13	S40500	405	405S17	X6CrAl13	Z8CA12		
	SUS410L					Z3C14			
	SUS429		S42900	429					
	SUS430	X6Cr17	S43000	430	430S17	X6Cr17	Z8C17	12X17	
	SUS430F	X7CrS17	S43020	430F		X7CrS18	Z8CF17		
	SUS430LX	X3CrTi17 X3CrNb17	S43035			X6CrTi17	Z4CT17		
	SUS430J1L	X2CrTi17				X6CrNb17	Z4CNb17		
	SUS434	X6CrMo17-1	S43400	434	434S17	X6CrMo17-1	Z8CD17-01		
	SUS436L	X1CrMoTi16-1	S43600	436					
	SUS436J1L								
	SUS444	X2CrMoTi18-2	S44400	444			Z3CDT18-02		
	SUS445J1								
	SUS445J2								
	SUS447J1		S44700						
	SUSXM27		S44627				Z1CD26-01		
Martensitic	SUS403		S40300	403					
	SUS410	X12Cr13	S41000	410	410S21	X10Cr13	Z13C13		
	SUS410S	X6Cr13	S41008	410S	403S17	X6Cr13	Z8C12	08X13	
	SUS410F2								
	SUS410J1		S41025						
	SUS416	X12CrS13	S41600	416	416S21		Z11CF13		
	SUS420J1	X20Cr13	S42000	420	420S29	X20Cr13	Z20C13	20X13	
	SUS420J2	X30Cr13	S42000	420	420S37	X30Cr13	Z33C13	30X13	
	SUS420F	X29CrS13	S42020	420F			Z30CF13		
	SUS420F2								
	SUS429J1								
	SUS431	X19CrNi16-2	S43100	431	431S29	X20CrNi17-2	Z15CN16-02	20X17H2	
	SUS440A	X70CrMo15	S44002	440A			Z70C15		
SUS440B		S44003	440B						
SUS440C	X105CrMo17	S44004	440C			Z100CD17	95X18		
SUS440F		S44020	S44020						
Precipitation hardening type	SUS630	X5CrNiCuNb16-4	S17400	S17400			Z6CNU17-04		
	SUS631	X7CrNiAl17-7	S17700	S17700		X7CrNiAl17-7	Z9CNA17-07	09X17H7IO	
	SUS631J1								

Note: The above chart is based on published data and not authorized by each manufacturer.

User's Guide - Technical Reference

Grade

Insert

Ext. Toolholder

Int. Toolholder

Threading

Grooving

Miniature tool

Milling cutter

Endmill

Drilling tool

Tooling System

User's Guide

Index

Symbols of Metals

● Heat resistant steel

Type	Japan	International	Other countries							
			U.S.A.		Great Britain	Germany	France	Russia		
			JIS	ISO	UNS	AISI SAE	BS BS/EN	DIN DIN/EN	NF NF/EN	ГОСТ
Heat resistant steel	Austenitic	SUH31				331S42		Z35CNWS14-14	45X14H14B2M	
		SUH35			S63008		349S52		Z52CMN21-09Az	
		SUH36					349S54	X53CrMnNi21-9	Z55CMN21-09Az	55X20Г9 AH4
		SUH37			S63017		381S34			
		SUH38								
		SUH309			S30900	309	309S24		Z15CN24-13	
		SUH310			S31000	310	310S24	CrNi2520	Z15CN25-20	20X25H20C2
		SUH330			N08330	N08330			Z12NCS35-16	
		SUH660			S66286				Z6NCTV25-20	
		SUH661			R30155					
Heat resistant steel	Ferritic	SUH21					CrAl1205			
		SUH409	X6CrTi12		S40900	409	409S19	X6CrTi12	Z6CT12	
		SUH409L	X2CrTi12						Z3CT12	
		SUH446			S44600	446			Z12C25	15X28
Heat resistant steel	Martensitic	SUH1			S65007		401S45	X45CrSi9-3	Z45CS9	
		SUH3							Z40CSD10	40X10C2M
		SUH4					443S65		Z80CSN20-02	
		SUH11								40X9C2
		SUH600								20X12BHMБФP
		SUH616			S42200					

● Tool steel

Type	Japan	International	U.S.A.	Type	Japan	International	U.S.A.	
	JIS	ISO	AISI ASTM		JIS	ISO	AISI ASTM	
Carbon tool steel	SK140	-	-	Alloy tool steel	SKS5	-	-	
	SK120	C120U	W1-11 1/2		SKS51	-	L6	
	SK105	C105U	W1-10		SKS7	-	-	
	SK95	-	W1-9		SKS81	-	-	
	SK90	C90U	-		SKS8	-	-	
	SK85	-	W1-8		SKS4	-	-	
	SK80	C80U	-		SKS41	-	-	
	SK75	-	-		SKS43	105V	W2-9 1/2	
	SK70	C70U	-		SKS44	-	W2-8 1/2	
	SK65	-	-		SKS3	-	-	
	SK60	-	-		SKS31	-	-	
	High speed steel	SKH2	HS18-0-1		T1	SKS93	-	-
		SKH3	-		T4	SKS94	-	-
SKH4		-	T5	SKS95	-	-		
SKH10		-	T15	SKD1	X210Cr12	D3		
SKH40		HS6-5-3-8	-	SKD2	X210CrW12	-		
SKH50		HS1-8-1	-	SKD10	X153CrMoV12	-		
SKH51		HS6-5-2	M2	SKD11	-	D2		
SKH52		HS6-6-2	M3-1	SKD12	X100CrMoV5	A2		
SKH53		HS6-5-3	M3-2	SKD4	-	-		
SKH54		HS6-5-4	M4	SKD5	X30WCrV9-3	H21		
SKH55		HS6-5-2-5	-	SKD6	-	H11		
SKH56		-	M36	SKD61	X40CrMoV5-1	H13		
SKH57		HS10-4-3-10	-	SKD62	X35CrWMoV5	H12		
SKH58	HS2-9-2	M7	SKD7	32CrMoV12-28	H10			
SKH59	HS2-9-1-8	M42	SKD8	38CrCoW18-17-17	H19			
Alloy tool steel	SKS11	-	F2	SKT3	-	-		
	SKS2	-	-	SKT4	55NiCrMoV7	-		
	SKS21	-	-	SKT6	45NiCrMo16	-		

● Special use steel

Type	Japan	International	U.S.A.	Type	Japan	International	U.S.A.
	JIS	ISO	AISI ASTM		JIS	ISO	AISI ASTM
Free cutting carbon steels	SUM11	-	1110	Free cutting carbon steels	SUM32	-	-
	SUM12	-	1109		SUM41	-	1137
	SUM21	9S20	1212		SUM42	-	1141
	SUM22	11SMn28	1213		SUM43	44SMn28	1144
	SUM22L	11SMnPb28	-	High carbon chromium	SUJ1	-	-
	SUM23	-	1215		SUJ2	B1	52100
	SUM23L	-	-		SUJ3	B2	ASTM A 485 Grade 1
	SUM24L	11SMnPb28	12L14		SUJ4	-	-
	SUM25	12SMn35	-		SUJ5	-	-
	SUM31	-	1117				
	SUM31L	-	-				

Note: The above chart is based on published data and not authorized by each manufacturer.

User's Guide - Technical Reference

Symbols of Metals

● Casting or forging steel

Type	Japan	International	Other countries					
	JIS		ISO	U.S.A. AISI ASTM	Great Britain BS BS/EN	Germany DIN DIN/EN	France NF NF/EN	Russia ГОСТ
Casting steel	Carbon steel casting	SC	200-400, 230-450, 270-480	U-	A1, A2	GS-	GE230, GE280, GE320	-
	Steel casting for welded structure	SCW	200-400W, 230-450W, 270-480W, 340-550W	WCA, WCB, WCC	A4	-	GE230, GE280	-
	Heat resisting steel casting	SCH	GX40CrSi24, GX40CrNiSi22-10, GX40NiCrSi38-19	Grade HC, HD, HF	309C30, 310C45, 330C12	-	GX40NiCrNb45-35, GX50NiCrCoW35-25-15-5	-
	Steel casting for high temperature and high pressure service	SCPH	-	Grade WC1, WC6, WC9	A1, A2, B1, B2, B3, B4, B5, B7	G20Mo5, G17CrMo5-5, G17CrMo5-10	G17CrMo9-10, GX15CrMo5, GP240GH, GP280GH	-
	Steel casting for low temperature and high pressure service	SCPL	-	Grade LCB, LC1, LC2, LC3	AL1, BL2	-	FB-M, FC1-M, FC2-M, FC3-M	-
Casting iron	Grey iron casting	FC	100,150,200,250, 300,350	No.20,25,30,35, 40,45,50	EN-GJL-	EN-GJL-	EN-GJL-	-
	Spheroidal graphite iron casting	FCD	700-2, 600-3, 500-7, 450-10, 400-15, 400-18, 350-22	60-40-18, 65-45-12, 8-55-06, 100-70-03, 120-90-02	EN-GJS-	EN-GJS-	EN-GJS-	B4
	Austempered spheroidal graphite iron casting	FCAD	-	-	EN-GJS-	EN-GJS-	EN-GJS-	-
	Austenitic iron casting	FCA-FCDA-	L-, S-	Type 1, 2, Type D-2, D-3A Class 1, 2	F1, F2, S2W, S5S	GGL-, GGG-	L-, S-	-
Forging steel	Carbon steel forging for general use	SF	-	Class A, B, C, D, E, F	C22, C25, C30, C35, C40, C45, C50, C55, C60	P285, P355	P245, P280, P305	-
	Chromium molybdenum steel forgings for general use	SFCM	-	Class E, F, G, I Grade 3A, 4 Class G, J, K, L, M	-	-	-	-
	Nickel Chromium molybdenum steel forgings for general use	SFNCM	-	Class G, H, I, J Class 3A, 4, 5, 6 Class K, L, M	-	-	-	-

● Non-ferrous alloy

Type	Japan	International	Other countries		
	JIS		ISO	U.S.A. ASTM SAE	Great Britain BS BS/EN
Copper alloy casting	CAC101	-	-	-	-
	CAC102	-	-	-	-
	CAC103	-	-	-	-
Brass casting	CAC201	-	-	-	-
	CAC202	-	C85400	-	-
	CAC203	-	C85700	-	-
High strength brass casting	CAC301	-	C86500	-	-
	CAC302	-	C86400	-	-
	CAC303	-	C86200	-	-
	CAC304	-	C86300	-	-
Bronze casting	CAC401	-	C84400	-	-
	CAC402	-	C90300	-	-
	CAC403	-	C90500	-	-
	CAC406	-	C83600	-	-
Phosphor bronze casting	CAC407	-	C92200	-	-
	CAC502A	-	-	-	-
	CAC502B	-	C90700	-	-
	CAC503A	-	C90800	-	-
Aluminium bronze casting	CAC503B	-	-	-	-
	CAC701	-	C95200	-	-
	CAC702	-	C95400	-	-
	CAC703	-	C95410	-	-
Silicon bronze castings	CAC704	-	C95800	-	-
	CAC801	-	-	-	-
	CAC802	-	C87500	-	-
	CAC803	-	C87400	-	-
					CuZn16Si4-C(CC761S)

Note: The above chart is based on published data and not authorized by each manufacturer.

User's Guide - Technical Reference

Symbols of Metals

● Non-ferrous alloy

Type	Japan	International	Other countries				
	JIS	ISO	U.S.A.	Great Britain	Germany	France	
			ASTM SAE	BS BS/EN	DIN DIN/EN	NF NF/EN	
Aluminium alloy	Aluminium alloy ingots for casting	AC1B	Al-Cu4MgTi	204.0		EN AC-2100	
		AC2A	-	-		-	
		AC2B	-	319.0			-
		AC3A	-	-			EN AC-44100
		AC4A	-	-			-
		AC4B	Al-Si8Cu3	333.0			EN AC-46200
		AC4C	Al-Si7Mg(Fe)	356.0			EN AC-42000
		AC4CH	Al-Si7Mg0.3	A356.0			EN AC-42100
		AC4D	-	355.0			EN AC-45300
		AC5A	Al-Cu4Ni2Mg2	242.0			-
		AC7A	-	514.0			-
		AC8A	Al-Si12CuNiMg	-			EN AC-48000
	AC8B	-	-			-	
	AC8C	-	332.0			-	
	AC9A	-	-			-	
	AC9B	-	-			-	
	Aluminium alloy die casting	ADC1	-	A413.0			-
		ADC3	-	A360.0			-
		ADC5	-	518.0			-
		ADC6	-	-			-
ADC10		-	-			-	
ADC10Z		-	A380.0			-	
ADC12		-	-			-	
ADC12Z		-	383.0			-	
ADC14	-	B390.0			-		
Magnesium alloy	Magnesium alloy casting	MC5	-	AM100A		-	
		MC6	-	ZK51A		-	
		MC7	-	ZK61A		-	
		MC8	MgRE3Zn2Zr	EZ33A		EN MC65120	
		MC9	MgAg3RE2Zr	QE22A		EN MC65210	
		MC10	MgZn4RE1Zr	ZE41A		EN MC35110	
	Magnesium alloy die casting	MD1A	-	AZ91A		G-A9Z1Y4	
		MDC1B	-	AZ91B		-	
		MDC1D	MgAl9Zn1(A)	AZ91D		EN MC21120	
		MDC2B	MgAl6Mn	AM60B		EN MC21320	
Type	Japan	International	Other countries				
	JIS	ISO	U.S.A.	Great Britain	Germany	France	
			ASTM AA	BS BS/EN	DIN DIN/EN	NF NF/EN	
Aluminium alloy	Aluminium alloy extruded shapes	A5052S	-	5052		EN AW-5052	
		A5454S	-	5454		EN AW-5454	
		A5083S	AlMg4.5Mn0.7	5083		EN AW-5083	
		A5086S	-	5086		EN AW-5086	
		A6061S	AlMg1SiCu	6061		EN AW-6061	
		A6063S	AlMg0.7Si	6063		EN AW-6063	
		A7003S	-	-		EN AW-7003	
		A7N01S	-	-		-	
		A7075S	AlZn5.5MgCu	7075		EN AW-7075	

Note: The above chart is based on published data and not authorized by each manufacturer.

Grade

Insert

Toolholder

Ext. Toolholder

Int. Toolholder

Threading

Grooving

Miniature tool

Milling cutter

Endmill

Drilling tool

Tooling System

User's Guide

Index

User's Guide - Technical Reference

Approximate Conversion Table of Hardness

● Approximate conversion value for Brinell hardness. *1

(The source: JIS HB Ferrous Materials and Metallurgy I -2005)

HB		HV	Rockwell *3				HS	Approx. tensile strength (MPa) *2	HB		HV	Rockwell *3				HS	Approx. tensile strength (MPa) *2
Brinell, 10mm ball, Load 3000kg		Vickers	HRA	HRB	HRC	HRD	Shore		Brinell, 10mm ball, Load 3000kg		Vickers	HRA	HRB	HRC	HRD	Shore	
Standard ball	Tungsten carbide ball		A Scale, Load 60kg, Brale Diamond	B Scale, Load 100kg, Diameter 1/16 in. Steel ball	C Scale, Load 150kg, brale diamond	D Scale, Load 100kg, Brale Diamond			Standard ball	Tungsten carbide ball		A Scale, Load 60kg, Brale Diamond	B Scale, Load 100kg, Diameter 1/16 in. Steel ball	C Scale, Load 150kg, brale diamond	D Scale, Load 100kg, Brale Diamond		
-	-	940	85.6	-	68.0	76.9	97	-	429	429	455	73.4	-	45.7	59.7	61	1510
-	-	920	85.3	-	67.5	76.5	96	-	415	415	440	72.8	-	44.5	58.8	59	1460
-	-	900	85.0	-	67.0	76.1	95	-	401	401	425	72.0	-	43.1	57.8	58	1390
-	(767)	880	84.7	-	66.4	75.7	93	-	388	388	410	71.4	-	41.8	56.8	56	1330
-	(757)	860	84.4	-	65.9	75.3	92	-	375	375	396	70.6	-	40.4	55.7	54	1270
-	(745)	840	84.1	-	65.3	74.8	91	-	363	363	383	70.0	-	39.1	54.6	52	1220
-	(733)	820	83.8	-	64.7	74.3	90	-	352	352	372	69.3	(110.0)	37.9	53.8	51	1180
-	(722)	800	83.4	-	64.0	73.8	88	-	341	341	360	68.7	(109.0)	36.6	52.8	50	1130
-	(712)	-	-	-	-	-	-	-	331	331	350	68.1	(108.5)	35.5	51.9	48	1095
-	(710)	780	83.0	-	63.3	73.3	87	-	321	321	339	67.5	(108.0)	34.3	51.0	47	1060
-	(698)	760	82.6	-	62.5	72.6	86	-	-	-	-	-	-	-	-	-	-
-	(684)	740	82.2	-	61.8	72.1	-	-	311	311	328	66.9	(107.5)	33.1	50.0	46	1025
-	(682)	737	82.2	-	61.7	72.0	84	-	302	302	319	66.3	(107.0)	32.1	49.3	45	1005
-	(670)	720	81.8	-	61.0	71.5	83	-	293	293	309	65.7	(106.0)	30.9	48.3	43	970
-	(656)	700	81.3	-	60.1	70.8	-	-	285	285	301	65.3	(105.5)	29.9	47.6	-	950
-	(653)	697	81.2	-	60.0	70.7	81	-	277	277	292	64.6	(104.5)	28.8	46.7	41	925
-	(647)	690	81.1	-	59.7	70.5	-	-	269	269	284	64.1	(104.0)	27.6	45.9	40	895
-	(638)	680	80.8	-	59.2	70.1	80	-	262	262	276	63.6	(103.0)	26.6	45.0	39	875
-	630	670	80.6	-	58.8	69.8	-	-	255	255	269	63.0	(102.0)	25.4	44.2	38	850
-	627	667	80.5	-	58.7	69.7	79	-	248	248	261	62.5	(101.0)	24.2	43.2	37	825
-	-	677	80.7	-	59.1	70.0	-	-	241	241	253	61.8	100.0	22.8	42.0	36	800
-	601	640	79.8	-	57.3	68.7	77	-	235	235	247	61.4	99.0	21.7	41.4	35	785
-	-	640	79.8	-	57.3	68.7	-	-	229	229	241	60.8	98.2	20.5	40.5	34	765
-	578	615	79.1	-	56.0	67.7	75	-	223	223	234	-	97.3	(18.8)	-	-	-
-	-	607	78.8	-	55.6	67.4	-	-	217	217	228	-	96.4	(17.5)	-	33	725
-	555	591	78.4	-	54.7	66.7	73	2055	212	212	222	-	95.5	(16.0)	-	-	705
-	-	579	78.0	-	54.0	66.1	-	2015	207	207	218	-	94.6	(15.2)	-	32	690
-	534	569	77.8	-	53.5	65.8	71	1985	201	201	212	-	93.8	(13.8)	-	31	675
-	-	553	77.1	-	52.5	65.0	-	1915	197	197	207	-	92.8	(12.7)	-	30	655
-	514	547	76.9	-	52.1	64.7	70	1890	192	192	202	-	91.9	(11.5)	-	29	640
(495)	-	539	76.7	-	51.6	64.3	-	1855	187	187	196	-	90.7	(10.0)	-	-	620
-	-	530	76.4	-	51.1	63.9	-	1825	183	183	192	-	90.0	(9.0)	-	28	615
-	495	528	76.3	-	51.0	63.8	68	1820	179	179	188	-	89.0	(8.0)	-	27	600
(477)	-	516	75.9	-	50.3	63.2	-	1780	174	174	182	-	87.8	(6.4)	-	-	585
-	-	508	75.6	-	49.6	62.7	-	1740	170	170	178	-	86.8	(5.4)	-	26	570
-	477	508	75.6	-	49.6	62.7	66	1740	167	167	175	-	86.0	(4.4)	-	-	560
(461)	-	495	75.1	-	48.8	61.9	-	1680	163	163	171	-	85.0	(3.3)	-	25	545
-	-	491	74.9	-	48.5	61.7	-	1670	156	156	163	-	82.9	(0.9)	-	-	525
-	461	491	74.9	-	48.5	61.7	65	1670	149	149	156	-	80.8	-	-	23	505
444	-	474	74.3	-	47.2	61.0	-	1595	143	143	150	-	78.7	-	-	22	490
-	-	472	74.2	-	47.1	60.8	-	1585	137	137	143	-	76.4	-	-	21	460
-	444	472	74.2	-	47.1	60.8	63	1585	131	131	137	-	74.0	-	-	-	450
-	-	472	74.2	-	47.1	60.8	-	1585	126	126	132	-	72.0	-	-	20	435
-	-	472	74.2	-	47.1	60.8	-	1585	121	121	127	-	69.8	-	-	19	415
-	-	472	74.2	-	47.1	60.8	-	1585	116	116	122	-	67.6	-	-	18	400
-	-	472	74.2	-	47.1	60.8	-	1585	111	111	117	-	65.7	-	-	15	385

Note :

*1: This table is based on AMS Metals Handbook, the 8th Edition, Volume 1, and includes some information added to "Approx. tensile strength (MPa)," such as the values calculated in metric; and Brinell hardness that exceeds recommended values.

*2: 1 MPa = 1 N/mm²

*3: Figures in () are not commonly used. It's just reference.

Surface Roughness

(According to JIS B 0601, 2001 and its explanation.)

Type	Symbol	How to determine	Example (Fig.)
Arithmetic mean roughness	Ra	<p>Ra means the value obtained by the following formula and expressed in micrometer (μm) when sampling only the reference length from the roughness curve in the direction of mean line, taking X-axis in the direction of mean line and Y-axis in the direction of longitudinal magnification of this sampled part and the roughness curve is expressed by $y=f(x)$:</p> $Ra = \frac{1}{\ell} \int_0^{\ell} f(x) dx$ <p>where, ℓ : reference length</p>	
Maximum height	Rz	<p>Rz shall be that only the reference length is sampled from the roughness curve in the direction of mean line, the distance between the top of profile peak line and the bottom of profile valley line on this sampled portion is measured in the longitudinal magnification direction of roughness curve and the obtained value is expressed in micrometer (μm).</p> $Rz = Rp + Rv$	
Ten point mean roughness	Rz_{JIS}	<p>Rz_{JIS} shall be that only the reference length is sampled from the roughness curve in the direction of its mean line, the sum of the average value of absolute values of the heights of five highest profile peaks (Zp) and the depths of five deepest profile valleys (Zv) measured in the vertical magnification direction from the mean line of this sampled portion and this sum is expressed in micrometer (μm)</p> $Rz_{JIS} = \frac{ Zp1 + Zp2 + Zp3 + Zp4 + Zp5 + Zv1 + Zv2 + Zv3 + Zv4 + Zv5 }{5}$	<p>where, $Zp1, Zp2, Zp3, Zp4, Zp5$: altitudes of the heights of five highest profile peaks of the sampled portion corresponding to the reference length ℓ</p> <p>where, $Zv1, Zv2, Zv3, Zv4, Zv5$: altitudes of the depths of five deepest profile valleys of the sampled portion corresponding to the reference length ℓ</p>